

ASS. REC. BY:

REF:

TP /

CS1/TP20012022/Kvf3

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

14

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

S/10 388R

Yr Regn:

/

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mer E220 2.0i c.c

Colour

White

A/C:

Insured / Std / NI / NA

Sp. Reading

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WDB2110082B

179564

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

1/2/14

D.O.I.

1/2020

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

/

Paper Survey  
Smart accordingly

4/11/20 Submit LS \$19,950 (Red 72,416.09, 78%)

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

4/11/20-Typist

Report Format: PS

Lump Sum H.B.t: (\$ 19,950)

Days Of Repair: 14

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S - R.S. SI

Fees

Others

TOTAL

**SHD 388R - FCIL**

Not Notion  
C/Prp &

**ROEL**

Third Party Insurer :

FCIL

PART		LIST
1	1	Bootlid RR \$ 1,840.00
2	1	Bootlid 'E220' Badge \$ 68.00
3	1	Bootlid 'CDI' Badge \$ 58.00
4	1	Bootlid Centre Logo Badge \$ 28.00
5	1	Bootlid Protector Garnish With Chrome \$ 488.00
6	1	Bootlid Lock - Top \$ 200.00
7	1	Bootlid Lock - Bottom \$ 144.00
8	1	Bootlid Lock Actuator \$ 280.00
9	1	Bootlid Weatherstrip \$ 160.00
10	1	Bootlid Third Brake Lamp \$ 385.00
11	1	Rear End Panel Outer \$ 660.00
12	1	Rear End Panel Inner \$ 216.00
13	1	Rear End Panel Inner Trim \$ 120.00
14	1	Rear End Panel Inner Trim Flap \$ 24.00
15	1	Rear Luggage Floor Panel Tray \$ 381.00
16	1	Rear Luggage Floor Compartment Tray \$ 58.00
17	1	Rear Luggage Floor Panel Trim Board \$ 210.00
18	1	Rear Lamp RH \$ 520.00
19	1	Rear Lamp Panel Outer RH \$ 55.30 X
20	1	Rear Lamp Panel Inner RH \$ 55.30 X
21	1	Rear Lamp LH \$ 520.00 X
22	1	Rear Bumper \$ 1,380.00
23	1	Rear Bumper Reinforcement \$ 540.00 X
24	1	Rear Bumper Centre Pad \$ 205.22 X
25	1	Rear Bumper Side Pad \$ 124.22 X
26	1	Rear Bumper Tow Hook Cover \$ 28.00 X
27	1	Rear Bumper Bracket \$ 15.00 X
28	1	Rear Bumper Side Retainer Bracket \$ 88.00
29	1	Rear Bumper Inner Frame \$ 198.00 X
30	1	Rear Bumper Bottom Bracket \$ 40.00 X
31	1	Rear Bumper Top Bracket \$ 86.00 X
32	1	Rear Bumper Side Holder Bracket \$ 90.00 X
33	1	Rear Fender LH \$ 1,810.00 X



**TRANS-CAB AUTO SERVICES PTE LTD**

NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

**SHD 388R - FCIL****ROEL**

34	1	Rear Fender RH	\$	<i>R<sub>1</sub></i>	1,810.00	✓
35	1	Rear Fender Top Garnish RH	\$	<i>S<sub>2</sub></i>	30.00	X
36	1	Rear Fender Inner Trim RH	\$	<i>Return</i>	230.00	✓
37	1	Rear Seat Belt RH	\$	<i>T<sub>2</sub></i>	335.00	✓
38	1	Rear Seat Belt LH	\$	<i>T<sub>2</sub></i>	335.00	✓
39	1	Rear lower arm RH	\$	<i>S<sub>2</sub></i>	488.00	X
40	1	Rear shock absorber RH	\$	<i>S<sub>2</sub></i>	490.00	X
41	1	Rear knuckle arm RH	\$	<i>S<sub>2</sub></i>	1,612.00	X
42	1	Front License Plate Garnish	\$	<i>S<sub>2</sub></i>	192.00	X
43	1	Front Bumper	\$	<i>Buc / cm</i>	1,265.00	✓
44	1	Front Bumper Reinforcement	\$	<i>R<sub>2</sub></i>	656.00	✓
45	1	Front Bumper Centre Inner Frame LH	\$	<i>CM</i>	65.00	✓
46	1	Front Bumper Side Retainer LH	\$	<i>S<sub>2</sub></i>	88.00	X
47	1	Front Bumper Side Retainer RH	\$	<i>CM</i>	88.00	✓
48	1	Front Bumper Centre Inner Frame RH	\$	<i>S<sub>2</sub></i>	65.00	X
49	1	Front Bumper Side Inner Frame LH	\$	<i>S<sub>2</sub></i>	46.00	X
50	1	Front Bumper Side Inner Frame RH	\$	<i>CM</i>	46.00	✓
51	1	Front Bumper Inner Sponge Centre	\$	<i>S<sub>2</sub></i>	58.00	X
52	1	Front Bumper Inner Sponge Side LH	\$	<i>S<sub>2</sub></i>	55.00	X
53	1	Front Bumper Inner Sponge Side RH	\$	<i>M<sub>1</sub></i>	55.00	✓
54	1	Front Bumper Absorber	\$	<i>S<sub>2</sub></i>	248.00	X
55	1	Front Bumper Fog Lamp LH	\$	<i>S<sub>2</sub></i>	272.00	X
56	1	Front Bumper Fog Lamp Garnish LH	\$	<i>S<sub>2</sub></i>	68.00	X
57	1	Front Bumper Fog Lamp Rim LH	\$	<i>S<sub>2</sub></i>	55.00	X
58	1	Front Bumper Fog Lamp RH	\$	<i>M<sub>1</sub></i>	272.00	✓
59	1	Front Bumper Fog Lamp Garnish RH	\$	<i>CM</i>	68.00	✓
60	1	Front Bumper Fog Lamp Rim RH	\$	<i>M<sub>1</sub></i>	55.00	✓
61	1	Front Bumper Centre Air Grille	\$	<i>S<sub>2</sub></i>	36.00	X
62	1	Front Bumper Bracket	\$	<i>R</i>	60.00	X
63	1	Front Bumper Side Bracket	\$	<i>R</i>	40.00	X
64	1	Front Bumper Tow Hook Cover	\$	<i>M<sub>1</sub></i>	70.00	✓
65	1	Front Headlamp RH	\$	<i>CM</i>	944.00	✓
66	1	Front Headlamp LH	\$	<i>S<sub>2</sub></i>	944.00	X
67	1	Front Headlamp Panel LH	\$	<i>R</i>	120.00	X
68	1	Front Headlamp Panel RH	\$	<i>R<sub>2</sub></i>	120.00	✓
69	1	Front Headlamp Bracket RH	\$	<i>R<sub>2</sub></i>	96.40	✓
70	1	Front Headlamp Bracket LH	\$	<i>R</i>	96.40	X
71	1	Front Support Panel Assy	\$	<i>R</i>	456.00	X
72	1	Bonnet	\$	<i>B<sub>2</sub></i>	2,912.00	✓
73	1	Bonnet Star Logo	\$	<i>S<sub>2</sub></i>	165.00	X
74	1	Bonnet Lock Top	\$	<i>R</i>	68.00	X
75	1	Bonnet Centre Lock Top	\$	<i>R</i>	96.00	X

76	1	Bonnet Centre Lock Latch Bottom	\$	R	40.00	
77	1	Bonnet Opening Lever Handle	\$	Sm	12.00	
78	1	Bonnet Lock Brace Panel	\$	R	72.00	
79	1	Bonnet Hinge RH	\$	R	101.00	
80	1	Bonnet Hinge LH	\$	R	101.00	
81	1	Bonnet Insulator	\$	Sm	138.00	
82	1	Front Top Panel	\$	R	185.00	
83	1	Radiator Assy	\$	Sm	2,520.00	X
84	1	Radiator Cowling	\$	Sm	96.00	
85	1	Radiator Fan Motor	\$	Sm	1,312.00	
86	1	Radiator Fan Blade	\$	Sm	865.00	
87	1	Radiator Grille	\$	Sm	632.00	
88	1	Aircon Condenser	\$	Sm	960.00	
89	1	Air Intercooler	\$	Sm	1,275.00	
90	1	Front Fender LH	\$	R	865.31	
91	1	Front Fender RH	\$	R	865.31	✓
92	1	Front Fender LEDGE RH	\$	Sm	54.00	✓
93	1	Front Fender Protector RH	\$	M/T	30.77	✓
94	1	Front Fender Inner Cowling RH	\$	CM	76.00	✓
95	1	Front Fender Wheel house panel RH	\$	R	2,680.00	X
96	1	Front shock absorber RH	\$	R	692.00	✓
97	1	Front upper arm RH	\$	D/T	544.00	✓
98	1	Front lower arm RH	\$	D/T	748.00	✓
99	1	Front castor arm RH	\$	Sm	615.00	X
100	1	Front knuckle arm RH	\$	R	1,152.00	✓
101	1	Front door RH	\$	R	1,840.00	X
102	1	Front Driver Seat RH	\$	R	8,343.75	X
103	1	Rocker panel skirting (garnish) RH	\$	CM	585.00	✓
104	1	Rear door RH	\$	R	1,840.00	X
105	1	Roof side panel air bag RH	\$	B/T	2,450.00	✓
106	1	Roof side panel air bag sensor RH	\$	Sm	1,102.00	✓
107	1	Roof lining	\$	T	2,425.00	✓
108	1	Roof panel outer	\$	R	4,852.33	X

<b>TOTAL</b>	<b>\$</b>	<b>66,415.31</b>
<b>10%</b>	<b>\$</b>	<b>6,641.53</b>
	<b>\$</b>	<b>59,773.78</b>

**Specical Nett**

1 SET	Rear Bumper Parking Sensor	\$	Sm	380.00	X
1 SET	Bootlid Inner Trim Clip	\$	Sm	40.00	X



# TRANS-CAB AUTO SERVICES PTE LTD

NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHD 388R - FCIL

ROEL

1 SET	Rear End Panel Inner Trim Clip	\$	nn	40.00	X
1 SET	Rear Bumper Fastener Clip	\$	nn	45.13	✓
1 SET	Rear Fender Top Garnish Clip	\$	nn	40.00	X
1 SET	Rear Fender Inner Trim Clip	\$	nn	20.00	✓
1	Spare Tire Fastener Bowl	\$	nn	180.00	X
1 SET	License plate	\$	nn	100.00	X
1	Rear Windscreen Glass Sealant	\$	nn	100.00	40.00
1	Rear Windscreen Glass Inner Seal	\$	nn	80.00	30.00
1 SET	Front Bumper Inner Frame Clip	\$	nn	60.00	—
1 SET	Front Bumper Inner Frame Metal Clip	\$	nn	40.00	—
1	Spare tyre	\$	nn	540.00	}
1	Spare wheel rim	\$	nn	450.00	
1	Tyre Mechanical Jack	\$	nn	269.10	
1	Tyre Mechanical Jack Holder Bracket	\$	nn	79.10	
1	Rear Bootlid 'DYNASTY' Sticker	\$	nn	15.00	
1	Front tyre RH	\$	nn	350.00	}
1	Front alloy rim RH	\$	nn	850.00	
1	Rear tyre RH	\$	nn	350.00	60.00
1	Rear alloy rim RH	\$	nn	850.00	X
1 SET	Roof lining clip	\$	nn	45.00	—
1 SET	Rocker panel skirting (garnish) clip	\$	nn	23.45	—
1 SET	Front Bumper clip	\$	nn	41.22	✓
1 SET	Front Fender Inner Cowling clip	\$	nn	15.88	✓
1 SET	Radiator Grille clip	\$	nn	18.43	X

TOTAL \$ 5,022.31

TOTAL PARTS \$ 64,796.09

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	11,200.00	1500
To Rust-Proofing Of The Affected Areas.	\$	170.00	90
To Check Electrical Lighting Concerned.	\$	120.00	40
Putty And Spray Painting Of The Affected Portion.	\$	10,800.00	1760
To Remove And Refit Interior Fittings, Trimings, Garnish, Fittings And Other, to	\$	270.00	120

To Transfer Of Bootlid Fittings, Attachments And Perform Water Seepage Test.	\$	170.00	X
To Transfer Of Tire, Rim And On Wheel Balancing.	\$	170.00	X
To Check Steering Geometry And Computer Wheel Alignment.	\$	120.00	601
To Transfer Of Fender Fittings, Attachment And Perform Water Seepage Test.	\$	170.00	X
Towing Fee	\$	200.00	1201
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	170.00	1201
To Dismantle And Refit Rear Undercarriage Parts, Final Checking And Testing.	\$	nn 380.00	X
To Repair And Realign Rear Exhaust Pipe.	\$	nn 170.00	X
To Reinstall Rear Bumper Parking Sensor.	\$	170.00	601
To Supply And Re-Do Rear Luggage Floor Panel Insulation Padding.	\$	nn 380.00	X
To Check ABS Brake Efficiency, Final Checking And Testing.	\$	nn 380.00	X
To vacuum, replace, refix and recharge air condenser	\$	380.00	1001
To replace, refix and top up coolant for	\$	nn 170.00	X
To vacuum, replace, refix and recharge Air Intercooler	\$	nn 170.00	X
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	nn 380.00	X
To Reseal Sealant On Gap	\$	120.00	601

**TRANS-CAB AUTO SERVICES PTE LTD**  
NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346  
TEL NO.6287 6666 FAX NO.6366 8862  
CO/GST REG NO.201019626G  
**SHD 388R - FCIL**

**ROEL**

To dismantle and refit front end suspension, undercarriage parts, final checking and	\$	380.00	X
To remove and refit air bag system and reset.	\$	480.00	250/
To Remove And Refit Cushion System And Reset.	\$	450.00	150/

<b>TOTAL</b>	<b>\$</b>	<b>27,570.00</b>
--------------	-----------	------------------

<b>Over all total</b>	<b>\$</b>	<b>92,366.09</b>
-----------------------	-----------	------------------

<b>Total repair days</b>	<b>40 DAYS</b>
	<i>14 days</i>



### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### ACCIDENT STATEMENT

Date Of Report	03/02/2014 14:07
Date Of Accident	01/02/2014 22:20
Exact Location Of Accident	Marina Boulevard
Country/State of Loss	Singapore

#### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD388R
-----------------------------	---------

#### Insured/Policyholder

Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K

#### Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	E220 CDI

Exact Purpose for which vehicle was being used at time of accident	Hire and Reward
--	-----------------

Are you claiming under your own insurance policy for repair to your vehicle?	No
--	----

If No, Please state action to be taken	Reporting Only
--	----------------

Vehicle Category	Taxi
------------------	------

#### Insurance Company

Name of Insurance Company	First Capital Insurance Ltd
Type Of Coverage	Third Party
Fleet Policy	Yes
Policy Number	D-12047359MFSH/1955
Cover Note Number	

#### Driver

Name of Driver	CHIN WOON CHOON
NRIC No	S6903027J
Date Of Birth	31/01/1969
Occupation	Outdoor
Date Of Driving Pass	26/01/1999
Driving Experience	15 Years And 0 Months
Gender	Male
Mobile Number	(Local) +65-86528983
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL
Address	BLK 210A BUKIT BATOK ST 21 #16-268
Postcode	651210



Was driver an employee of the Insured's Company No  
If No, Relationship of the Driver with the Insured Other - Relief  
Vehicle Registration Number of Driver's Own Vehicle -  
Vehicle -  
Insurance Company of Driver's Own Vehicle -  
-

#### General Information of the Accident

Type Of Accident Side Swipe- Opposite Direction  
Weather Conditions Clear  
Road Surface Dry

#### Other Information

Was any foreign vehicle involved in this accident? No  
Was any body injured in the Accident? Yes  
Was any other material or property damaged? Yes  
Was there any video captured by Car Camera? No

#### Details of Police Action

Was the accident reported to the police? Yes  
If Yes, Please state which Police Station  
Police Station Name Traffic Police Division Hq  
Police Station Address ROAD: 10 Ubi Avenue 3 , POSTCODE: 408865 , COUNTRY: Singapore  
Police Station Contact TEL NO: 65470000 - FAX NO:  
Was notice of intended Prosecution given? No  
If Yes, against whom?

#### Circumstances of Accident

Please refer to Police Report - T/20140203/4042  
Are accident photos available for attachment? Yes

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number UNKNOWN  
Vehicle Make/Model/Colour TAXI  
Details Of Properties  
Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

#### Details of Witness

Name  
Phone Number  
Email Address

#### DETAILS OF INJURED PERSON 1

Name CHIN WOON CHOON  
Approximate Age  
Injuries Sustain  
Injured person in which vehicle? SHD388R  
Were seat belts worn? Yes  
Was injured conveyed to hospital by ambulance? Yes

Police Station Of Origin:  
Traffic Police Division HQ  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000



T/20140203/4042

1 of 3

Report No. T/20140203/4042

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 03/02/2014 12:53		Vide Report No.:		Station Diary No.:	
<b>Informant's Particulars</b>					
Name of Informant: CHIN WOON CHOON			Address: APT BLK 210A BUKIT BATOK STREET 21 #16-268 SINGAPORE 651210		
ID Type / ID No.: NRIC NO / S6903027J			Contact No.: Home/Office: Mobile: 86528983		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 45	Date of Birth: 31/01/1969	Type of Informant: Driver		
Race: Chinese			Language: Chinese		Institution / School Name:
Occupation: Driver			Driving Licence Information: Class: 3		Date of Expiry:

<b>General Information of the Accident</b>				
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 01/02/2014 22:20	Type of Location: X-Junction
Location: Along Road 1 MARINA BLVD				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Side Swipe - Opposite Direction				Anyone conveyed by ambulance: Yes

<b>Details of Vehicle Involved</b>									
Vehicle No.	Type	Make	Color	Condition	No of Passenger	Insurance Company	Insurance No	Effective Date	Expiry Date
SHD388R	Car			Seriously Damaged	0				

<b>Details of Person Involved</b>	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



Police Station Of Origin:  
Traffic Police Division HQ  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000



T/20140203/4042

2 of 3

Report No. T/20140203/4042

## CONTINUATION OF REPORT

<b>Driver</b>			
Name	CHIN WOON CHOON	ID No.	S6903027J
Related Vehicle	NIL	Contact No.	86528983
Hospital/Clinic	SINGAPORE GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave (MC)	NIL	Degree of Injury	NIL

**Brief Details.**

ON THE DATE AND TIME MENTIONED ABOVE, I WAS DRIVING COMPANY TAXI (SHD388R) ALONG MARINA BLVD. I WAS ON LANE 2 OF OUT THE 4 LANE. I PASSING THE GREEN LIGHT THEN SUDDENLY A CAR FROM MY RIGHT COLLIED ONTO MY FRONT RIGHT. AFTER THAT I DISCOVER MY LEFT EYE WAS BLEEDING AND I CALLED THE POLICE AFTER THAT. I WAS CONVEYED BY THE AMBULANCE TO SGH.