

JEC AUTO SERVICE PTE LTD

1 KAKI BUKIT AVENUE 6, #02-11 AUTOBAY@KAKI BUKIT

SINGAPORE 417883

TEL: 92327457

TO	: CHINA TAIPING	DATE	: 3/11/2020
ATTENTION	: MOTOR INSURANCE CLAIM	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
VEHICLE DETAILS			
VEHICLE NO	: SJK5319Y	Veron	
VEHICLE MODEL	: TOYOTA WISH		
CHASSIS NO	: JTDER12WX03000606		
ACCIDENT DETAILS	DATE	:	
	TIME	:	
THIRD PARTY REQUESTOR / CONTACT	:	XIAN / 92327457	

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER <i>Disl'd</i>	1	\$ 545.00	\$ 545.00
2	REAR BUMPER SIDE HOLDER <i>new</i>	2	\$ 58.00	\$ 116.00
3	REAR BUMPER REFLECTOR <i>RH and L</i>	2	\$ 78.00	\$ 156.00
4	REAR BUMPER IMPACT BRACKET <i>out'd</i>	2	\$ 68.40	\$ 136.80
5	REAR END PANEL <i>Disl'd</i>	1	\$ 597.40	\$ 597.40
6	REAR END PANEL TOP GARNISH <i>Disl'd</i>	1	\$ 285.40	\$ 285.40
7	TAILLAMP <i>cut'd</i>	2	\$ 408.50	\$ 817.00
8	TAILLAMP LOWER BRACKET <i>new</i>	2	\$ 60.80	\$ 121.60
9	TAILGATE <i>Disl'd</i>	1	\$ 1,280.00	\$ 1,280.00
10	TAILGATE LOCK <i>Disl'd</i>	1	\$ 363.40	\$ 363.40
11	TAILGATE WEATHERSTRIPE <i>cut</i>	1	\$ 329.10	\$ 329.10
12	TAILGATE OUTER CHROME MOULDING <i>cut'd</i>	1	\$ 271.60	\$ 271.60
13	TAILGATE PULL POCKET <i>new</i>	1	\$ 42.90	\$ 42.90
14	TAILGATE INNER TRIM BOARD <i>Disl'd</i>	1	\$ 485.50	\$ 485.50
15	TAILGATE DAMPER <i>new</i>	2	\$ 261.80	\$ 523.60
16	TAILGATE WIPER MOTOR <i>Disl'd</i>	1	\$ 509.30	\$ 509.30
17	TAILGATE GLASS <i>new</i>	1	\$ 988.70	\$ 988.70
18	TAILGATE GLASS MOULDING <i>cut</i>	1	\$ 246.00	\$ 246.00
19	TOYOTA LOGO <i>new</i>	1	\$ 68.00	\$ 130.20
20	AERO TOURER EMBLEM <i>new</i>	1	\$ 65.50	\$ 65.50
21	BORNEO MOTOR EMBLEM <i>new</i>	1	\$ 58.60	\$ 58.60
22	REAR FENDER INNER TRIM BOARD <i>cut'd</i>	2	\$ 652.10	\$ 1,304.20
23	SPARE TYRE LOCK REGULATOR <i>new</i>	1	\$ 399.70	\$ 399.70
24	REAR EXHAUST PIPE <i>new</i>	1	\$ 788.50	\$ 788.50
25	REAR EXHAUST PIPE MOUNTING <i>new</i>	1	\$ 38.00	\$ 38.00

26	REAR EXHAUST PIPE HEAT SHIELD <i>new</i>	1	\$ 105.10	\$ 105.10	X
----	--	---	-----------	-----------	---

7555.80

5666.85

TOTAL PRICE: \$ 10,705.10
LESS 25% \$ 2,676.27
SUB TOTAL PRICE: \$ 8,028.83

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL	
1	REAR NUMBER PLATE <i>cut</i>	1	\$ 30.00	\$ 30.00	✓
2	REAR NUMBER PLATE HOLDER <i>old</i>	1	\$ 30.00	\$ 30.00	✓
3	REAR BUMPER CLIPS <i>new</i>	1 SET	\$ 50.00	\$ 50.00	30
4	REVERSE SENSOR <i>Donc</i>	1 SET	\$ 280.00	\$ 280.00	2w
5	REAR END PANEL TOP GARNISH CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00	10
6	REAR END PANEL SEALANT <i>new</i>	1 SET	\$ 60.00	\$ 60.00	✓
7	TAILLAMP SPONGE GASKET <i>new</i>	2	\$ 20.00	\$ 40.00	✓
8	TAILGATE OUTER CHROME MOULDING CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00	10
9	TAILGATE INNER TRIM BOARD CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00	✓
10	TAILGATE GLASS SEALANT <i>new</i>	1 SET	\$ 60.00	\$ 60.00	✓
11	REAR CAMERA <i>Donc</i>	1	\$ 480.00	\$ 480.00	380
12	REAR FENDER INNER TRIM BOARD CLIPS <i>new</i>	2 SET	\$ 30.00	\$ 60.00	✓

940

TOTAL : \$ 1,180.00

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,200.00	8w	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,200.00	8w	
3	WIRING CHECK	\$ 100.00	30	
4	TO REMOVE REVERSE SENSOR	\$ 100.00	50	
5	TO APPLY TUFF COAT	\$ 150.00	60	
6	TO REMOVE UPHOLSTERY	\$ 150.00	60	
7	TO TRANSFER TAILGATE FITTINGS	\$ 150.00	80	
9	TO REMOVE TAILGATE GLASS	\$ 180.00	120	
10	TO REMOVE REAR CAMERA	\$ 100.00	50	
11	TOWING FEES	\$ 60.00	X	

TOTAL: \$ 3,390.00

ESTIMATE REPORT

TOTAL PARTS COST: \$ 9,208.83

TOTAL LABOUR COST: \$ 3,390.00

TOTAL REPAIR COST: \$ 12,598.83

total: 8656.85
1/s' 6.9K.

06 Days.

APPROVED DETAILS

SURVEYOR:

CONTACT:

PART BY PART / LUMP SUM:

NO. OF DAYS:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: