

Not Withheld
1/1 Sep 8 1900h

AAD2011-011

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9840S

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

03 NOV 2020

SHD9840S

VF1ABL15AUC277502

RENAULT

LATITUDE

30/10/2020

EQ

25/04/2014

PART	
1	BUMPER COVER FRT
1	BUMPER SPOILER FRT
1	BUMPER RETAINER FRT RH
1	BUMPER BRACKET FRT RH (Headlamp Lower)
1	BUMPER FOG LAMP GRILLE RH
1	BUMPER BEAM FRT
1	BUMPER BRACKET KIT FRT RH
1	HEADLAMP RH
1	FENDER PANEL FRT RH
1	FENDER BRACKET FRT RH
1	WHEELARCH FRT RH
1	WIPER RESERVOIR

LIST	
\$	Bumper 747.20 ✓
\$	Sp 344.70 X
\$	Br 101.40 ✓
\$	Sp 116.47 X
\$	Sp 207.21 X
\$	R 663.70 X
\$	R 101.40 X
\$	mgc 743.60 ✓
\$	R 437.10 X
\$	R 106.40 X
\$	Sp 191.40 X
\$	Sp 179.60 X

TOTAL	\$	3,940.18
10%	\$	394.02
	\$	3,546.16

Special Nett	
1	BUMPER CLIP FRT
1	BUMPER RETAINER CLIP FRT
1	WHEELARCH CLIP FRT
1	FENDER SCREW

	\$	nc	90.00	661m
	\$	nn	75.00	X
	\$	nn	75.00	X
	\$	nn	60.00	X
TOTAL	\$		240.00	

TOTAL PARTS	\$	3,786.16
-------------	----	----------

LABOUR

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9840S

AAD2011-011

To rust-proofing and apply undercoat of the affected areas.	\$	<i>nn</i> 230.00	X
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00	X
Putty and spray painting of the affected portion.	\$	1,400.00	<i>440/</i>
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	2,000.00	<i>400/</i>
To transfer of tire, rim and on wheel balancing.	\$	170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	<i>20/</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00	X
TOTAL	\$	4,360.00	
Over All Total	\$	8,146.16	

(PART-BY-PART) Repair Days

*20 Days**2 days*

For Official Use

Prepared By : _____
(Accident Dept)Verify By : _____
(Accident Workshop)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: