

SERVICE ESTIMATE

94781 - C00001 SL: SERVICE SALES - PC

Mr Tham Kwok Leong

32 Kismis Green

Address Ok

Singapore 596264

Closed by : Michelle Ong Siew Be

Svc Consultant :

Remarks : Mr Tham Kwok Leong

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 1

Inv.date. : 02/11/2020

WIP No. . : 47472

Veh.In/Out:

*Tel.No. . : Mobile: 97353256

Reg.No. . : SLU8466J

Reg.date . : 15/12/2017

Mileage ... : 0

Chassis No: YV1UZ10ACJ1031689

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR BUMPER, REAR SPOILER, TAILGATE, REAR TOW EYE COVER, BRACKETS, EMBLEMS, BONNET, BONNET LOCK, FRT BUMPER, HEADLAMPS, GRILLE, LOGO, BRACKETS, SUPPORT PANEL, ETC.	0	5600.00	0		5,600.00 S	3200 /
800	TO PUTTY AND SPRAY PAINT ON REAR BUMPER, TAILGATE, TOW EYE COVER, BONNET, FRT BUMPER, ETC.	0	3500.00	0		3,500.00 S	2800 /
802	TO REPLACE REAR WINDSCREEN <i>plast?</i>	0	800.00	0		800.00 S	/
89994	TO INSTALL REAR WINDSCREEN	0	280.00	0		280.00 S	/
SOLAR FILM							
802	TO TRANSFER TAILGATE MECHANISM	0	800.00	0		800.00 S	250 /
280	TO FOCUS HEADLAMPS	0	175.00	0		175.00 S	170 /
280	TO CHECK WIRING INCLUDE	0	525.00	0		525.00 S	/
RESETTING OF ALL ELECTRICAL							

SERVICE ESTIMATE

94781 - C00001
Mr Tham Kwok Leong
32 Kismis Green

SL: SERVICE SALES - PC

Address Ok
Singapore 596264

Closed by : Michelle Ong Siew Be
Svc Consultant :
Remarks : Mr Tham Kwok Leong

GST Reg.No:M28920628X
Inv.No. . : B&P 0 Page 2
Inv.date. : 02/11/2020
WIP No. . : 47472
Veh.In/Out:
*Tel.No. . : Mobile: 97353256
Reg.No. . : SLU8466J
Reg.date. : 15/12/2017
Mileage . : 0
Chassis No: YV1UZ10ACJ1031689

Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	------	-----	-------	-------	-----	--------	---

MODULES

R06	TO INSTALL FRONT & REAR NUMBER	0	120.00	0	120.00	S	X 111
PLATE WITH HOLDER							
BONNET FRT XC60 18-	bt	1.0	EA	3025.60		3,025.60	S 2723.04
BONNET HINGE LH XC60	? XSV	1.0	EA	233.70		233.70	S
BONNET HINGE RH XC60	? XSV	1.0	EA	233.70		233.70	S
BONNET LOCK RH S90 1	? XSV	1.0	EA	185.50		185.50	S
BONNET LOCK LH XC60	? XSV	1.0	EA	148.40		148.40	S
BONNET LOCK CONTRO	? CR	1.0	EA	140.10		140.10	S 126.09
BONNET CABLE OUTER X	? CR	1.0	EA	78.00		78.00	S 70.20
LOCK BRACE LH XC90 1	? bt	1.0	EA	78.40		78.40	S 70.56
LOCK BRACE RH XC90 1	? bt	1.0	EA	78.40		78.40	S 70.56
SOUND ABSORBER BONNE	X SV	1.0	EA	493.80		493.80	S
BUMPER COVER FRT XC6	de	1.0	EA	1743.20		1,743.20	S 1568.88
RADIATOR GRILLE XC60	CR	1.0	EA	920.50		920.50	S 828.45
BUMPER BRACKET SIDE	? CR	1.0	EA	72.90		72.90	S 65.61
BUMPER BRACKET SIDE	? CR	1.0	EA	72.90		72.90	S 65.61

Wearnes Automotive Pte. Ltd.

45 Leng Kee Road, Singapore 159103 T +65 6430 4700 www.wearnesauto.com

Co reg no. 199501400R / GST reg no. M28920628X

SERVICE ESTIMATE

94781 - C00001 SL: SERVICE SALES - PC

Mr Tham Kwok Leong
32 Kismis Green

Address Ok
Singapore 596264

Closed by : Michelle Ong Siew Be
Svc Consultant :
Remarks : Mr Tham Kwok Leong

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 3

Inv.date. : 02/11/2020

WIP No. . : 47472

Veh.In/Out:

*Tel.No. . : Mobile: 97353256

Reg.No. . : SLU8466J

Reg.date. : 15/12/2017

Mileage . : 0

Chassis No: YV1UZ10ACJ1031689

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	TOW COVER FRT XC60 1 <i>Xsvl</i>	1.0 EA	77.70			77.70	S
	BUMPER BRACKET FRT L <i>?cm/</i>	1.0 EA	72.90			72.90	S <i>65.61</i>
	BUMPER BRACKET FRT R <i>?cm/</i>	1.0 EA	72.90			72.90	S <i>65.61</i>
	VO31425175/BUMPER GR <i>?Xsvl</i>	1.0 EA	458.20			458.20	S
	BUMPER FOAM FRT XC60 <i>?cm/</i>	1.0 EA	359.60			359.60	S <i>323.64</i>
	LOUVRE DECOR LH XC60 <i>?Xsvl</i>	1.0 EA	32.10			32.10	S
	LOUVRE DECOR RH XC60 <i>?Xsvl</i>	1.0 EA	29.20			29.20	S
	COVER DECOR LH T5 XC <i>?Xsvl</i>	1.0 EA	33.40			33.40	S
	COVER DECOR RH T5 XC <i>?Xsvl</i>	1.0 EA	33.40			33.40	S
	RETAINER SENSOR CTR <i>?Xsvl</i>	1.0 EA	20.30			20.30	S
	RETAINER SENSOR CTR <i>?Xsvl</i>	1.0 EA	21.50			21.50	S
	BRACKET DECOR LH XC60 <i>?Xsvl</i>	1.0 EA	45.30			45.30	S
	BRACKET DECOR RH XC60 <i>?Xsvl</i>	1.0 EA	40.80			40.80	S
	HEADLAMP LED LH XC60 <i>cm/</i>	1.0 EA	2453.20			2,453.20	S <i>2207.88</i>
	HEADLAMP LED RH XC60 <i>cm/</i>	1.0 EA	2453.20			2,453.20	S <i>2207.88</i>
	HEADLAMP CONTROL UNI <i>?Xsvl</i>	1.0 EA	480.40			480.40	S
	HEADLAMP CONTROL UNI <i>?Xsvl</i>	1.0 EA	480.40			480.40	S

SERVICE ESTIMATE

94781 - C00001
Mr Tham Kwok Leong
32 Kismis Green

SL: SERVICE SALES - PC

Address Ok
Singapore 596264

Closed by : Michelle Ong Siew Be
Svc Consultant :
Remarks : Mr Tham Kwok Leong

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 4

Inv.date. : 02/11/2020

WIP No. . : 47472

Veh.In/Out:

*Tel.No. . : Mobile: 97353256

Reg.No. . : SLU8466J

Reg.date. : 15/12/2017

Mileage . : 0

Chassis No: YV1UZ10ACJ1031689

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

CROSS MEMBER ? 1/4	1.0 EA	153.00				153.00 S	137.70
VO32216660/BUMPER RA ? 1/4	1.0 EA	1403.90				1,403.90 S	1263.51
TAILGATE REAR XC60 1 cut	1.0 EA	2852.20				2,852.20 S	2566.98
EMBLEM 'VOLVO' REAR ne	1.0 EA	96.70				96.70 S	87.03
EMBLEM 'XC60' CH 365 ne	1.0 EA	100.80				100.80 S	90.72
EMBLEM 'T5' XC60 S80 ne	1.0 EA	92.50				92.50 S	83.25
Emblem 'AWD' XC90 16 ne	1.0 EA	82.10				82.10 S	73.89
VO39847249/BUMPER CO cut	1.0 EA	1401.00	1469.40			1,401.00 S	1322.46
TOW COVER REAR XC60 mis	1.0 EA	77.70				77.70 S	69.93
PROTECTING PLATE REA ? x su	1.0 EA	675.30				675.30 S	
BUMPER BRACKET CTR R ? on	1.0 EA	72.90				72.90 S	65.61
BUMPER BRACKET LHR X ? for	1.0 EA	44.50				44.50 S	
BUMPER BRACKET RHR X ? for	1.0 EA	44.50				44.50 S	
BLIND RIVET 4.0*21 P ne	10.0 EA	3.20				32.00 S	28.80
BUMPER CLIP 8x8,5 ne	10.0 EA	5.70				57.00 S	51.30
BUMPER INSTALLING MT ne	1.0 EA	87.70				87.70 S	78.93
EXTERIOR ADHESIVE GL ne	2.0 EA	249.40				498.80 S	448.92

SERVICE ESTIMATE

94781 - C00001
Mr Tham Kwok Leong
32 Kismis Green

SL: SERVICE SALES - PC

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 5

Inv.date. : 02/11/2020

WIP No. . : 47472

Veh.In/Out:

*Tel.No. . : Mobile: 97353256

Reg.No. . : SLU8466J

Reg.date. : 15/12/2017

Mileage . : 0

Chassis No: YV1UZ10ACJ1031689

Address Ok
Singapore 596264

Closed by : Michelle Ong Siew Be
Svc Consultant :

Remarks : Mr Tham Kwok Leong

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

D WELDING PRIMER	1.0 EA	367.80				367.80 S	331.02
ADHESIVE TUBE CHEMIC	1.0 EA	725.00				725.00 S	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Resu
4p 90010068
8 day
10/11/2020 @ 1210
Resurvey before paint

Labour Total	11,800.00
Parts Total	23,535.00
Package Total	0.00

Gross Total. 35,335.00

Net..... 35,335.00

GST @ 7.0% 2,473.45

Total..... 37,808.45

Paid..... 0.00

Please Pay.. 37,808.45

GST: S=StdRated; O=OutOfScope; Z=ZeroRated