

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SMP5352M

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	55.00	/ /
2	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	200.00	100 /
3	ZZ/001	CONDUCT TP CLAIM CN TAIPING DATE:02/11/2020 1220HR LOCATION:ORCHARD ROAD		
4	ZZ/002	REPAIR/REPLACE REAR BUMPER, END PANEL, TAILGATE, RH REAR FENDER & LH REAR FENDER	1400.00	560 /
5	ZZ/003	RESPRAY REAR BUMPER, END PANEL, TAILGATE, LH REAR FENDER & RH REAR FENDER	1250.00	750 /
6	ZZ/004	TRANSFER TAILGATE MECHANISM TO NEW TAILGATE	120.00	/ /
7	ZZ/005	SUPPLY & INSTALL REAR WINDSCREEN TINTED FILM	144.00	/ /
8	ZZ/006	REFIX REAR WINDSCREEN	240.00	/ /
9	ZZ/007	REMOVE/REFIX REAR SEAT, TRIM, CARPET & GARNISH TO FACILITATE REPAIR	240.00	120? - X m
10	ZZ/008	SUPPLY & INSTALL 1 UNIT HELLA DRIVE RECORDER	357.00	/ /
11	ZZ/009	QC & CONSULT CHECK		
12	ZZ/10	CARWASH & VACUUM		
TOTAL LABOUR CHARGES			4006.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMP5352M

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
1 DOOR BACK TAILGATE GLASS <i>bro</i> ✓	9001A-5TK1C	4015.00 ✓		
2 DOOR BACK TAILGATE <i>lt</i> ✓	K010M-5TAAA	1742.00 ✓		
3 A FIN BACK DOOR TAILGATE GARNISH <i>? X</i> ✓	90810-5TA0A	797.20 X		
4 A FIN BACK DOOR (SERENA WORDING GARNISH) <i>? X</i> ✓	90810-5TD5C	797.20 X		
5 EMBLEM-REAR -HIGHWAY STAR <i>neu</i> ✓	90897-5TA0A	50.90 ✓		
6 EMBLEM-REAR-E POWER <i>neu</i> ✓	90892-5TL0A	94.40 ✓		
7 FACE-RR BUMPER <i>de</i> ✓	85022-5TT6H	1414.00 ✓		
8 SENSOR-REVERSE <i>? X</i> ✓	SENSOR			360.00
9 COVER REVERSE SENSOR BRACKET LH <i>neu</i> ✓	28533-5TT0D			96.30 ✓
10 COVER REVERSE SENSOR BRACKET RH <i>neu</i> ✓	28533-5TT1D			96.30 ✓
11 COVER REVERSE SENSOR BRACKET CENTER 2 PCS <i>neu</i> ✓	28533-5ZA0A			145.00 ✓
SUB TOTAL		8910.70	0.00	697.60
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		1782.14	0.00	0.00
GRAND TOTAL		7128.56	0.00	697.60
OVERALL TOTAL		7826.16		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SMP5352M

TOTAL LABOUR CHARGES	4006.00
TOTAL SPARE PARTS CHARGES	7826.16
GRAND TOTAL	11832.16 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME : Rasul - 4p 90010068
SURVEYED DATE : 04/11/2020 @ 1130
AUTHORIZED DATE :
EXCESS CLAUSE : 0.00
LIABILITY : 0.00
REMARKS : 5 days + 4 = 9 days in total
Resurvey before paint

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: