

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Tan Kah Leong

Date: 05 Nov 2020

Preliminary Advice

Insured Vehicle No	: 201206113H	Accident Date	: 02/11/2020
TP Vehicle No	: SMP5352M	Assignment Date	: 04/11/2020
Make	: NISSAN SERENA	Est. Duration of Repair	: 5
Date of Inspection	: 04/11/2020		
Inspection At	: TC AUTOCLINIC PTE LTD (LENG KEE) 25 LENG KEE ROAD SINGAPORE 159097		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,832.16
Revised Amount	:S\$	8,516.64
Check Items (Estimated)	:S\$	1,875.52
Total	:S\$	10,392.16
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :