

TC AUTOCLINIC PTE LTD  
25 LENG KEE ROAD  
SINGAPORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SMP5352M

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 ZZ/001	SUPPLEMANTERY LABOUR AND PARTS		
2 ZZ/002	LABOUR TO VACUUM ALL SHATTERED GLASS & DEBRIS FROM INTERIOR OF VEHICLE TO FACILITATE REPAIR	15.00	/
3 ZZ/003	REMOVE/REPLACE REAR END PANEL	280.00	/
4 ZZ/004	APPLY SEALANT AND ANTI RUST TO REAR END PANEL	220.00	/
5 ZZ/005	REMOVE/REFIX ROOF LINING TO FACILITATE REPAIR	420.00	/
6 ZZ/006	RESPRAY REAR END PANEL, LH REAR FENDER & RH REAR FENDER	720.00	/
7 ZZ/007	CONDUCT WATER TEST AFTER REPAIR	80.00	/
	TOTAL LABOUR CHARGES	1735.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMP5352M

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
			NETT	LIST	S/NETT	
1	FIN BACK DOOR SERENA <b>cra</b> ✓	90810-5TD5D	797.20	X Repeated		
2	BUMPER B/DOOR RUBBER STOPPER <b>nec</b> ✓	90878-5TA0A	9.10			
3	FINISHER BACK DOOR LOWER GARNISH <b>cra</b> ✓	90901-5TA0A	297.90			
4	HANDLE-PULL <b>cut</b> ✓	90940-4N000	19.60			
5	ORNAMENT-REAR EMBLEM <b>nec</b> ✓	90886-5TA0B	79.90			
6	A FIN BACK DOOR CHROME GARNISH <b>cra</b> ✓	90810-5TA0A	797.20	X Repeated		
7	RR PANEL-LWR <b>bt</b> ✓	79120-5TT0A	215.00			
SUB TOTAL			2215.90	0.00	0.00	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			443.18	0.00	0.00	
GRAND TOTAL			1772.72	0.00	0.00	
OVERALL TOTAL			1772.72			

LEGEND: REMARKS( OK ) = APPROVED, REMARKS( X ) = NOT APPROVED