

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0822/2020/NS
DATE : 30-Oct-20
WIP : 54873

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Hi Adrian,

5 days - ok - Jy - 28 Jan 21

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR LIM KNG YAU
ADDRESS : 77 FLORA DRIVE
#08-23
SINGAPORE 506884
TELEPHONE : HP +65 96426011
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1700041626-03
VEHICLE NO : **SLR 5653 X**
MODEL CODE : AUDI A4 SEDSN 1.4 TFSI S
MODEL YEAR : 18/08/2017
ENGINE NO : CVN 040756
CHASSIS NO : WAUZZZF48HA177989
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 27-Oct-20
PLACE OF ACCIDENT : HEDGES PARK CONDOMINIUM CARPARK

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLR 5653 X

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	S/N \$	360.00	\$	360.00
2	TO REMOVE AND TRANSFER LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	280.00		
3	TO DISMANTLE AND RENEW REAR BUMPER AND LHS REAR DOOR. TO REPAIR LHS REAR FENDER. RE- ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,450.00	\$	500.00
4	TO RESPRAY REAR BUMPER, LHS REAR FENDER AND LHS REAR DOOR.	\$	2,900.00	\$	1,650.00
5	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$	280.00	\$	280.00
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 6,462.00	\$	2,982.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLR 5653 X

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	REAR BUMPER		\$ 2,181.00	
2	REAR BUMPER FIXING PARTS		\$ 72.00	
3	REAR BUMPER SECURING STRIP		\$ 220.00	
4	REAR BUMPER SPOILER		\$ 246.00	
5	REAR LIGHT REFLECTOR - LH		\$ 41.00	
6	REAR BUMPER GUIDE SECTION - LH		\$ 44.00	
7	REAR DOOR - LH		\$ 2,354.00	
8	REAR DOOR OUTER SEAL - LH	NEC	\$ 203.00	
9	BONDING AGENT	NEC	\$ 47.00	
10	CLEANING SOLUTION	NEC	\$ 65.00	
11	SEALING STRIP		\$ 16.00	
12	REAR DOOR ATTACHMENT PARTS		\$ 563.00	
13	REAR DOOR CATCH		\$ 119.00	
14	REAR ALUMINIUM RIM - LH		TBC	
15	SUNDRIES		\$ 300.00	
TOTAL SPARE PARTS		:	\$ 6,471.00	\$ -
TOTAL LABOUR CHARGES		:	\$ 6,462.00	\$ 2,982.00
GRAND TOTAL		:	\$ 12,933.00	\$ 2,982.00

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

