

 PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0822/2020/NS
DATE : 30-Oct-20
WIP : 54873

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT**TEL: 6841 0055 - FAX: 6256 4315**

OWNER'S NAME : MR LIM KNG YAU
ADDRESS : 77 FLORA DRIVE
#08-23
SINGAPORE 506884
TELEPHONE : HP +65 96426011
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1700041626-03
VEHICLE NO : **SLR 5653 X**
MODEL CODE : AUDI A4 SEDSN 1.4 TFSI S
MODEL YEAR : 18/8/2017
ENGINE NO : CVN 040756
CHASSIS NO : WAUZZZF48HA177989
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 27-Oct-20
PLACE OF ACCIDENT : HEDGES PARK CONDOMINIUM CARPARK


ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLR 5653 X

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	S/N \$ 360.00 ✓	
2	TO REMOVE AND TRANSFER LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 280.00 ✗	
3	TO DISMANTLE AND RENEW REAR BUMPER AND LHS REAR DOOR. TO REPAIR LHS REAR FENDER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,450.00 500 ✓	
4	TO RESPRAY REAR BUMPER, LHS REAR FENDER AND LHS REAR DOOR.	\$ 2,900.00 1650 ✓	
5	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$ 280.00 ✓	
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 6,462.00	



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLR 5653 X

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1 REAR BUMPER <i>Repis</i>		\$ 2,181.00	+
2 REAR BUMPER FIXING PARTS		\$ 72.00	+
3 REAR BUMPER SECURING STRIP		\$ 220.00	+
4 REAR BUMPER SPOILER		\$ 246.00	+
5 REAR LIGHT REFLECTOR - LH		\$ 41.00	+
6 REAR BUMPER GUIDE SECTION - LH <i>ne new</i>		\$ 44.00	+
7 REAR DOOR - LH <i>Repis</i>		\$ 2,354.00	+
8 REAR DOOR OUTER SEAL - LH <i>ne new</i>	NEC	\$ 203.00	+
9 BONDING AGENT	NEC	\$ 47.00	+
10 CLEANING SOLUTION	NEC	\$ 65.00	+
11 SEALING STRIP		\$ 16.00	+
12 REAR DOOR ATTACHMENT PARTS		\$ 563.00	+
13 REAR DOOR CATCH		\$ 119.00	+
14 REAR ALUMINIUM RIM - LH <i>at</i>		TBC	✓
15 SUNDRIES <i>NN</i>		\$ 300.00	X
TOTAL SPARE PARTS	:	\$ 6,471.00	
TOTAL LABOUR CHARGES	:	\$ 6,462.00	
GRAND TOTAL	:	\$ 12,933.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



NAME : Adrian S
SURVEYED DATE : 04/11/20
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : Not Authorised, 05 Days

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT