



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

Co Reg No : 1977014696

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
LUM E-SHAN (LIN QISHAN)	Cust No/Name KCV11967/LUM E-SHAN (LIN QISHAN)
14 CHOA CHU KANG GROVE #12-37 SINGAPORE 688209	Reg No/Reg Date SMN8049E / 29/08/201
Contact No	Date In/Mileage / 0
	Chassis No MMBSTA13AKH001716
	Engine No 3A92UHS3083
	Make/Model MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim X08 BLACK / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KCV11967	CRDVCH	29/10/2020/ 16:17	TLC	442 / CocoLu	58991

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW REAR BUMPER, REPAIR REAR AIRDAM, BOOTLID @650X1.5	1.00	1650.00		1650.00
E PNT88000 REMOVE & INSTALL PARKING SENSOR	1.00	100.00		100.00
E PNT98000 SPRAY PAINT FOR REAR AIRDAM, REAR BUMPER, BOOTLID, @350 X3	1.00	1650.00		1650.00
A 54900099 CHECK WIRING & ELECTRICAL SYSTEM	1.00	30.00		30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	1.00	200.00		200.00
M SUNDRY Sundry	1.00	20.00		20.00
M FACE,RR BUMPER de 7.550	1.00	748.00	00.00	748.00
M BRACKET,RR BUMPER,RH 7.550	1.00	28.00	00.00	28.00
M BRACKET,RR BUMPER,LH 7.550	1.00	28.00	00.00	28.00
M MARK,THREE-DIA ne	1.00	69.00	00.00	69.00
M MARK,ATTRAGE new	1.00	21.00	00.00	21.00

SURVEYOR NAME: Rahul - Hp 90010088SURVEYOR SIGNATURE: [Signature]DATE: 09/11/2020 @ 12:40REMARKS: 4 daysResy before put

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Confirm & accepted by

Acknowledged by Repairer

Signature:

Date:

Nett

4,574.00

7% GST on 4574.00

320.18

Total Payable

4,894.18

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.