


 **PREMIUM AUTOMOBILES**



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0829/2020/NS
DATE : 3-Nov-20
WIP : 56199

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING


SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR SANGRAM SINGH
ADDRESS : 5 RHU CROSS
#10-19
SINGAPORE 437434
TELEPHONE : HP +65 90022053
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1700037162-03
VEHICLE NO : SGL 367 X
MODEL CODE : AUDI A4 SEDAN 1.4 TFSI S
MODEL YEAR : 2/9/2017
ENGINE NO : CVN 045373
CHASSIS NO : WAUZZZF41JA022724
MILEAGE : 22577KM
DATE IN : 2-Nov-20
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 31-Oct-20
PLACE OF ACCIDENT : 82 ENG NEO

PREMIUM AUTOMOBILES




55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAT@PREMIUMAUTO.COM.SG / ATMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SGL 367 X

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	S/N \$ 360.00	X
2	TO RENEW REAR WINDSCREEN AND 1/4 GLASS TO FACILITATE FENDER RENEWAL.	S/N \$ 600.00	✓
3	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND 1/4 GLASS.	S/N \$ 400.00	? sales agreement
4	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN.	S/N \$ 200.00	✓
5	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR TAIL LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT.	S/N \$ 1,400.00	✓ photo.
SUB TOTAL LABOUR CHARGES		: \$ 2,960.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / LAI@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SGL 367 X

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGR ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$ 1,400.00	photo.
7	TO DISMANTLE AND RENEW REAR BUMPER. CUT OUT AND WELD RHS REAR FENDER, RHS OUTER WHEEL HOUSING AND RHS REAR D-INNER SIDE PANEL. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 7,700.00	3000 2500
8	TO RESPRAY REAR BUMPER, RHS REAR FENDER, DOOR ENTRANCES, RHS OUTER WHEEL HOUSING AND RHS D-INNER SIDE PANEL, RHS SILL PANEL, FUEL FILLER CAP, ROOF CHANNEL, DRAIN PANEL AND END PANELLING. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS.	\$ 6,000.00	fuel cover 1925 + 100 2025
9	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 18,252.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGL 367 X

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
1 REAR BUMPER		\$	2,181.00	X NN
2 REAR BUMPER FIXING PARTS		\$	72.00	X NN
3 REAR BUMPER SECURING STRIP		\$	220.00	X NN
4 REAR BUMPER GUIDE SECTION - RH		\$	45.00	X NN
5 REAR FENDER - RH		\$	2,644.00	bt
6 REAR WINDSCREEN		\$	1,141.00	nee photo
7 SIDE WINDOW - RH		\$	609.00	nee photo
8 PRIMER		\$	19.00	nee
9 FUEL POCKET		\$	88.00	?
10 FUEL FILLER CAP		\$	305.00	?
11 LED TAIL LIGHT - RH		\$	1,008.00	Over
12 TAIL LIGHT TRIM - RH		\$	30.00	X NN
13 WHEEL HOUSING LINER - RH		\$	237.00	?
14 WHEEL HOUSING LINER ATTACHMENT PARTS		\$	90.00	?
15 LUGGAGE COMPARTMENT TRIM - RH		\$	779.00	X NN
16 WHEEL HOUSING - RH OUTER		\$	625.00	?
17 INNER SIDE PANEL - RH REAR		\$	846.00	?
18 1/4 GLASS SEALANT	S/N	\$	100.00	nee
19 REAR WINDSCREEN SEALANT	S.N	\$	200.00	nee
20 METAL FILLER POWDER	S.N	\$	280.00	nee
SUB TOTAL SPARE PARTS	:	\$	11,519.00	

 **PREMIUM AUTOMOBILES**



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG


MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGL 367 X

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
21 STONE CHIP	S/N	\$ 180.00	<i>ok</i>
22 CAVITY WAX	S/N	\$ 140.00	<i>ok</i>
23 ACRYLIC SEALANT	S/N	\$ 180.00	<i>ok</i>
24 SUNDRIES		\$ 300.00	<i>?</i>
TOTAL SPARE PARTS	:	\$ 12,319.00	
TOTAL LABOUR CHARGES	:	\$ 18,252.00	
GRAND TOTAL	:	\$ 30,571.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

 **PREMIUM AUTOMOBILES**



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Tanpin 17495749*
 SURVEYED DATE : *8/11/2012 3:50pm*
 AUTHORISED DATE : *Not Authorise*
 EXCESS COST : *Ex: to be advise*
 LIABILITY :
 REMARKS : *Resurvey before paint 12 days*
Tanpin @ khkib.com. 10 days.

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
 PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Thiro party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental system(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

JOHNNY BOO
 BODY REPAIR MANAGER

ALLAN WU
 CLAIMS CONSULTANT