

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS  
WORKSHOP : UBI ROAD 1  
CONTACT NO : 6366 2323  
FAX NO : 6841 1183  
REFERENCE : PA/OD/0829/2020/NS  
DATE : 03-Nov-20  
WIP : 56199

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

**AIG ASIA PACIFIC INSURANCE PTE LTD**

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

*Hi Taufikh,*

*12 days - ok - Jy - 28 Dec 20*

**ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT**

**TEL: 6841 0055 - FAX: 6256 4315**

OWNER'S NAME : MR SANGRAM SINGH  
ADDRESS : 5 RHU CROSS  
#10-19  
SINGAPORE 437434  
TELEPHONE : HP +65 90022053  
TYPE OF CLAIM : OWN DAMAGE CLAIM  
POLICY NO : 1700037162-03  
VEHICLE NO : SGL 367 X  
MODEL CODE : AUDI A4 SEDAN 1.4 TFSI S  
MODEL YEAR : 02/09/2017  
ENGINE NO : CVN 045373  
CHASSIS NO : WAUZZZF41JA022724  
MILEAGE : 22577KM  
DATE IN : 02-Nov-20  
ESTIMATED BY : JOHNNY BOO / ALLAN WU  
ACCIDENT DATE : 31-Oct-20  
PLACE OF ACCIDENT : 82 ENG NEO



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SGL 367 X**

<b>S/N</b>	<b>NATURE OF JOBS</b>	<b>ESTIMATED CHARGES</b>	<b>SURVEYOR'S RECOMMENDATIONS</b>
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	S/N \$ 360.00	
2	TO RENEW REAR WINDSCREEN AND 1/4 GLASS TO FACILITATE FENDER RENEWAL.	S/N \$ 600.00	\$ 600.00
3	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND 1/4 GLASS.	S/N \$ 400.00	
4	TO CARRY OOUT WATER SEEPAGE TEST FOR REAR WINDSCREEN.	S/N \$ 200.00	\$ 200.00
5	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR TAIL LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT.	S/N \$ 1,400.00	\$ 1,400.00
<b>SUB TOTAL LABOUR CHARGES</b>		<b>: \$ 2,960.00</b>	<b>\$ 2,200.00</b>





55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGL 367 X**

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	REAR BUMPER		\$ 2,181.00	
2	REAR BUMPER FIXING PARTS		\$ 72.00	
3	REAR BUMPER SECURING STRIP		\$ 220.00	
4	REAR BUMPER GUIDE SECTION - RH		\$ 45.00	
5	REAR FENDER - RH		\$ 2,644.00	\$ 2,115.20
6	REAR WINDSCREEN		\$ 1,141.00	\$ 912.80
7	SIDE WINDOW - RH		\$ 609.00	\$ 486.80
8	PRIMER		\$ 19.00	\$ 14.96
9	FUEL POCKET		\$ 88.00	
10	FUEL FILLER CAP		\$ 305.00	
11	LED TAIL LIGHT - RH		\$ 1,008.00	\$ 806.40
12	TAIL LIGHT TRIM - RH		\$ 30.00	
13	WHEEL HOUSING LINER - RH		\$ 237.00	
14	WHEEL HOUSING LINER ATTACHMENT PARTS		\$ 90.00	
15	LUGGAGE COMPARTMENT TRIM - RH		\$ 779.00	
16	WHEEL HOUSING - RH OUTER		\$ 625.00	
17	INNER SIDE PANEL - RH REAR		\$ 846.00	
18	1/4 GLASS SEALANT	S/N	\$ 100.00	\$ 100.00
19	REAR WINDSCREEN SEALANT	S/N	\$ 200.00	\$ 200.00
20	METAL FILLER POWDER	S/N	\$ 280.00	\$ 280.00
<b>SUB TOTAL SPARE PARTS</b>		<b>:</b>	<b>\$ 11,519.00</b>	<b>\$ 4,916.16</b>



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGL 367 X**

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
		<i>c/f</i>		\$ 4,916.16
21	STONE CHIP	S/N	\$ 180.00	\$ 180.00
22	CAVITY WAX	S/N	\$ 140.00	\$ 140.00
23	ACRYLIC SEALANT	S/N	\$ 180.00	\$ 180.00
24	SUNDRIES		\$ 300.00	\$ 59.44
<b>TOTAL SPARE PARTS</b>		:	\$ 12,319.00	\$ 5,475.60
<b>TOTAL LABOUR CHARGES</b>		:	\$ 18,252.00	\$ 9,367.00
<b>GRAND TOTAL</b>		:	\$ 30,571.00	\$ 14,842.60

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

b1-04/12/20