



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2102196

36 ROBINSON ROAD  
#16-01 CITY HOUSE  
SINGAPORE 068877

INV Date 05/04/2021  
Reference CC4/FCI20012047/R1ea3q2  
Code FCI2

#### PROFESSIONAL SERVICE FEE

Vehicle No. SMT 2022P  
Insured Veh. SHD 6978Z  
Claim No. D20004152MFSH  
Policy No. D-20094922MFSH  
Accident Date 14/09/2020  
Inspection Date 24/11/2020

Description	Total
Third Party Express Settlement	500.00
<b>Subtotal</b>	<b>500.00</b>
<b>GST (7%)</b>	<b>35.00</b>
<b>Grand Total</b>	<b>535.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD  
36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Ref: CC4/FCI20012047/R1ea3q2

Date: 05/04/2021

Code: FCI2

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SHD 6978Z	<b>Veh. Inspected</b>	SMT 2022P
<b>Policy No.</b>	D-20094922MFSH	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	D20004152MFSH	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	RACHEL WU	<b>Assign Date</b>	04/11/2020

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	SKODA KODIAQ 1.4 TSI AM.P	<b>c.c</b>	1395
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2020
<b>Chassis No.</b>	TMBKC7NSXL8506329	<b>Colour</b>	WHITE
<b>Odometer</b>	12039 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	FAIR		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	235/55 R18	PIRELLI	6 mm
<b>L/H Front Tyre</b>	235/55 R18	PIRELLI	6 mm
<b>R/H Rear Tyre</b>	235/55 R18	PIRELLI	6 mm
<b>L/H Rear Tyre</b>	235/55 R18	PIRELLI	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	14/09/2020	<b>Inspection Date</b>	24/11/2020
<b>Survey held at</b>	VOLKSWAGEN GROUP SINGAPORE PTE LTD 247 ALEXANDRA ROAD SINGAPORE 159934		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMT 2022P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	COVER FOR FRT BUMPER (SN)	TO REPAIR SEE LABOUR	1,695.00	-
1	GUIDE PIEC RHF SIDE BRACKET (SN)	NOT NECESSARY	49.70	-
1	SENSOR BRA (SN)	NOT NECESSARY	13.00	-
1	SENSOR BRA (SN)	NOT NECESSARY	13.00	-
1	2K-PLASTIC ADHESIVE (SN)	NOT NECESSARY	75.94	-
1	BONDING AGENT FOR PLASTIC (SN)	NOT NECESSARY	59.40	-
1	CAP RHF FOG LAMP GRILLE (SN)	NOT NECESSARY	55.50	-
1	FRONT SPOI (SN)	SCRATCHED	425.00	425.00
1	TRIM FOR W RHF WHEEL ARCH (SN)	SCRATCHED	172.00	172.00
9	GROMMET (SN)	NOT NECESSARY	14.04	-
1	UNBEKANNT RHF HEADLAMP (SN)	NOT NECESSARY	3,075.02	-
			5,647.60	597.00
<b>LABOUR</b>				
	DIAGNOSTIC AND PROGRAMMING .		480.00	480.00
	CHECK SHORT CIRCUIT /HARNESS REPAIR .	NOT NECESSARY	280.00	-
	LABOUR .INCLUSIVE OF THE REPAIR OF COVER FOR FRT BUMPER .		2,520.00	840.00
	SPRAY PAINTING .		2,400.00	800.00
	TO ALIGN LED HEADLAMP .	NOT NECESSARY	100.00	-
			5,780.00	2,120.00
<b>GRAND TOTAL</b>			<b>11,427.60</b>	<b>2,717.00</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>2,717.00</b>

Report Ref No. CC4/FCI20012047/R1ea3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMT 2022P

INSPECTION







# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMT 2022P

RE-INSPECTION





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

