

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20012053/KPS3Q2**Date:** 08/06/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993949
Claimant Vehicle No :	SLJ6037K	Insured Vehicle No :	GBK3002T
Date of Loss:	29/10/2020	Nature of Claim:	TP
		Claim No:	9656918478SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLJ6037K	Engine No:	G4NAGU300698
Make & Model:	HYUNDAI TUCSON, 2.0 GLS (A)	Chassis No:	KMHJ3813MHU365900
Reg. Date:	19/12/2016 (Man. Year: 2016)	Odometer:	34325 km
Colour:	Metallic Silver		
Engine Capacity:	1999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/60 R17	Rear Tyre Size:	225/60 R17
Front Left Side:	Kumho 7 mm	Rear Left Side:	Kumho 7 mm
Front Right Side:	Kumho 7 mm	Rear Right Side:	Kumho 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,829.36	1,785.60	4,043.76	69.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,510.00	1,160.00	350.00	23.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,339.36	2,945.60	4,393.76	59.87
Approved Total (Overridden) (S\$)		2,350.00		
(S\$)	7,339.36	2,350.00	4,989.36	67.98
+ GST 7.00/7.00% (S\$)	513.76	164.50	349.26	67.98
Nett Amount (S\$)	7,853.12	2,514.50	5,338.62	67.98
+ Loss of Use (6.0 x S\$100.00/day) (S\$)		600.00		
(S\$)		3,114.50		
Liabe Amount (50.00%) (S\$)		1,557.25		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,564.70		
Global Sum Settlement (S\$)		1,560.00		

INSPECTION

Date of Assignment:	04/11/2020	
Date Inspected:	09/11/2020	Inspected At: City Auto Pte Ltd (HQ) 160 Sin Ming Drive #05-01., Sin Ming AutoCity, Singapore 575722
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER -LOWER	Distorted / Cut	381.40 FL	*381.40 FL
2	1		*FRONT BUMPER -UPPER	Buckled / Dented	509.50 FL	*509.50 FL
3	1		*FRONT BUMPER RETAINER -LH	Necessary	28.00 FL	*28.00 FL
4	1		*HEADLAMP -LH	Serviceable	2,677.90 FL	*- FL
5	1		*FRONT FENDER -LH	Bent	641.70 FL	*641.70 FL
6	1		*FRONT FENDER GARNISH -LH	Dented / Cut	108.90 FL	*108.90 FL
7	1		*FRONT FENDER INNER SHIELD LH	Serviceable	130.60 FL	*- FL
8	1		*MUD FLAP -LH	Serviceable	29.70 FL	*- FL
9	1		*FRONT WHEEL BEARING -LH	Not Necessary	540.50 FL	*- FL
10	1		*FRONT ABSORBER -LH	Serviceable	287.30 FL	*- FL
11	1		*FRONT KNUCKLE -LH	Serviceable	357.50 FL	*- FL
12	1		*WING MIRROR -LH	Repair	1,031.20 FL	*- FL
13	1		*RIM -LH	Dented	450.00 FS	*450.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	7,174.20	2,119.50
- List Item Discount on L Items 20.00/20.00% (S\$)	1,344.84	333.90
Total Parts (S\$)	5,829.36	1,785.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	COMPUTERISED WHEEL ALIGNMENT	New	60.00	60.00
2	LABOUR TO CHARGE SUSPENSION	New	150.00	0.00
3	TO KNOCK JACKOUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN,REFIX AND TO RENEW ACCIDENT PARTS	New	550.00	450.00
4	SPRAY PAINTING ON AFFECTED & REPLACED PARTS	New	750.00	650.00
Gross Labour Cost (\$\$)			1,510.00	1,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >