



CITY AUTO PTE LTD

One Stop Automotive Solution
BLK 8, SIN MING IND. ESTATE #01-60/62, SIN MING ROAD, SINGAPORE 575643
TEL: 6453 1235, 6452 0850 FAX: 6453 7944
24hrs Towing Services Tel 9823 9898
Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

AIG ASIA PACIFIC INSURANCE PTE. LTD

NO. 78
SHENTON WAY #07-16
SINGAPORE 079120

Contact : -

Not with paint
Runny paint
1/18p @ 2350/p
5 days

Estimate : QUOT202011-000056(00)

Date : 03/11/2020
Vehicle No. : SLJ6037K
Make/Model : HYUNDAI TL TUCSON 2.0 GLS AT 2WD
Mileage (km) : 0
Chassis No. : KMHJ3813MHU365900
Accident Date : 29/10/2020 00:00:00
Claim No. : GBK3002T
Reference : JO202011-0089
Policy No. : DMPG19011713

19/12/2016

S/No	Particular	Quantity	Unit Price	Amount S\$
LIST ITEMS :				
1	Front bumper - lower	1.0	381.40	381.40 ✓
2	Front bumper - upper	1.0	509.50	509.50 ✓
3	Front bumper retainer - LH	1.0	28.00	28.00 ✓
4	Headlamp - LH	1.0	2,677.90	2,677.90 ✓
5	Front fender - LH	1.0	641.70	641.70 ✓
6	Front fender garnish - LH	1.0	108.90	108.90 ✓
7	Front fender inner shield LH	1.0	130.60	130.60 ✓
8	Mud flap - LH	1.0	29.70	29.70 ✓
9	Front wheel bearing - LH	1.0	540.50	540.50 ✓
10	Front absorber - LH	1.0	287.30	287.30 ✓
11	Front knuckle LH	1.0	357.50	357.50 ✓
12	Wing Mirror - LH	1.0	1,031.20	1,031.20 ✓
List Total :				6,724.20
20% Discount S\$				1,344.84
				5,379.36
SPECIAL NET :				
1	Rim - LH	1.0	450.00	450.00 ✓
SPECIAL NET Total S\$:				450.00
LABOUR :				
	Computerised wheel alignment	1.0	60.00	60.00 ✓
	- Labour to change suspension	1.0	150.00	150.00 ✓
	- To knock jackout damaged parts, panel beating, welding, align, refix and to renew accident parts	1.0	550.00	550.00 ✓
	- Spray painting on affected & replace parts	1.0	750.00	750.00 ✓
				1,510.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

CONTINUE NEXT PAGE

Page 1 of 2