## **OMFORTDELGRO PTE LTD**

## REPAIR ESTIMATE\*

VEHICLE NO SHD4059P

04/11/20

MAKE .

| ODEL IONIQ G3 |   | CHIANG/ AIG |            |   |
|---------------|---|-------------|------------|---|
| Qty           | Parts Description/ Labour                                   | Туре        | Unit Price | Amount  |
|               | 1REAR BUMPER X K  |             |            | \$459.4                                       |
|               | 1 REAR BUMPER BRACKET LH/RH X AIAI                          | 1 1         | \$55.80    | \$111.6                                       |
|               | 1 REAR REINFORCEMENT X                                      |             |            | \$294.8                                       |
|               | OREAR BUMPER CLIPS X AN                                     |             | \$2.20     | \$22.0  |
|               | 1 REAR BUMPER CENTRE MOULDING / (U)                         |             |            | \$451.2                                       |
|               | 1FOG LAMP   |             |            | \$201.0                                       |
|               | Troo bann   |             |            | \$1,540.0                                     |
|               | 20.009  | <b>%</b>    |            | \$308.0                                       |
|               | DISCOUNTED TOTAL  | u l         |            | \$1,232.                                      |
|               |   |             |            |   |
|               | 1 REVERSE SENSOR X  |             |            | \$135.  |
|               | 1BUMPER MAT X   |             |            | \$50.   |
|               | REAR NUMBERPLATE W/HOLDER                                   |             |            | \$50.   |
|               | TREAK NOWIBERFEATE WYTTOLDER > 131/                         |             |            | \$235.  |
|               |   | 1 1         |            |   |
|               | Labour Charge   |             | _ 1        |   |
|               |   |             | 31         | \$640.  |
|               | Panel Beating   |             | 9          | od \$300.                                     |
|               | Spray Painting Charge                                       |             | 1          | 义 \$60.                                       |
|               | Remove/refix reverse sensor                                 |             | 1          | \$50.   |
|               | Check lighting TOTAL LABOU                                  | R           |            | \$1,050.                                      |
|               | TOTAL BABOO   |             | *          |   |
|               | CCTIMANTE TOTA  |             |            | \$2,517.                                      |
|               | ESTIMATE TOTAL  | "] [        |            | 1 Pro 200 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 |
|               |   |             |            |   |
|               |   |             |            |   |
|               |   |             |            |   |
|               | This is an initial estimate based on a visual inspection of |             |            | A   |

This is an initial estimate based on a visual inspection of the above vehicle. The final rep be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Ster (LKK) WI A

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## FORTDELGRO ENGINEERING

ember of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701

Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops

59 Loyang Drive Singapore 508869

383 Sin Ming Drive Singapore 575717
45 Pendan Road Singapore 609286

7 Sungei Kadut Way Singapore 76873:
501 Yishun industrial Park A Singapore 76873:

Date/Time : 04 11 1 20 20 20 12 2 57 Page : 1

| ∌am:           | ARC Repair TP(CLSO)1                      | JOB CARD | Sales Order:                      | JC NO.:305431699            |
|----------------|---|----------|-----------------------------------|-----------------------------|
| OMER           |   |          | REGN NO.:<br>SHD4059P             | MILEAGE                     |
| MS<br>STOMER N | COMFORT TRANSPORTATION PTE LTD O. 7010045 | LTD      | MAKE:<br>HYUNDAI                  | FUEL EF                     |
| DRESS          | 202 GIN MING DRIVE                        |          | MODEL IONIQ(G3) 04                | DATE/TIME IN .11.2020 10:35 |
| - (P)          |   |          | YR OF MANU.<br>30.10.2019         | TARGET DATE                 |
| COUNT CA       | ARD NO.                                   |          | CHASSIS CODE<br>KMHC851CVLU187731 | COMPLETION DATE/TIME:       |

JOB DESCRIPTION

Accident Date: 04.11.2020 NATURE: 3P 04.11.2020

S/NO

LABOR CODE

FRONT DESCRIPTION REAR

| ECKED & PASSED OUT BY:                       |                              |                      |
|--|------------------------------|----------------------|
| SERVICE ADVISOR                              |                              | CUSTOMER'S SIGNATURE |
| wledgement Slip                              | Exit Pass                    |                      |
| .: SHD4059P CHIANG                           | Vehicle No.:<br>SHD4059P     |                      |
| of Service Advisor Signature/Date            | Name of Service Advisor      | Date                 |
| sturned to Service Reception upon collection | To be kept by Security Guard |                      |