



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2100646

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 01/02/2021
Reference CC6/FCI20012060/Ugs3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SLN 2276S
Insured Veh. SHC 8177K
Claim No. D20004448MFSH
Policy No. D-18088936MFSH
Accident Date 30/10/2020
Inspection Date 04/11/2020

Description	Total
Third Party Express Settlement	350.00
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC6/FCI20012060/Ugs3q2	
			Date: 01/02/2021	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 8177K	Veh. Inspected	SLN 2276S	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D20004448MFSH	Excess (\$)	0.00	
Assign From	CHRIS	Assign Date	04/11/2020	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 3 (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JM6BN22A8H0151540	Colour	BROWN	
Odometer	227905 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	CRUCERO	6 mm	
L/H Front Tyre	205/60 R16	CRUCERO	6 mm	
R/H Rear Tyre	205/60 R16	CRUCERO	6 mm	
L/H Rear Tyre	205/60 R16	CRUCERO	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	30/10/2020	Inspection Date	04/11/2020	
Survey held at	FOCUS AUTO PTE LTD NO 1 KAKI BUKIT AVE 6 AUTOBAY #02-48 SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 2276S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT FENDER -LH	BUCKLED	756.20	360.80
1	FRONT FENDER DUST COVER -LH	TORN	124.40	119.30
1	SET FRONT FENDER DUST COVER CLIPS -LH	NECESSARY	33.00	30.00
1	FRONT HEADLAMP -LH	CRACKED	773.30	773.30
1	FRONT GRILLE	CRACKED	380.40	380.40
1	FRONT GRILLE MOULING -LH	SCRATCHED	172.40	172.40
1	FRONT BUMPER	DISTORTED	925.20	925.20
1	FRONT BUMPER SIDE RETAINER -LH	BENT	39.70	39.70
1	FRONT BUMPER UNDER COVER -LH	TORN	267.20	267.20
1	FRONT BUMPER CENTRE COVER -LH	MISSING	30.20	30.20
1	FRONT BUMPER LOWER SUPPORT	NOT NECESSARY	298.20	-
1	FRONT FENDER LOWER SUPPORT BRACKET -LH	BENT	35.20	35.20
1	FRONT SHOCK ABSORBER -LH	NOT NECESSARY	492.40	-
1	FRONT LOWER ARM -LH	NOT NECESSARY	482.20	-
1	FRONT KNUCKLE ARM -LH	NOT NECESSARY	564.20	-
1	FRONT HUB BEARING -LH	NOT NECESSARY	245.40	-
1	FRONT BUMPER CENTRE BRACKET -LH	CRACKED	50.20	50.20
1	FRT BUMPER REINFORCEMENT	BENT	444.50	444.50
	LESS 20% DISCOUNT		-1,222.86	-725.68
			4,891.44	2,902.72
<u>SPECIAL NETT ITEMS</u>				
1	FRONT SPORT RIM -LH (SN)	TO REPAIR SEE LABOUR	720.00	-
			720.00	-
<u>LABOUR</u>				
	TOWING .	NOT NECESSARY	50.00	-
	PANEL BEATING .INCLUSIVE OF THE REPAIR OF FRONT SPORT RIM -LH .		850.00	480.00
	CHECK WIRING .		60.00	20.00
	RUST PROOFING .		60.00	30.00
	ALIGNMENT .		50.00	50.00

Report Ref No. CC6/FCI20012060/Ugs3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE & REPLACE FRONT UNDER CARRIAGE. TO SPRAY PAINTING.	NOT NECESSARY	250.00	-
			720.00	600.00
			2,040.00	1,180.00
GRAND TOTAL			7,651.44	4,082.72
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,250.00

Report Ref No. CC6/FCI20012060/Ugs3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLN 2276S

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLN 2276S

RE-INSPECTION

