

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50

AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6844 4625 Email: claims@focusauto.com.sg

www.khachina

not Authorised
Sale
4/11/20
2/5 3250 /
Hd long 5
Whistle After 12yr

M/S : FIRST CAPITAL INSURANCE LTD**Estimate No : M001720****Date : 02/11/2020****Veh Reg No SLN2276S****Make/Model : MAZDA****ATTN : Motor Claim Department****Your Ref No: : SLN2276S****Chassis No : JM6BN22A8H0151540****Claim Type : THIRD PARTY****Engine No: P520442906****Accident Date : 30/10/2020****Reg. Date : 26/04/2017****Estimate Repair Cost to Vehicle No : SLN2276S****PAGE:1/2**

S/N	Description	Quantity	Unit	Price	Amount
	LIST PRICE			SS	SS
1	Front Fender - LH <i>inc 360.80</i>	1	PCS	756.20	756.20 ✓
2	Front Fender Dust Cover - LH <i>to in 119.30</i>	1	PCS	124.40	124.40 ✓
3	Front Fender Dust Cover Clipse - LH <i>new 30.00 1 set</i>	1	PCS	550	33.00 ✓
4	Front Headlamp - LH <i>one</i>	1	PCS	773.30	773.30 ✓
5	Front Grille <i>one</i>	1	PCS	380.40	380.40 ✓
6	Front Grille Moulding - LH <i>SCR</i>	1	PCS	172.40	172.40 ✓
7	Front Bumper <i>DIS</i>	1	PCS	925.20	925.20 ✓
8	Front Bumper Side Retainer - LH <i>set</i>	1	PCS	39.70	39.70 ✓
9	Front Bumper <i>under</i> Lower Cover - LH <i>to in</i>	1	PCS	267.20	267.20 ✓
10	Front bumper <i>centre</i> Lower Dust Cover - LH <i>new</i>	1	PCS	30.20	30.20 ✓
11	Front Bumper Lower Support <i>new</i>	1	PCS	298.20	298.20 X
12	Front Fender Lower Support Bracket - LH <i>2 set</i>	1	PCS	35.20	35.20 ✓
13	Front Shock Absorber - LH <i>new</i>	1	PCS	492.40	492.40 X
14	Front Lower Arm - LH <i>new</i>	1	PCS	482.20	482.20 X
15	Front Knuckle Arm - LH <i>new</i>	1	PCS	564.20	564.20 X
16	Front Hub Bearing - LH <i>new</i>	1	PCS	245.40	245.40 X
17	Front Bumper Centre Bracket - LH <i>one</i>	1	PCS	50.20	50.20 ✓
TOTAL				5642.30	5669.80
DISCOUNT 20%				4513.88	4535.88

Al hyper reinforcement 444.80 sent

3628.40
20%
2902.72

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50

AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6844 4625 Email: claims@focusauto.com.sg

M/S : FIRST CAPITAL INSURANCE LTD

Estimate No : M001720

Date: : 02/11/2020

Veh Reg No : SLN2276S

Make/Model : MAZDA

ATTN : Motor Claim Department

Your Ref No: : SLN2276S

Chassis No : JM6BN22A8H0151540

Claim Type : THIRD PARTY

Engine No: P520442906

Accident Date : 30/10/2020

Reg. Date : 26/04/2017

Estimate Repair Cost to Vehicle No : SLN2276S

PAGE:2/2

S/N	Description	Quantity	Unit	Price	Amount
<u>SPECIAL NET</u>				<u>S\$</u>	<u>S\$</u>
18	Front Sport Rim - LH	1	PCS	720.00	720.00 X
TOTAL					720.00
<u>LABOUR CHARGES</u>				<u>S\$</u>	<u>S\$</u>
19	Towing				11 50.00 X
20	Panel Beating				850.00 480
21	Check Wiring				60.00 20
22	Rust Proofing				60.00 30
23	Alignment				50.00 ✓
24	To Remove & Replace Front Under Carriage				11 250.00 X
25	To Spray Painting				720.00 600
TOTAL					2040.00
OVERALL TOTAL					7295.88

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FOR FOCUS AUTO PTE LTD



AUTHORISE SIGNATURE

408272
22
3266