

Lkk Hsiao Tony

FASTECH AUTO PTE LTD
BLK 1 KAKI BUKIT AVE 6
#01-48 AUTOBAY
SINGAPORE 417883

Not Authorized
N/A
4/11/20
L/S \$3800
Hsiao

VEHICLE No: GBG 6586B

1PC	TAILGATE	2/3 out	1399.20	\$2,668.00	/
1PC	TAILGATE ,NISSAN, EMBLEM	neu		\$175.00	/
1PC	TAILGATE LOWER MEMBER	best		\$688.00	/
2PCS	TAILGATE LOCK LATCHES @215.00	neu		\$430.00	X
2PCS	TAILGATE HINGES \$50.00	n		\$100.00	X
2PCS	TAILGATE 'L' LOWER PANELS @145.00	n		\$290.00	X
2PCS	TAILGATE 'L' LOWER PANEL STOPPERS @121.00	n		\$242.00	X
2PCS	TAILLAMPS @208.00	neu		\$416	✓
2PCS	TAILLAMP BRACKERS @165.00	n		\$330.00	X
2PCS	DROP SIDEGATES @2998.00	n		\$5,996.00	X
2PCS	DROP SIDEGATE LOWER PANELS @981.00	n		\$1,962.00	X
1PC	REAR SPARE TYRE CHAIN & BRACKET	best/ neu	395.10	\$4,551.00	/
1PC	FRONT CABIN REAR PILLAR	n		\$799.00	X
1PC	CHASSIS FRAME N/S	n		\$3,800.00	X
				\$22,447.00	

S.NETT

1SET	70KM/H & 13PAX STICKER	neu		\$25.00	20
1SET	REAR REVERSE SENSOR	should		\$280.00	200
1SET	TAILGATE ALUMINIUM RIVET	neu		\$50.00	✓
1PC	REAR LICENCE PLATE	best		\$30.00	14
	TO CHECK WIRING			\$50.00	30
	TO DISMANTLE & REPLACING REVERSE SENSOR			\$80.00	50
	TO LIFT UP REAR CARGO DECK FOR REPAIR CHASSIS			\$880.00	X
	TO SPRAY RUST PROOFING			\$180.00	50
	LABOUR FOR PANEL BEATING & REPLACING PARTS			\$1,800.00	880
	TO PUTTY & SPRAY PAINTING			\$1,800.00	700
	TOTAL			\$27,622.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-307330
104
P-276597
S-N-284
L-1710
4759.97
38099