

Progressive Car Care Pte Ltd

Buk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@proccare.com.sg
GST: 201006949C RCB NO: 201006949C

M/S : PARANJOTHY CHARLES JOSEPH
22 EUNOS CRESCENT #12-3009
SINGAPORE 400022

ATTN: FIRST CAPITAL

Your Ref No: TP 1120-6129
Claim Type: Third Party
Accident Date: 01/11/2020
TP Veh Reg No: SHC 8487 R

Estimate No: EST1506359
Date: 02 Nov 2020
Policy No: 1900258471
Veh Reg No: SMJ3128P
Make/Model: HONDA FREED
HYBRID 7-SEATER 1.5G
AUTO
Chassis No: GB71080203
Engine No: LEB5616505
Reg. Date: 02/01/2019

Estimate Repair Cost to Vehicle No :SMJ3128P

Description	U/Price	Quantity	Price S\$	Amount S\$
List Price				
1 FRONT BUMPER	1,050.900	1 PC	1,050.90 <i>th</i>	
2 FRONT BUMPER SIDE HOLDER - RH/LH	25.0000	2 PC	<i>RHX</i> 50.00 <i>LH de</i>	
3 FRONT BUMPER CLIPS	3.9000	10 PC	39.00 <i>nei</i>	
4 FRONT BUMPER GRILLE	165.0000	1 PCS	165.00 <i>de</i>	
5 FRONT BUMPER GRILLE SIDE COVER - LH	89.4000	1 PCS	89.40 <i>x</i>	
6 FRONT GRILLE ASSY W/HONDA LOGO	750.9000	1 PC	750.90 <i>Cur</i>	
7 FRONT RIM - LH	956.0000	1 PCS	956.00 <i>?</i>	
8 FRONT HEADLAMP - LH	1,950.900	1 PC	1,950.90 <i>cur</i>	
9 FRONT HEADLAMP LOWER RETAINER - LH	40.8000	1 PC	40.80 <i>cur</i>	
10 BONNET	720.8000	1 PC	720.80 <i>bt</i>	
11 BONNET HINGE - LH/RH -	45.6000	2 PC <i>Hgh to</i>	91.20 <i>bt</i>	
12 FRONT FENDER - LH	440.6000	1 PC	440.60 <i>bt</i>	
13 FRONT FENDER COWLING - LH	121.6800	1 PC	121.68 <i>x</i>	
14 FRONT FENDER COWLING CLIPS - LH	3.9000	10 PCS	39.00 <i>x</i>	
15 FRONT FENDER 'HYBRID' LOGO - LH	65.6000	1 PCS	65.60 <i>nei</i>	
16 FRONT REINFORCEMENT	297.6000	1 PC	297.60 <i>bt</i>	
17 SUPPORT PANEL ASSY	752.6000	1 PCS	752.60 <i>x</i>	
18 SUPPORT PANEL TOP GARNISH CLIPS	3.9000	4 PCS	15.60 <i>x</i>	
19 AIRCON CONDENSER	985.0000	1 PCS	985.00 <i>x</i>	
20 RADIATOR	1,502.900	1 PC	1,502.90 <i>x</i>	
21 CAR BATTERY METAL BRACKET HOLDER	21.1000	1 PC	21.10 <i>x</i>	
22 FRONT WHEEL HOUSING PANEL - LH	360.7000	1 PC	360.70 <i>x</i>	
			10,507.28	
		Less 20%	2,101.46	8,405.82
Special Net				
23 FRONT NUMBER PLATE WITH CASING	45.0000	1 PC	45.00 <i>bt</i>	
24 FRONT TYRE - LH	200.0000	1 PCS	200.00 <i>?</i>	
25 RADIATOR COOLANT	30.0000	1 PCS	30.00 <i>x</i>	
26 QUARTER GLASS SEALANT	10.0000	.5 PCS	5.00 <i>x</i>	
			280.00	280.00
Labour				
27 TO REPLACE FRONT SUPPORT PANEL & REMOVE, REPLACE LH WHEELHOUSE & FENDER, INCLUDING AFFECTED ATTACHMENTS AND FITTINGS, CUT/WELD AND REALIGN	1,100.000	1 JOB	700.00 <i>700</i>	1,100.00 <i>600</i>

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
GST:201006949C RCB NO:201006949C

M/S : PARANJOTHY CHARLES JOSEPH
22 EUNOS CRESCENT #12-3009
SINGAPORE 400022

ATTN: FIRST CAPITAL

Your Ref No: TP 1120-6129
Claim Type: Third Party
Accident Date: 01/11/2020
TP Veh Reg No: SHC 8487 R

Estimate No: EST1506359
Date: 02 Nov 2020
Policy No: 1900258471
Veh Reg No: SMJ3128P
Make/Model: HONDA FREED
HYBRID 7-SEATER 1.5G
AUTO
Chassis No: GB71080203
Engine No: LEB5616505
Reg. Date: 02/01/2019

Estimate Repair Cost to Vehicle No :SMJ3128P

Description	U/Price	Quantity	Price	Amount
			SS	SS
28 TO CHECK FRONT WIRING, SOCKETS INCLUDING FOCUS OF HEADLAMP	50.0000	1 JOB	50.00	30.
29 TO RESPRAY PAINT ON ACCIDENT PORTIONS INCLUDING SUPPORT PANEL	900.0000	1 JOB	900.00	800
30 TO REMOVE, REPLACE RIM & REBALANCING	45.0000	1 JOB	45.00	30.
31 TO TUFF-KOTE	120.0000	1 JOB	120.00	30.
32 TO 4 WHEEL ALIGNMENT	80.0000	1 JOB	80.00	✓?
33 TO REMOVE, REPLACE CONDENSER & REFILL GAS	100.0000	1 JOB	100.00	X
34 TO DISMANTLE LH FENDER QUARTER GLASS TO FACILITATE REPLACEMENT OF FENDER	60.0000	1 JOB	60.00	X
35 TO RESET CHECK LIGHT	100.0000	1 JOB	100.00	
			2,555.00	2,555.00
Total			SS 11,240.82	
Add GST @ 7%			786.86	
Total Amount Payable			SS 12,027.68	

TOTAL: SINGAPORE DOLLAR TWELVE THOUSAND TWENTY SEVEN AND CENTS SIXTY EIGHT ONLY

Tanpin 97415744/67418134

'wp' 4/11/20 @ 4pm

Resurvey before paint

5 days
tanpin@lkkauto.com

* To check for LH rim type consistent to accident.

For Progressive Car Care Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: