




Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
GST:201006949C RCB NO:201006949C

PARANJOOTH CHARLES JOSEPH

22 EUNOS CRESCENT #12-3009
SINGAPORE 400022

ATTN: FIRST CAPITAL

Your Ref No: TP 1120-6129
Claim Type: Third Party
Accident Date: 01/11/2020
TP Veh Reg No: SHC 8487 R

PARTS 5112.72

SN 35.00

LAP 670.00

6817.72

Estimate No: EST1506359
Date: 02 Nov 2020
Policy No: 1900258471
Veh Reg No: SMJ3128P
Make/Model: HONDA FREED
HYBRID 7-SEATER 1.5G
AUTO
Chassis No: GB71080203
Engine No: LEB5616505
Reg. Date: 02/01/2019

Estimate Repair Cost to Vehicle No :SMJ3128P

Description	U/Price	Quantity	Price	Amount
List Price			SS	SS
1 FRONT BUMPER	1,050.900	1 PC	1,050.90	✓
2 FRONT BUMPER SIDE HOLDER - RH/LH	25.0000	2 PC	50.00	✓
3 FRONT BUMPER CLIPS	3.9000	10 PC	39.00	✓
4 FRONT BUMPER GRILLE	165.0000	1 PCS	165.00	✓
5 FRONT BUMPER GRILLE SIDE COVER - LH	89.4000	1 PCS	89.40	✓
6 FRONT GRILLE ASSY W/HONDA LOGO	750.9000	1 PC	750.90	✓
7 FRONT RIM - LH	956.0000	1 PCS	956.00	✓
8 FRONT HEADLAMP - LH	1,950.900	1 PC	1,950.90	✓
9 FRONT HEADLAMP LOWER RETAINER - LH	40.8000	1 PC	40.80	✓
10 BONNET	720.8000	1 PC	720.80	✓
11 BONNET HINGE - LH/RH -	45.6000	2 PC	91.20	✓
12 FRONT FENDER - LH	440.6000	1 PC	440.60	✓
13 FRONT FENDER COWLING - LH	121.6800	1 PC	121.68	✓
14 FRONT FENDER COWLING CLIPS - LH	3.9000	10 PCS	39.00	✓
15 FRONT FENDER 'HYBRID' LOGO - LH	65.6000	1 PCS	65.60	✓
16 FRONT REINFORCEMENT	297.6000	1 PC	297.60	✓
17 SUPPORT PANEL ASSY	752.6000	1 PCS	752.60	✓
18 SUPPORT PANEL TOP GARNISH CLIPS	3.9000	4 PCS	15.60	✓
19 AIRCON CONDENSER	985.0000	1 PCS	985.00	✓
20 RADIATOR	1,502.900	1 PC	1,502.90	✓
21 CAR BATTERY METAL BRACKET HOLDER	21.1000	1 PC	21.10	✓
22 FRONT WHEEL HOUSING PANEL - LH	360.7000	1 PC	360.70	✓
			10,507.28	
		Less 20%	2,101.46	
Special Net				
23 FRONT NUMBER PLATE WITH CASING	45.0000	1 PC	45.00	✓
24 FRONT TYRE - LH	200.0000	1 PCS	200.00	✓
25 RADIATOR COOLANT	30.0000	1 PCS	30.00	✓
26 QUARTER GLASS SEALANT	10.0000	.5 PCS	5.00	✓
			280.00	
Labour				
27 TO REPLACE FRONT SUPPORT PANEL & REMOVE, REPLACE LH WHEELHOUSE & FENDER, INCLUDING AFFECTED ATTACHMENTS AND FITTINGS, CUT/WELD AND REALIGN	1,100.000	1 JOB	1,100.00	✓

Steve
5/11/20

5112.72

35

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road I #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@proccare.com.sg
GST:201006949C RCB NO:201006949C

M/S : PARANJOTHY CHARLES JOSEPH
22 EUNOS CRESCENT #12-3009
SINGAPORE 400022

ATTN: FIRST CAPITAL

Your Ref No: TP 1120-6129
Claim Type: Third Party
Accident Date: 01/11/2020
TP Veh Reg No: SHC 8487 R

Estimate No: EST1506359
Date: 02 Nov 2020
Policy No: 1900258471
Veh Reg No: SMJ3128P
Make/Model: HONDA FREED
HYBRID 7-SEATER 1.5G
AUTO
Chassis No: GB71080203
Engine No: LEB5616505
Reg. Date: 02/01/2019

Estimate Repair Cost to Vehicle No :SMJ3128P

Description	U/Price	Quantity	Price	Amount
			SS	SS
28 TO CHECK FRONT WIRING, SOCKETS INCLUDING FOCUS OF HEADLAMP	50.0000	1 JOB	50.00	30. ✓
29 TO RESPRAY PAINT ON ACCIDENT PORTIONS INCLUDING SUPPORT PANEL	900.0000	1 JOB	900.00	800 ✓
30 TO REMOVE, REPLACE RIM & REBALANCING	45.0000	1 JOB	45.00	30. ✓
31 TO TUFF-KOTE	120.0000	1 JOB	120.00	30. ✓
32 TO 4 WHEEL ALIGNMENT	80.0000	1 JOB	80.00	40? ✓
33 TO REMOVE, REPLACE CONDENSER & REFILL GAS	100.0000	1 JOB	100.00	
34 TO DISMANTLE LH FENDER QUARTER GLASS TO FACILITATE REPLACEMENT OF FENDER	60.0000	1 JOB	60.00	
35 TO RESET CHECK LIGHT	100.0000	1 JOB	100.00	1670
			2,555.00	2,555.00
Total				S\$ 11,240.82
Add GST @ 7%				786.86
Total Amount Payable				S\$ 12,027.68

TOTAL: SINGAPORE DOLLAR TWELVE THOUSAND TWENTY SEVEN AND CENTS SIXTY EIGHT ONLY

Tanpin 97475744/67418134

wp' 4/11/20 @ 4pm

Respray before paint

5 days
tanpin@10hands.com

* To check for LH rim type consistent to accident.

Re fore spray Steve 6/11/20, 4.30pm

For Progressive Car Care Pte Ltd

AUTHORISED SIGNATURE