

ASS. REC. BY:

REF:

CC4/11120012070/ups3

ASSIGNMENT

From:

Date:

5/11/2020

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SMU 926P

at Workshop m/s

Borno Motor

of

17 Ubi Road 4

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

\$142k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

P

days

Res.: Yes or No

Lum Sum:

K.R.

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

"up"

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SMU 926P

Yr Regn:

8, 20

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CAI

Make:

Toyota previous Aeroc 2362

Colour

3/4ck

A/C: Insured / Std / NI / NA

Sp. Reading

4364

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTEGD 56M 907173884

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/55 R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

9

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

3/11/20

D.O.I.

5/11/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

27A 66405

24/1/20 confirmed r/p #16059.46 with Sam

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Photos

Others

TOTAL

Rep. Format:

Lump Sum / L.B. / C.

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Week-end (\$

S + RS. SI

Co Reg No : 196700086Z
 GST Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail		Account No		Customer Detail	
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept		S1000006 / ICIII1		Mr Julian Lim Jian Wei (Lin Jianwei) 14A Bedok Avenue Singapore 469918 Mobile: 91722958	
		Document No			
		0			
		Document Date			
		04/11/2020			

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	GFXSK E1	ACR50R	07/08/2020	SMU0926P	0	20457	67/TP/SMU0926P
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTEGD56M907173884	2AZ1B14576	60	Sam San Joi	04/11/2020 11.00	--/--/----	0.00	

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES TP CLAIM TP-SHC1574T ACC DATE:03/11/2020 DRIVE IN:04/11/2020 DATE-IN:04/11/2020 DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				30.00
2	S	PSP PER PANE LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION ON RH ACCIDENT AREAS				366.36
3	S	BP-SUBLET REPLACE SPORT RIM AND CONDUCT WHEEL BALANCING				72.00
4	Z	BP-SLANT SUPPLY SEALANT (NETT)- RH BOTH DOOR				120.00
5	B	BP-LAB2 CHECK LIGHTING & WIRING SYSTEM				122.40
6	B	BP-LAB2 TRANSFER & INSTALL COMPONENTS TO NEW DOOR				720.00
7	B	BP-LAB2 REMOVE & INSTALL CARPET, GARNISH AND TRIMMING TO ASSIST REPAIR				360.00
8	B	BP-LAB2 REMOVE & INSTALL REAR REVERSE SENSOR				180.00
9	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				180.00
10	B	BP-LAB2 REPLACE RH ACCIDENT DAMAGED PARTS STRAIGHTEN & ALIGN RH ACCIDENT AFFECTED AREAS				3600.00

not authorized
date 4/11/20
the price is very high.
no work
8 days

2520.

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

4216975

4216975

TO SECURITY GUARD

 PLEASE ALLOW THE UNDERMENTIONED
 VEHICLE TO LEAVE THE COMPANY PREMISES.

 DATE 04/11/2020
 TIME 13:32

Han: HSI AUTOM

VEHICLE NO SMU0926P

CUSTOMER

 SIGNATURE
 FOR BORNEO MOTORS (SINGAPORE) PTE LTD


Incharge

Borneo Motors



Borneo Motors (Singapore) Pte Ltd

Online Service Booking :

www.toyota.com.sg

Toyota Bodycare Centre

17 Ubi Road 4

Singapore 409611

Tel no.: 6631 1188

Co Reg No : 196700086Z
GST Reg No, : MR-8500000-9**ESTIMATE**

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail	Account No	Customer Detail
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept	S1000006/ICIII1	Mr Julian Lim Jian Wei (Lin Jianwei) 14A Bedok Avenue Singapore 469918 Mobile: 91722958
	Document No 0	
	Document Date 04/11/2020	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	GFXSK E1	ACR50R	07/08/2020	SMU0926P	0	20457	67/TP/SMU0926P
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTEGD56M907173884	2AZ1B14576	60	Sam San Joi	04/11/2020 11.00	--/--/----	0.00	

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
11	B	BP-RES2 S RESpray JOB ON RH ACCIDENT AFFECTED AREA	590	3540		4130.00
12	B	BP-MECH2 CONDUCT FULL WHEEL ALIGNMENT				180.00 ✓
13	1	T67001-28240 PANEL SUB-ASSY, FR	1.00	1718.70	✓	1718.70 ✓
14	2	T75955-28030 TAPE, BLACK OUT FR	1.00	43.80	✓	43.80 ✓
15	3	T75929-28020 TAPE, BLACK OUT FR	1.00	35.00	✓	35.00 ✓
16	4	T75957-28030 TAPE, BLACK OUT FR	1.00	52.30	✓	52.30 ✓
17	5	T75968-28020 TAPE, BLACK OUT FR	1.00	22.10	✓	22.10 ✓
18	6	T67861-28082 WEATHERSTRIP, FR	1.00	205.20	✓	205.20 ✓
19	7	T68710-12151 HINGE ASSY, FR DOOR,	1.00	97.50	✓	97.50 ✓
20	8	L68730-33021 HINGE ASSY, FR DOOR,	1.00	110.60	✓	110.60 ✓
21	9	T67003-28620 PANEL SUB-ASSY, RR	1.00	1741.90	✓	1741.90 ✓
22	0	T75931-28030 R/H SLIDE BLACK TAPE,	1.00	43.80	✓	43.80 ✓
23	1	T75933-28030 R/H SLIDE BLACK TAPE,	1.00	48.20	✓	48.20 ✓
24	2	T75951-28031 R/H SLIDE BLACK TAPE,	1.00	26.40	✓	26.40 ✓
25	3	T75937-28021 R/H SLIDE BLACK TAPE,	1.00	35.00	✓	35.00 ✓
26	4	T75953-28031 R/H SLIDE BLACK TAPE,	1.00	30.70	✓	30.70 ✓
27	5	T84250-28410 SENSOR ASSY, POWER	1.00	1285.20	✓	1285.20 ✓
28	6	T61411-28070 PANEL, ROCKER, OUTER	1.00	317.20	✓	317.20 ✓
29	7	T61601-28A71 PANEL SUB-ASSY,	1.00	990.00	✓	990.00 ✓

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Materials	
		Lubrication/Fluid	
		Others	
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

4216976

4216976

TO SECURITY GUARD

DATE 04/11/2020
TIME 13:32PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO SMU0926P

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Inchcape

Borneo Motors

CUSTOMER

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9**ESTIMATE**

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail		Account No	Customer Detail	
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept		S1000006 / ICI111	Mr Julian Lim Jian Wei (Lin Jianwei) 14A Bedok Avenue Singapore 469918 Mobile: 91722958	
		Document No		
		Document Date		
		0		
		04/11/2020		

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	GFXSK	E1	ACR50R	07/08/2020	SMU0926P	0	20457 67/TP/SMU0926P

Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On
JTEGD56M907173884	2AZ1B14576	60	Sam San Joi	04/11/2020 11.00	--/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
30	8	T52159-28959 COVER, RR BUMPER	1.00	596.90	X	596.90 X
31	9	S52161-0K040 CLIPS	10.00	4.10	X	41.00 X
32	0	T42611-28A20 WHEEL, DISC	1.00	2190.40	X	2190.40 X
33	1	T76903-28201 C1 Rear MUDGUARD SUB-ASSY, mas	1.00	1367.40	✓	1367.40 ✓
34	2	T76905-28140 C2 Rear MUDGUARD SUB-ASSY, mas	1.00	818.10	✓	818.10 ✓
35	3	T76931-28040 BRACKET, SIDE	1.00	8.10	✓	8.10 ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota at Borneo Motors within 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

Acknowledged by Repairer

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total	
	Please acknowledge receipt of vehicle	Parts	11,825.50	GST 7.00%
		Labour	9,622.40	
		Materials	438.36	
		Lubrication/Fluid	0.00	
		Others	0.00	
		Amount Due	23,418.30	

PLEASE TEAR ALONG PERFORATED LINE

4216977

4216977

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 04/11/2020
TIME 13:32

VEHICLE NO SMU0926P

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motors**

TAX INVOICE

Toyota Bodycare Centre
17 Ubi Road 4
Singapore 409611
Tel no.: 6631 1188

India International Insurance P L
64 Cecil Street
#06-02 IOB Building
Singapore 049711
Attn: Motor Claims Dept

S1000006/ICIIII1

39011248

23/11/2020

Mr Julian Lim Jian Wei (Lin Jianwei)
14A Bedok Avenue
Singapore 469918
Mobile: 91722958

19 GFXSK E1 ACR50R 07/08/2020 SMU0926P 4376 20457 67/TP/SMU0926P

JTEGD56M907173884 2AZ1B14576 60 Sam San Joi 04/11/2020 11.11 18/11/2020 13.12

1	Z	BP-SUNDRY	SUNDRIES	TP CLAIM		30.00
		TP-SHC1574T		ACC DATE:03/11/2020		
		DRIVE IN:04/11/2020				
		DATE-IN:04/11/2020		DATE SURVEY:05/11/2020		
		NO OF REPAIR DAYS:8		DAYS		
		BY:MARCUS (LKK)				
2	S	PSP PER PANE	LABOUR FOR PLATINUM SHINEPRO & SHINE	0619		366.36
		PER PANEL APPLICATION ON RH ACCIDENT AREAS				
3	S	BP-SUBLET	REPLACE RH REAR TYRE	0239	0.580	464.00 ✓
4	S	BP-SUBLET	SUPPLY SEALANT (NETT)- RH BOTH DOOR	0742	80%	120.00
5	S	BP-SUBLET	CHECK LIGHTING & WIRING SYSTEM	0742	cu7	122.40
6	S	BP-SUBLET	TRANSFER & INSTALL COMPONENTS TO NEW DOO	0742		720.00
		R				
7	S	BP-SUBLET	REMOVE & INSTALL CARPET,GARNISH AND TRIM	0742		360.00
		MING TO ASSIST REPAIR				
8	S	BP-SUBLET	REMOVE & INSTALL REAR REVERSE SENSOR	0742		180.00
9	S	BP-SUBLET	TO RESET ECU AND REPROGRAMME	0742		180.00
10	S	BP-SUBLET	REPLACE RH ACCIDENT DAMAGED PARTS	0742		2520.00
		STRAIGHTEN & ALIGN RH ACCIDENT AFFECTED AREAS				

PLEASE MAIL YOUR CHEQUE TO 2 PANDAN CRESCENT, LEVEL 10 INCHCAPE CENTRE, SINGAPORE 128462

23/11/2020
09:08

SMU0926P

TAX INVOICE

Toyota Bodycare Centre
17 Ubi Road 4
Singapore 409611
Tel no.: 6631 1188

India International Insurance P L
64 Cecil Street
#06-02 IOB Building
Singapore 049711
Attn: Motor Claims Dept

S1000006/ICIII1

39011248

23/11/2020

Mr Julian Lim Jian Wei (Lin Jianwei)
14A Bedok Avenue
Singapore 469918
Mobile: 91722958

19 GFXSK E1 ACR50R 07/08/2020 SMU0926P 4376 20457 67/TP/SMU0926P

JTEGD56M907173884 2AZ1B14576 60 Sam San Joi 04/11/2020 11.11 18/11/2020 13.12

11	S	BP-SUBLET S	RESPRAY JOB ON RH ACCIDENT AFFECTED AREA 0742				3540.00
12	S	BP-SUBLET	CONDUCT FULL WHEEL ALIGNMENT	0742			180.00
13	1	T67001-28240	PANEL ASSY, FR RH AERAS	1.00	1718.70		1718.70
14	2	T75955-28030	TAPE, BLACK OUT FR	1.00	43.80		43.80
15	3	T75929-28020	TAPE, BLACK OUT FR	1.00	35.00		35.00
16	4	T75957-28030	TAPE, BLACK OUT FR	1.00	52.30		52.30
17	5	T75968-28020	TAPE, BLACK OUT FR	1.00	22.10		22.10
18	6	T67003-28620	PANEL SUB-ASSY, RR AERAS	1.00	1741.90		1741.90
19	7	T75931-28030	TAPE, BLACK OUT	1.00	43.80		43.80
20	8	T75933-28030	TAPE, BLACK OUT	1.00	48.20		48.20
21	9	T75951-28031	TAPE, BLACK OUT	1.00	26.40		26.40
22	0	T75937-28021	TAPE, BLACK OUT	1.00	35.00		35.00
23	1	T75953-28031	TAPE, BLACK OUT	1.00	30.70		30.70
24	2	T84250-28410	SENSOR ASSY, POWER	1.00	1285.20		1285.20
25	3	T76903-28201 C1	MUDGUARD SUB-ASSY,	1.00	1367.40		1367.40
26	4	T76905-28140 C2	MUDGUARD SUB-ASSY,	1.00	818.10		818.10
27	5	T76931-28040	BRACKET, SIDE	1.00	8.10		8.10

			16,059.46
7,276.70	GST 7.00%		1,124.16
30.00			
8,752.76			0.00
0.00			
0.00			
			17,183.62

PLEASE MAIL YOUR CHEQUE TO 2 PANDAN CRESCENT, LEVEL 10 INCHCAPE CENTRE, SINGAPORE 128462

23/11/2020
09:08

SMU0926P

TAX INVOICE

Toyota Bodycare Centre
17 Ubi Road 4
Singapore 409611
Tel no.: 6631 1188

India International Insurance P L
64 Cecil Street
#06-02 IOB Building
Singapore 049711
Attn: Motor Claims Dept

S1000006/ICIIII

39011241

18/11/2020

Mr Julian Lim Jian Wei (Lin Jianwei)
14A Bedok Avenue
Singapore 469918
Mobile: 91722958

19 GFXSK E1 ACR50R 07/08/2020 SMU0926P 4376 20457 67/TP/SMU0926P

JTEGD56M907173884 2AZ1B14576 60 Sam San Joi 04/11/2020 11.11 18/11/2020 13.12

1	Z	BP-SUNDRY	SUNDRIES	TP CLAIM		30.00
		TP-SHC1574T		ACC DATE:03/11/2020		
		DRIVE IN:04/11/2020				
		DATE-IN:04/11/2020		DATE SURVEY:05/11/2020		
		NO OF REPAIR DAYS:8		DAYS		
		BY:MARCUS (LKK)				
2	S	PSP PER PANE	LABOUR FOR PLATINUM SHINEPRO & SHINE	0619		366.36
		PER PANEL APPLICATION ON RH ACCIDENT AREAS				
3	S	BP-SUBLET	REPLACE RH REAR TYRE	0239		580.00
4	S	BP-SUBLET	SUPPLY SEALANT (NETT)- RH BOTH DOOR	0742		120.00
5	S	BP-SUBLET	CHECK LIGHTING & WIRING SYSTEM	0742		122.40
6	S	BP-SUBLET	TRANSFER & INSTALL COMPONENTS TO NEW DOO	0742		720.00
		R				
7	S	BP-SUBLET	REMOVE & INSTALL CARPET,GARNISH AND TRIM	0742		360.00
		MING TO ASSIST REPAIR				
8	S	BP-SUBLET	REMOVE & INSTALL REAR REVERSE SENSOR	0742		180.00
9	S	BP-SUBLET	TO RESET ECU AND REPROGRAMME	0742		180.00
10	S	BP-SUBLET	REPLACE RH ACCIDENT DAMAGED PARTS	0742		2520.00
		STRAIGHTEN & ALIGN RH ACCIDENT AFFECTED AREAS				

PLEASE MAIL YOUR CHEQUE TO 2 PANDAN CRESCENT, LEVEL 10 INCHCAPE CENTRE, SINGAPORE 128462

18/11/2020
13:13

SMU0926P

TAX INVOICE

Toyota Bodycare Centre
17 Ubi Road 4
Singapore 409611
Tel no.: 6631 1188

India International Insurance P L
64 Cecil Street
#06-02 IOB Building
Singapore 049711
Attn: Motor Claims Dept

S1000006/ICIIII

39011241

18/11/2020

Mr Julian Lim Jian Wei (Lin Jianwei)
14A Bedok Avenue
Singapore 469918
Mobile: 91722958

19 GFXSK EI ACR50R 07/08/2020 SMU0926P 4376 20457 67/TP/SMU0926P

JTEGD56M907173884 2AZ1B14576 60 Sam San Joi 04/11/2020 11.11 18/11/2020 13.12

11	S	BP-SUBLET	RESPRAY JOB ON RH ACCIDENT AFFECTED AREA 0742				3540.00
12	S	BP-SUBLET	CONDUCT FULL WHEEL ALIGNMENT	0742			180.00
13	1	T67001-28240	PANEL ASSY,FR RH AERAS		1.00	1718.70	1718.70
14	2	T75955-28030	TAPE,BLACK OUT FR		1.00	43.80	43.80
15	3	T75929-28020	TAPE,BLACK OUT FR		1.00	35.00	35.00
16	4	T75957-28030	TAPE,BLACK OUT FR		1.00	52.30	52.30
17	5	T75968-28020	TAPE,BLACK OUT FR		1.00	22.10	22.10
18	6	T67003-28620	PANEL SUB-ASSY, RR AERAS		1.00	1741.90	1741.90
19	7	T75931-28030	TAPE,BLACK OUT		1.00	43.80	43.80
20	8	T75933-28030	TAPE,BLACK OUT		1.00	48.20	48.20
21	9	T75951-28031	TAPE,BLACK OUT		1.00	26.40	26.40
22	0	T75937-28021	TAPE,BLACK OUT		1.00	35.00	35.00
23	1	T75953-28031	TAPE,BLACK OUT		1.00	30.70	30.70
24	2	T84250-28410	SENSOR ASSY, POWER		1.00	1285.20	1285.20
25	3	T76903-28201 C1	MUDGUARD SUB-ASSY,		1.00	1367.40	1367.40
26	4	T76905-28140 C2	MUDGUARD SUB-ASSY,		1.00	818.10	818.10
27	5	T76931-28040	BRACKET, SIDE		1.00	8.10	8.10

			16,175.46
7,276.70	GST 7.00%		1,132.28
30.00			
8,868.76			0.00
0.00			
0.00			
			17,307.74

PLEASE MAIL YOUR CHEQUE TO 2 PANDAN CRESCENT, LEVEL 10 INCHCAPE CENTRE, SINGAPORE 128462

18/11/2020
13:13

SMU0926P