



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyota.com.sg

Toyota Bodycare Centre
17 Ubi Road 4
Singapore 409611
Tel no: 6631 1188

Account Detail	Account No	Customer Detail
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept	S1000006 / IC1111	
	Document No	
	0	Mr Julian Lim Jian Wei (Lin Jianwei) 14A Bedok Avenue Singapore 469918 Mobile: 91722958
	Document Date	
	04/11/2020	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	GFXSK	E1	07/08/2020	SMU0926P	0	20457	67/TP/SMU0926P
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTEGD56M907173884	2AZ1B14576	60	Sam San Joi	04/11/2020 11.00	--/--/----	0.00	

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES TP CLAIM TP-SHC1574T ACC DATE:03/11/2020 DRIVE IN:04/11/2020 DATE-IN:04/11/2020 DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				30.00
2	S	PSP PER PANE LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION ON RH ACCIDENT AREAS				366.36
3	S	BP-SUBLET REPLACE SPORT RIM AND CONDUCT WHEEL BALANCING				72.00
4	Z	BP-SLANT SUPPLY SEALANT (NETT) - RH BOTH DOOR				120.00
5	B	BP-LAB2 CHECK LIGHTING & WIRING SYSTEM				122.40
6	B	BP-LAB2 TRANSFER & INSTALL COMPONENTS TO NEW DOOR				720.00
7	B	BP-LAB2 REMOVE & INSTALL CARPET, GARNISH AND TRIM MING TO ASSIST REPAIR				360.00
8	B	BP-LAB2 REMOVE & INSTALL REAR REVERSE SENSOR				180.00
9	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				180.00
10	B	BP-LAB2 REPLACE RH ACCIDENT DAMAGED PARTS STRAIGHTEN & ALIGN RH ACCIDENT AFFECTED AREAS				3600.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

4216975

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 04/11/2020
TIME 13:32

Man: HSIAUTONG

4216975

VEHICLE NO SMU0926P

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Inchcape



Borneo Motors (Singapore) Pte Ltd

Online Service Booking:

www.toyota.com.sg

Toyota Bodycare Centre

17 Ubi Road 4

Singapore 409611

Tel no.: 6631 1188

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9**ESTIMATE**

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail	Account No	Customer Detail
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept	S1000006 / ICIII1	Mr Julian Lim Jian Wei (Lin Jianwei) 14A Bedok Avenue Singapore 469918 Mobile: 91722958
	Document No 0	
	Document Date 04/11/2020	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	GFXSK E1	ACR50R	07/08/2020	SMU0926P	0	20457	67/TP/SMU0926P
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTEGD56M907173884	2AZ1B14576	60	Sam San Joi	04/11/2020 11.00	--/--/----	0.00	

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
11	B	BP-RES2 S RESPRAY JOB ON RH ACCIDENT AFFECTED AREA	1.00	3540		4130.00
12	B	BP-MECH2 CONDUCT FULL WHEEL ALIGNMENT				180.00 ✓
13	1	T67001-28240 PANEL SUB-ASSY, FR	1.00	1718.70		1718.70
14	2	T75955-28030 TAPE, BLACK OUT FR	1.00	43.80		43.80
15	3	T75929-28020 TAPE, BLACK OUT FR	1.00	35.00		35.00
16	4	T75957-28030 TAPE, BLACK OUT FR	1.00	52.30		52.30
17	5	T75968-28020 TAPE, BLACK OUT FR	1.00	22.10		22.10
18	6	T67861-28082 WEATHERSTRIP, FR	1.00	205.20		205.20
19	7	T68710-12151 HINGE ASSY, FR DOOR,	1.00	97.50		97.50
20	8	L68730-33021 HINGE ASSY, FR DOOR,	1.00	110.60		110.60
21	9	T67003-28620 PANEL SUB-ASSY, RR	1.00	1741.90		1741.90
22	0	T75931-28030 R/H SLIDE BLACK TAPE,	1.00	43.80		43.80
23	1	T75933-28030 R/H SLIDE BLACK TAPE,	1.00	48.20		48.20
24	2	T75951-28031 R/H SLIDE BLACK TAPE,	1.00	26.40		26.40
25	3	T75937-28021 R/H SLIDE BLACK TAPE,	1.00	35.00		35.00
26	4	T75953-28031 R/H SLIDE BLACK TAPE,	1.00	30.70		30.70
27	5	T84250-28410 SENSOR ASSY, POWER	1.00	1285.20		1285.20
28	6	T61411-28070 PANEL, ROCKER, OUTER	1.00	317.20		317.20
29	7	T61601-28A71 PANEL SUB-ASSY,	1.00	990.00		990.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	
		Labour	
		Materials	
		Lubrication/Fluid	
		Others	
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

4216976

TO SECURITY GUARD

4216976

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 04/11/2020
TIME 13:32

VEHICLE NO SMU0926P

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motors**



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking:
www.toyota.com.sg
Toyota Bodycare Centre
17 Ubi Road 4
Singapore 409611
Tel no.: 6631 1188

Account Detail	Account No	Customer Detail
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept	S1000006/ICIII1 Document No 0 Document Date 04/11/2020	Mr Julian Lim Jian Wei (Lin Jianwei) 14A Bedok Avenue Singapore 469918 Mobile: 91722958

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	GFXSK	E1	07/08/2020	SMU0926P	0	20457	67/TP/SMU0926P
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTEGD56M907173884	2AZ1B14576	60	Sam San Joi	04/11/2020 11.00	--/--/----	0.00	

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
30	8	T52159-28959 COVER, RR BUMPER	1.00	596.90		596.90
31	9	S52161-OK040 CLIPS	10.00	4.10		41.00
32	0	T42611-28A20 WHEEL, DISC	1.00	2190.40		2190.40
33	1	T76903-28201 C1 MUDGUARD SUB-ASSY, rear	1.00	1367.40		1367.40
34	2	T76905-28140 C2 MUDGUARD SUB-ASSY, front	1.00	818.10		818.10
35	3	T76931-28040 BRACKET, SIDE	1.00	8.10		8.10

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota at Borneo Motors to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts 11,825.50 Labour 9,622.40 Materials 438.36 Lubrication/Fluid 0.00 Others 0.00	21,886.26
		GST 7.00%	1,532.04
		Less	0.00
		Amount Due	23,418.30

PLEASE TEAR ALONG PERFORATED LINE

4216977

4216977

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 04/11/2020
TIME 13:32

VEHICLE NO SMU0926P

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors