

Reg No : 196700086Z
 ST Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Online Service Booking :

www.toyota.com.sg

Toyota Bodycare Centre

17 Ubi Road 4

Singapore 409611

Tel no. : 6631 1188

Account Detail		Account No	Customer Detail	
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept		S1000006/ICIIII1	Mr Julian Lim Jian Wei (Lin Jianwei) 14A Bedok Avenue Singapore 469918 Mobile: 91722958	
		Document No		
		0		
		Document Date		
		04/11/2020		

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	GFXSK E1	ACR50R	07/08/2020	SMU0926P	0	20457	67/TP/SMU0926P
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTEGD56M907173884	2AZ1B14576	60	Sam San Joi	04/11/2020 11.00	--/--/----	0.00	

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES TP CLAIM TP-SHC1574T ACC DATE:03/11/2020 DRIVE IN:04/11/2020 DATE-IN:04/11/2020 DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				30.00
2	S	PSP PER PANE LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION ON RH ACCIDENT AREAS				366.36
3	S	BP-SUBLET REPLACE SPORT RIM AND CONDUCT WHEEL BALANCING				72.00
4	Z	BP-SLANT SUPPLY SEALANT (NETT)- RH BOTH DOOR				120.00
5	B	BP-LAB2 CHECK LIGHTING & WIRING SYSTEM				122.40
6	B	BP-LAB2 TRANSFER & INSTALL COMPONENTS TO NEW DOOR				720.00
7	B	BP-LAB2 REMOVE & INSTALL CARPET, GARNISH AND TRIMMING TO ASSIST REPAIR				360.00
8	B	BP-LAB2 REMOVE & INSTALL REAR REVERSE SENSOR				180.00
9	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				180.00
10	B	BP-LAB2 REPLACE RH ACCIDENT DAMAGED PARTS STRAIGHTEN & ALIGN RH ACCIDENT AFFECTED AREAS				3600.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

4216975

TO SECURITY GUARD

4216975

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 04/11/2020
 TIME 13:32

VEHICLE NO SMU0926P

SIGNATURE
 FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Inchcape

CUSTOMER

Reg No : 196700086Z
 ST Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail		Account No	Customer Detail	
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept		S1000006 / ICIII1	Mr Julian Lim Jian Wei (Lin Jianwei) 14A Bedok Avenue Singapore 469918 Mobile: 91722958	
		Document No		
		0		
		Document Date		
		04/11/2020		

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	GFXSK	E1	07/08/2020	SMU0926P	0	20457	67/TP/SMU0926P
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTEGD56M907173884	2AZ1B14576	60	Sam San Joi	04/11/2020 11.00	--/--/----	0.00	

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
11	B	BP-RES2 RESPRAY JOB ON RH ACCIDENT AFFECTED AREA				4130.00
		S				
12	B	BP-MECH2 CONDUCT FULL WHEEL ALIGNMENT				180.00
13	1	T67001-28240 PANEL SUB-ASSY, FR	1.00	1718.70		1718.70
14	2	T75955-28030 TAPE, BLACK OUT FR	1.00	43.80		43.80
15	3	T75929-28020 TAPE, BLACK OUT FR	1.00	35.00		35.00
16	4	T75957-28030 TAPE, BLACK OUT FR	1.00	52.30		52.30
17	5	T75968-28020 TAPE, BLACK OUT FR	1.00	22.10		22.10
18	6	T67861-28082 WEATHERSTRIP, FR	1.00	205.20		205.20
19	7	T68710-12151 HINGE ASSY, FR DOOR,	1.00	97.50		97.50
20	8	L68730-33021 HINGE ASSY, FR DOOR,	1.00	110.60		110.60
21	9	T67003-28620 PANEL SUB-ASSY, RR	1.00	1741.90		1741.90
22	0	T75931-28030 R/H SLIDE BLACK TAPE,	1.00	43.80		43.80
23	1	T75933-28030 R/H SLIDE BLACK TAPE,	1.00	48.20		48.20
24	2	T75951-28031 R/H SLIDE BLACK TAPE,	1.00	26.40		26.40
25	3	T75937-28021 R/H SLIDE BLACK TAPE,	1.00	35.00		35.00
26	4	T75953-28031 R/H SLIDE BLACK TAPE,	1.00	30.70		30.70
27	5	T84250-28410 SENSOR ASSY, POWER	1.00	1285.20		1285.20
28	6	T61411-28070 PANEL, ROCKER, OUTER	1.00	317.20		317.20
29	7	T61601-28A71 PANEL SUB-ASSY,	1.00	990.00		990.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

4216976

TO SECURITY GUARD

4216976

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 04/11/2020
 TIME 13:32

VEHICLE NO SMU0926P

SIGNATURE
 FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Inchcape

CUSTOMER

Co Reg No : 196700086Z
ST Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail		Account No	Customer Detail	
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept		S1000006 / ICIIII1	Mr Julian Lim Jian Wei (Lin Jianwei) 14A Bedok Avenue Singapore 469918 Mobile: 91722958	
		Document No		
		0		
		Document Date		
		04/11/2020		

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	GFXSK E1	ACR50R	07/08/2020	SMU0926P	0	20457	67/TP/SMU0926P
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTEGD56M907173884	2AZ1B14576	60	Sam San Joi	04/11/2020 11.00	--/--/----	0.00	

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
30	8	T52159-28959 COVER, RR BUMPER	1.00	596.90		596.90
31	9	S52161-OK040 CLIPS	10.00	4.10		41.00
32	0	T42611-28A20 WHEEL, DISC	1.00	2190.40		2190.40
33	1	T76903-28201 C1 MUDGUARD SUB-ASSY,	1.00	1367.40		1367.40
34	2	T76905-28140 C2 MUDGUARD SUB-ASSY,	1.00	818.10		818.10
35	3	T76931-28040 BRACKET, SIDE	1.00	8.10		8.10
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts 11,825.50	21,886.26
		Labour 9,622.40	GST 7.00% 1,532.04
		Materials 438.36	Less 0.00
		Lubrication/Fluid 0.00	
		Others 0.00	Amount Due 23,418.30

PLEASE TEAR ALONG PERFORATED LINE

4216977

TO SECURITY GUARD

4216977

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 04/11/2020
TIME 13:32

VEHICLE NO SMU0926P

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD


Borneo Motors

Inchcape