

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

SHO YEE HENG

BLK 412 TAMPINES ST 41

#12-271.S 520412

S 760803

TP III

Xiao Tony

Vehicle No

:SLE 2979 U

Make/Model

:HONDA VEZEL

Accident date

:02.11.2020

No	DESCRIPTION	Qty	Amount (\$\$)
<u>List Items</u>			
1	Front bumper <i>Repis</i>	1	\$ 506.00 <i>x</i>
2	Front bumper side holder <i>new</i>	2	\$ 34.00 <i>x</i>
3	Front bumper lower lip <i>cut</i>	1	\$ 215.20 <i>✓</i>
4	Front LH fender <i>Repis</i>	1	\$ 434.50 <i>x</i>
5	Front LH fender side garnish <i>cut</i>	1	\$ 198.00 <i>✓</i>
6	Front LH door <i>Dented</i>	2	\$ 927.10 <i>✓</i>
7	Front LH door glass outer moulding <i>new</i>	1	\$ 66.00 <i>x</i>
8	Front LH door sun <i>rise</i> <i>Ne</i>	1	\$ 110.00 <i>60(SN)</i>
9	Front LH door frame black sticker (1 set) <i>Nec</i>	1	\$ 28.90 <i>✓</i>
10	Front LH door side mirror assy <i>changed</i>	1	\$ 803.00 <i>✓</i>
11	Front LH shock absorber <i>Best</i>	1	\$ 473.20 <i>✓</i>
12	Front LH knuckle arm <i>and</i>	1	\$ 274.70 <i>✓</i>
13	Front LH knuckle arm bearing <i>new</i>	2	\$ 149.10 <i>✓</i>
14	Front LH lower arm <i>cut</i>	1	\$ 385.00 <i>✓</i>
15	Front LH linkage	1	\$ 66.00 <i>x</i>
16	Front LH drive shaft <i>new</i>	2	\$ 1210.00 <i>x</i>
17	Steering rack	2	\$ 1289.70 <i>x</i>
18	LH rocker panel garnish <i>cut</i>	2	\$ 415.30 <i>✓</i>
19	Rear LH door <i>Repis</i>	1	\$ 968.10 <i>x</i>
20	Rear LH door glass outer moulding	1	\$ 71.50 <i>x</i>
21	Rear LH door frame black sticker (1 set) <i>new</i>	1	\$ 30.50 <i>x</i>
22	Rear LH door sun rise <i>new</i>	2	\$ 110.00 <i>x</i>
23	Rear LH door side rubber <i>new</i>	1	\$ 44.50 <i>x</i>
24	Rear LH fender <i>Repis</i>	1	\$ 602.40 <i>x</i>
25	Rear LH fender side garnish <i>cut</i>	1	\$ 310.00 <i>182.80</i>
26	Rear LH shock absorber <i>new</i>	1	\$ 363.00 <i>x</i>
27	Rear LH knuckle arm <i>new</i>	1	\$ 1664.50 <i>x</i>
28	Rear LH knuckle arm bearing <i>new</i>	2	\$ 345.40 <i>x</i>
29	Rear axle <i>new</i>	1	\$ 1664.30 <i>x</i>
			\$ 13759.90
Less 20% Disc			\$ 2751.98
Total			\$ 11007.92

4062.30

3249.84

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

SHO YEE HENG
BLK 412 TAMPINES ST 41
#12-271.S 520412
S 760803

Vehicle No :SLE 2979 U
Make/Model :HONDA VEZEL
Accident date :02.11.2020

No	DESCRIPTION	Qty	Amount (\$\$)
----	-------------	-----	---------------

Special Nett Items

1	Front LH tyre <i>new</i>	1	\$ 350.00 <i>x</i>
2	Front LH sport rim <i>lt</i>	1	\$ 850.00 <i>400</i>
3	Rear LH tyre <i>new</i>	1	\$ 350.00 <i>x</i>
4	Rear LH sport rim <i>lt</i>	1	\$ 850.00 <i>400</i>
Total			\$ 2400.00

Labour Cost

1	To check wheel alignment	\$ 100.00 <i>80</i>
2	Remove & reinstall door glass <i>hitings</i>	\$ 150.00 <i>80</i>
3	Remove & reinstall front and rear suspension	\$ 600.00 <i>220</i>
4	Remove ,replace & repair consistent to the accident	\$ 1400.00 <i>500</i>
5	Respray painting	\$ 1300.00 <i>80</i>
6	Tuff kote	\$ 150.00 <i>40</i>
Total		\$ 3700.00

Grand Total \$ 17107.92

total: 5769.84

1/8: 46K

05 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: