

 PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0827/2020/NS
DATE : 2-Nov-20
WIP : 55212

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT**TEL: 6841 0055 - FAX: 6256 4315**

OWNER'S NAME : MR GERARD TAN YAU BOON
(GERARD CHEN YAOWEN)
ADDRESS : 82 JALAN DAUD
#08-04
SINGAPORE 419592
TELEPHONE : HP +65 98365263
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900155348
VEHICLE NO : **SMN 8785 M**
MODEL CODE : AUDI A4 SEDAN 2.0 TFSI 8W
MODEL YEAR : 30/8/2019
ENGINE NO : CVK 084102
CHASSIS NO : WAUZZZF41KA086571
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 30-Oct-20
PLACE OF ACCIDENT : PIE NEAR TOA PAYOH LOR 6 EXIT



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMN 8785 M

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 280.00 ✓	
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT CONTROL UNITS AND POWER MODULES.	S/N \$ 700.00 350 500	
3	TO DISMANTLE AND REINSTALL BOTH FRONT DOOR PANEL TRIMS. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSYS. <i>LH only.</i>	S/N \$ 700.00 280	
4	TO REMOVE AND REINSTALL AIRCON CONDENSER, CHARGED AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,200.00 ✓	
5	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHTS. TO REPAIR BOTH FRONT FENDERS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. ✓ ✓	\$ 4,900.00 1000 (Without Lock Carrier) 2250 (With Lock Carrier)	
6	TO RESPRAY FRONT BUMPER, BONNET, HINGES, BOTH FRONT FENDERS AND BOTH FRONT DOORS. <i>LH only.</i>	\$ 5,500.00 1650	
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 13,472.00	



PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMN 8785 M

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1 FRONT BUMPER <i>Dented</i>	\$	2,171.00	✓ 1736.80
2 FRONT BUMPER FIXING PARTS <i>new</i>	\$	580.00	+
3 FRONT BUMPER SECURING STRIP <i>Not Nec.</i>	2 \$	70.00	X
4 FRONT BUMPER GRILLE - CENTRE <i>cracked</i>	\$	194.00	✓ 154.80
5 FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>Not torn</i>	\$	208.00	✓ 166.00
6 RADIATOR GRILLE <i>cracked</i>	\$	1,317.00	✓ 1053.60
7 FRONT BUMPER AIR GUIDE GRILLE - LH/RH <i>new</i>	2 \$	268.00	+
8 FRONT BUMPER CARRIER <i>Bent.</i>	\$	795.00	✓ 635.60
9 FRONT BUMPER FOAM FILLER PIECE <i>Not nec</i>	\$	123.00	X
10 FRONT BUMPER TOP COVER <i>cracked</i>	\$	126.00	✓ 100.40
11 CAUTION SIGN STICKER <i>Not nec</i>	NEC \$	14.00	X
12 AIRCON STICKER <i>Not nec</i>	NEC \$	8.00	X
13 LOCK CARRIER BRACKET <i>cracked</i>	\$	136.00	✓ 108.40
14 LOCK CARRIER BRACKET SUPPORT - LH/RH <i>Damaged.</i>	2 \$	56.00	✓ 44.48
15 HORN - LH HIGH TONE	\$	124.00	+
16 HORN - RH LOW TONE <i>new</i>	\$	124.00	+
17 SPRING SHACKLE - LH/RH <i>new</i>	2 \$	58.00	+
18 FRONT PARKING AID SENSOR - INNER/OUTER <i>new</i>	2 \$	484.00	+
19 BONNET <i>Dented</i>	\$	2,763.00	✓ 2210.40
20 BONNET ATTACHMENT PARTS <i>new</i>	\$	408.00	X
SUB TOTAL SPARE PARTS	:	\$ 10,027.00	



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMN 8785 M

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
21 BONNET LID HINGE - LH/RH <i>Nec Nec</i>	2	\$ 602.00	X
22 BONNET IMPACT PROTECTION - CENTRE <i>2</i>		\$ 27.00	✓ 21.52
23 BONNET IMPACT PROTECTION - LH <i>1</i>		\$ 28.00	✓ 21.84
24 BONNET IMPACT PROTECTION - RH		\$ 27.00	✓ 21.52
25 BONNET STRIKER - LH/RH <i>Nec Nec</i>	2	\$ 100.00	X
26 BONNET LID LOCK <i>Nec Nec</i>	2	\$ 423.00	X
27 BONNET LOCK CABLE - CENTRE <i>Damaged</i>		\$ 57.00	2 ✓ 45.52
28 BONNET RELEASE CABLE <i>{ Nec Nec</i>		\$ 57.00	X
29 BONNET RELEASE LEVER <i>{</i>		\$ 13.00	X
30 LED HEADLIGHT - LH/RH <i>LH, RH cracked</i>	2	\$ 15,386.00	✓ 6154.40
31 LIFT CYLINDER - LH/RH <i>Nec</i>	2	\$ 416.00	X
32 LIFT CYLINDER CORRUGATED PIPE <i>Nec</i>		\$ 92.00	X
33 LOCK CARRIER <i>cracked</i>		\$ 1,004.00	2 ✓ 803.20
34 AIRCON CONDENSER <i>Dented</i>		\$ 615.00	2 ✓ 492.00
35 TEMPERATURE SENSOR BRACKET <i>cracked</i>		\$ 18.00	2 ✓ 14.40
36 READY MIX COOLANT <i>Nec</i>		\$ 177.00	2 ✓ 141.44
37 RADIATOR AIR GUIDE - LH/RH OUTER <i>RH cracked</i>	2	\$ 56.00	2 ✓ 22.08
38 RADIATOR AIR GUIDE - LH/RH INNER <i>RH cracked</i>	2	\$ 24.00	2 ✓ 9.36
39 RADIATOR AIR GUIDE - UPPER <i>Nec</i>		\$ 16.00	X
40 WINDOW SLOT SEAL - LH/RH <i>Nec</i>	2	\$ 606.00	X
41 FRONT NO PLATE <i>Dented</i>	S/N	\$ 60.00	✓ 60.00
42 SUNDRIES <i>Nec</i>		\$ 300.00	2 ✓ 18.72
TOTAL SPARE PARTS	:	\$ 30,131.00	
TOTAL LABOUR CHARGES	:	\$ 13,472.00	
GRAND TOTAL	:	\$ 43,603.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

: Adnan

SURVEYED DATE

: 04/11/22

AUTHORISED DATE

:

EXCESS COST

:

LIABILITY

:

REMARKS

:

Not Authorised 05 days (without lock carrier)
108 days (with lock carrier)

PLEASE NOTE

:

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,

PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT