

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 15:53

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120		Invoice No: 85016162	Account: A0006 (T 0)	
		Date : 08/04/2021	AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120	
		Order : SMN8785M		
		Term : 30		

Regn No: SMN8785M (V 42824)	Regn Date: 30/08/2019	Mileage: 12419	WIP No.: 55212
Model: A4 SEDAN 2.0 TFSI 8W2ADG	Chassis: WAUZZZF41KA086571	Engine: CVK 084102	Dept: U
You have been assisted by :- UB-Tony Foong (33)			

		Details	Qty	Unit Price	Amount
Q	EXC	M: 8888	-550.00	1.00	-550.00
S	SUBLET	Insurance Excess/Liability	60.00	1.00	60.00
S	BODYWORK	M: BNP - TO SUPPLY VEHICLE NUMBER PLATE	280.00	1.00	280.00
S	BODYWORK	M: TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	500.00	1.00	500.00
S	BODYWORK	M: TO REMOVE AND TRANSFER BOTH HEADLIGHT CONTROL UNIT AND POWER MODULES.	280.00	1.00	280.00
S	BODYWORK	M: TO DISMANTLE AND REINSTALL BOTH FRONT DOOR PANEL TRIMS.TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY.	1200.00	1.00	1,200.00
S	BODYWORK	M: TO REMOVE AND REINSTALL AIRCON CONDENSER, CHARGED AIR COOLER AND RADIATOR.CHECK ELECTRICAL FANS AND CONTROL UNIT.PRESSURISE COOLING SYSTEM.TO CARRY OUT VACUUM AND REGAS.	2250.00	1.00	2,250.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER AND BONNET.TO REPAIR BOTH FRONT FENDER. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION.REORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED.	1650.00	1.00	1,650.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER,BONNET AND LHS FRONT DOOR.	192.00	1.00	192.00
X	A8W0807065D GRU	TO CARRY OUT DIAGNOSTIC CHECK COVER	1.00	2171.00	1,736.80
		Less 020%			

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 2 15:53

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120		Invoice No: 85016162	Account: A0006 (T 0)	AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120	
		Date : 08/04/2021			
		Order : SMN8785M			
		Term : 30			

Regn No: SMN8785M (V 42824)	Regn Date: 30/08/2019	Mileage: 12419	WIP No.: 55212
Model: A4 SEDAN 2.0 TFSI 8W2ADG	Chassis: WAUZZZF41KA086571	Engine: CVK 084102	Dept: U
You have been assisted by :- UB-Tony Foong (33)			

		Details	Qty	Unit Price	Amount
X	A8W0807683 9B9	GRILLE	Less 020%	1.00	193.50 154.80
X	A8W0853651A 3FZ	GRILLE	Less 020%	1.00	1317.00 1,053.60
X	A8W0807113	BRACKET AP	Less 020%	1.00	794.50 635.60
X	A8W0807081	COVER AP	Less 020%	1.00	125.50 100.40
X	A8K0010520C	STICKER AP	Less 020%	1.00	13.50 10.80
X	A8W0010515A	STICKER AP	Less 020%	1.00	7.10 5.68
X	A8W0807771	BRACKET AP	Less 020%	1.00	135.50 108.40
X	A8W0807333	SUPPORT AP	Less 020%	1.00	27.80 22.24
X	A8W0807334	SUPPORT AP	Less 020%	1.00	27.80 22.24
X	AN 91093901	POP-RIVET AP	Less 020%	4.00	0.70 2.24
X	A8W0823029A	HOOD	Less 020%	1.00	2763.00 2,210.40
X	A8W0823124	PROTECTION	Less 020%	1.00	26.90 21.52
X	A8W0823125	(A) (SK) PROTECTION 9/	Less 020%	1.00	27.30 21.84
X	A8W0823126	PROTECTION	Less 020%	1.00	26.90 21.52
X	A8W0823529E	BOWD CABLE AP	Less 020%	1.00	56.90 45.52
X	A8W0941774A	HEADLIGHT	Less 020%	1.00	7693.00 6,154.40
X	A8W0805594	(SK) CARRIER AP (LAST	Less 020%	1.00	1004.00 803.20
X	A8W0816411Q	REFR.COND. AP	Less 020%	1.00	615.00 492.00
X	A8W0121284AL	AIR DUCT AP	Less 020%	1.00	27.60 22.08
X	A8W0121674A	AIR DUCT AP	Less 020%	1.00	11.70 9.36
X	A8W0820536	BRACKET AP	Less 020%	1.00	18.00 14.40
X	A8W0807611	PLATE AP	Less 020%	1.00	207.50 166.00
X	AG 12E040M2	COOLANT -25*C AP	Less 020%	4.00	44.20 141.44

Parts 13,976.48	Sub-Total	19,838.48
Labour 0.00	7% GST	1,388.69
Sublet 6,412.00	Grand Total	21,227.17
Menus 0.00		
Lubricant 0.00		





Received by

For & on behalf of
Premium Automobiles Pte Ltd