

Date of Accident: 01/11/2020

HWA SENG SPRAY PAINTING PTE LTD
11 Sin Ming Drive
Singapore 575722
(COMPANY REGISTRATION NO: 202017045G)
TEL: 64533100
FAX: 62669932

Your Insured
Vehicle NO: XE 5139R

Not Authorized
L1 & 1900h
Resurvey After Paint

ESTIMATE REPAIR COSTS TO ISUZU NPR REG. NO.: YP 4243 J

1pc	O/S Wing Mirror
1pc	O/S Wing Mirror Bracket
1pc	O/S Signal Lamp
1pc	O/S Corner Panel
1pc	O/S Headlamp
1pc	Front Panel
1pc	Emblem 'ISUZU'
1pc	Sticker 'Reward.NP'
1pc	Front Grille
1pc	Front Bumper
1pc	Front Bumper Reinforcement

	S\$	
mir	75.00	✓
mir	265.00	✓
cm	225.00	✓
cm	245.00	✓
my cm	350.00	✓
r	695.00	x
ru	89.00	✓
ru	58.00	✓
my cm	435.00	✓
r	585.00	x
r	365.00	x

3 days

	3387.00
Less : 15%	508.05
	2878.95

LABOUR & MISC CHARGES

Panel Knocking	700.00
Spray Painting	600.00
Wire Checking	60.00
Labour to Remove & Install Front Windscreen	180.00
Sealant & Clip	100.00
Inner Seal	100.00
Vacuum & Top Up Gas	120.00
Labour to Remove Dashboard & Air Con to Facilitate Repair	350.00

	400
	520
	200
ru	x
ru	x
ru	x
ru	x
ru	x

TOTAL 5088.95

HWA SENG SPRAY PAINTING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: