

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0831/2020/NS
DATE : 03-Nov-20
WIP : 55262

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Hi Adrian,

3 days - ok - Jy - 08 Feb 21

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR TAN YU HARN
ADDRESS : 70 PUNGGOL WALK
#06-44
SINGAPORE 828785
TELEPHONE : HP +65 98437030
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100456681-04
VEHICLE NO : **SGY 57 Y**
MODEL CODE : AUDI Q7 2.0 TFSI QU
MODEL YEAR : 03/03/2016
ENGINE NO : CYR 002365
CHASSIS NO : WAUZZZ4M6GD028738
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 30-Oct-20
PLACE OF ACCIDENT : RAFFLES LINK CARPARK

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SGY 57 Y

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	S/N \$ 360.00	\$ 360.00
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,350.00	\$ 600.00
3	TO RESPRAY REAR UPPER BUMPER, REAR LOWER BUMPER AND BOTH REAR WHEEL ARCH TRIMS.	\$ 3,000.00	\$ 1,600.00
4	TO RENEW LHS REAR EXHAUST SILENCER AND ALIGN TO POSITION.	S/N \$ 480.00	
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 5,382.00	\$ 2,752.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGL 367 X

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	REAR TOP BUMPER		\$ 1,215.00	\$ 972.00
2	REAR LOWER BUMPER		\$ 1,815.00	\$ 1,452.00
3	REAR BUMPER FIXING PARTS		\$ 205.00	
4	REAR LOWER SPOILER		\$ 1,247.00	\$ 997.60
5	REAR LOWER SPOILER STRIP		\$ 105.00	
6	BOOT LID CONTROL UNIT		\$ 379.00	
7	REAR BUMPER CARRIER		\$ 1,341.00	
8	REAR BUMPER GUIDE SECTION - CENTRE		\$ 140.00	
9	REAR BUMPER HOLDING STRAP		\$ 180.00	
10	REAR PARKING AID SENSOR - INNER/OUTER	2	\$ 484.00	
11	TAIL LIGHT - LH		\$ 355.00	\$ 283.60
12	EXHAUST TAIL PIPE TRIM - LH		\$ 325.00	
13	REAR WHEEL COVER - LH/RH	2	\$ 746.00	\$ 596.00
14	SUNDRIES		\$ 300.00	
TOTAL SPARE PARTS		:	\$ 8,837.00	\$ 4,301.20
TOTAL LABOUR CHARGES		:	\$ 5,382.00	\$ 2,752.00
GRAND TOTAL		:	\$ 14,219.00	\$ 7,053.20

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

BL-04/12./20

