

Massive Trading & Auto

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541
H/P 91082728

Fax : 64816131

Tan Wee Shen
Blk 211B Punggol Walk
#11-629
Singapore 822211

Not Authorised
Resurvey Required

Vehicle No : SMS 6104R
Make : Mitsubishi Attrage
Year : 2019

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be submitted
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Rear boot lid <i>828</i>		
2 pcs	Rear boot lid hinge		
1 pc	Rear boot lid inner insulator		
1 pc	Rear boot lid inner lock		
1 pc	Rear boot lid outer lock		
1 pc	Rear boot lid lock sensor <i>photo</i>		
1 pc	Rear boot lid chrome handle		
1 pc	Rear boot lid emblem " Logo " <i>30</i>		
1 pc	Rear boot lid emblem " Attrage " <i>25</i>		
1 pc	Rear boot lid emblem " Mivec " <i>39</i>		
1 pc	Rear boot rubber <i>155.10</i>		
1 pc	Rear end panel <i>402</i>		
1 pc	Rear end panel inner garnish <i>122</i>		
1 pc	Rear end panel air duct <i>82 photo</i>		
1 pc	Rear end panel air duct outer cover <i>photo</i>		
1 pc	Rear spare tyre panel		
1 pc	Rear o/s spare tyre side panel		
1 pc	Spare tyre board		
2 pcs	Rear tail-lamp assy <i>276.30</i>		
2 pcs	Rear tail-lamp panel <i>n/s photo</i>		
1 pc	Rear bumper <i>659</i>		
1 pc	Rear bumper centre beam		
2 pcs	Rear bumper reflector		
2 pcs	Rear bumper side retainer		
2 pcs	Rear fender		
1 pc	Rear windscreen moulding		
2 pcs	Rear fender inner trim		
1 pc	Rear exhaust silencer		

1pc Rear bumper lower spoiler \$899.00

<i>R</i>	\$828.00	
<i>R</i>	\$190.00	X
<i>nil</i>	\$285.00	X
<i>nil</i>	\$185.00	
<i>R</i>	\$175.00	TK
<i>Short / Rd</i>	\$187.00	TK
<i>wrap</i>	\$286.00	
<i>na</i>	\$48.00	
<i>na</i>	\$55.00	
<i>na</i>	\$48.00	
<i>nil / Rd</i>	\$185.00	
<i>R</i>	\$452.00	
<i>nil / Rd</i>	\$172.00	
<i>CM</i>	\$125.00	
<i>CM</i>	\$136.00	
<i>R</i>	\$1,050.00	X
<i>R</i>	\$305.00	X
<i>CM</i>	\$255.00	
<i>CM</i>	\$592.00	
<i>CM</i>	\$310.00	
<i>R</i>	\$768.00	
<i>nil</i>	\$155.00	X
<i>nil</i>	\$170.00	X
<i>nil</i>	\$130.00	X
<i>nil</i>	\$1,650.00	
<i>nil</i>	\$85.00	
<i>nil</i>	\$850.00	
<i>R</i>	\$685.00	X
	\$11,261.00	
	\$1,126.10	
	\$10,134.90	

818.00
10% 818.10
7,362.90

SMS 6104 R

balance b/f \$9,325.80

3. Nett Item

pc	Rear bumper lower spoiler	10% refer. list price \$899	Build	899.00
pc	Rear spare tyre panel black insulator		Build	899.00
pc	Rear windscreen sealant		na	\$200.00 X
set	Rear reverse sensor		na	\$45.00 ✓
pc	Rear reverse camera		na	\$200.00 ✓
			na	\$280.00 X
				\$1,475.00
				245.00

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.	\$1,500.00	1400
To putty & spray paint on rear accident affected portion.	\$1,500.00	1300
Check/reconnect wiring.	\$45.00	201
To spray anti rust on accident affected portion.	\$120.00	✓
Remove/renew rear exhaust silencer	\$120.00	601
Remove/refit rear boot upholstery to facilitate repair	\$100.00	✓
Remove/refit rear windscreen to facilitate repair	\$100.00	✓
Four wheel towing	\$150.00	X
Remove/refit roof lining to facilitate repair on rear fender	\$180.00	1201
Total	\$15,340.80	

3170.00

Hi Kenneth

List price - \$7,362.90
 s net - \$245.00
 labour - \$3,120.00

\$10,727.90

sum \$8,600.00 - 8 days