

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



Final Report

Estimate No. : **b1 56341**
Date Estimated : **22/10/2020**
Prepared By : **Brandon Chan Eng Meng**

- ESTIMATE REPAIR FOR -
Lum Kok Meng (Lin Guoming)
323 Choa Chu Kang Avenue 3
#15-27

Singapore 689865

- ACCOUNT - 135
China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

| | | | | |
|--------------|--------------------------|-------------------|-------------|----------|
| REGN. NO. | CHASSIS NO. | REGN. DATE | MODEL | MILEAGE |
| EL23L | WBA7K320707E64370 | 29/11/2019 | 118i | 0 |

| DESCRIPTION | ORIGINAL PRICE | DISC. % | NETT |
|--|----------------|---------|--------|
| To replace front bumper and attachments, front radiator grille including remove attachments to facilitate repair caused by the accident. | 850.00 | | 850.00 |
| To respray front bumper. | 934.00 | | 934.00 |
| To check electrical wiring system at the front section for proper function. | 150.00 | | 150.00 |
| To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function. | 150.00 | | 150.00 |
| Sundries | 80.00 | | 80.00 |

| DESCRIPTION | UNIT PRICE | QTY | DISC. % | NETT |
|-------------------------------------|------------|------|---------|--------|
| FRT BUMPER PANEL PRIMED (LINES PDC/ | 897.25 | 1.00 | | 897.25 |
| FRONT GRILLE (LUXURY) | 696.00 | 1.00 | | 696.00 |

SUPPLEMENTARY ITEMS

| | |
|---------------------------------|----------|
| Total Labour : | 2,164.00 |
| Total Parts : | 1,593.25 |
| Total Labour & Parts : | 3,757.25 |
| Deduction for Excess : | 0.00 |
| Total Repair Costs less Excess: | 3,757.25 |
| GST @7%: | 263.01 |
| Grand Total : | 4,020.26 |