

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC4/1120012100/4623

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2

days

Res.: Yes or No

Lum Sum:

1.31

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLA2771Y

Yr Regn:

216

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

CITROEN C4 CACTUS c.c

Colour:

Red

A/C: Insured / Std / NI / NA

Sp. Reading

62585

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

VF70PHM2BFE 529799

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55 R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

31/10/20

D.O.I.

13/11/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

No damage. video have impact LTA 28408

No second hand parts

20/1/21 confirmed P/P 1094-30 with Ray

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

) S + RS. SI

) Photos

) Others

TOTAL

11/4/2020

Repairer Estimates


PROGRESSIVE
CAR CARE PTE LTD

Progressive Car Care Pte Ltd

(Co. Reg. No. 201006949C)

Blk 3022A Ubi Road 1 #01-45/ 46 S408716

T: +65 6741 5336 | F: +65 6741 7208

E: claims@procarcare.com.sg

W: www.procarcare.com.sg

TP INSURER:

NA

India International Insurance Pte Ltd (HQ)

Singapore

Claimant Insurer:

Auto & General Insurance (Singapore) Pte. Limited.

11/7/1094.30

not Authorized

2 days

13/11/20

3 days

Take photo after repair

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	TP 1120-6133
Policy No:		Date of Loss:	31/10/2020
Vehicle Reg. No.:	SLA2771Y	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	LIEW WAI LEONG		
Make/Model:	CITROEN C4 CACTUS, 1.2 PURETECH 82 (A)	Vehicle Reg. Date:	26/02/2016
Vehicle Colour:	RED		
Engine No:	10B2080374115	Chassis No:	VF70PHMZBFE529799
Odometer:	62344 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Description of Accident/Loss	REFER TO THE ATTACH STATEMENT RECORDED BY PEI WEN - PROGRESSIVE CAR CARE PTE LTD TEL 6741 5336		
Remarks:	VEHICLE IS NOT IN WORKSHOP		
Present Location:	PROGRESSIVE CAR CARE PTE LTD (HQ)		

COST OF CLAIMS

	Amount
Parts	3,585.60
Miscellaneous Items	11.00
Labour	700.00
Paintwork Labour	400.00
Towing	0.00

Gross Total (S\$)	4,696.60
+ GST 7.00% (S\$)	328.76
Nett Amount (S\$)	5,025.36

This claim is handled by: NG PEI WEN

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Generated using Merimen e-Claims Internet Estimation & Adjusting System

11/4/2020

Repairer Estimates

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 04 Nov 2020)
 Parts: M1-SUV CITROEN C4 CACTUS 1.2 PureTech 82 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)

Print Code: Progressive Car Care Pte Ltd/SLA2771Y/04/11/2020 09:50
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	NA	*REAR BUMPER			
2	1	NA	*REAR BUMPER PAD			
3	1	NA	*REAR BUMPER TOWING COVER - RH	0.00	0.00	*987.00 F
4	4	NA	*REAR BUMPER SENSOR	0.00	0.00	*634.00 F
5	1	NA	*REAR BUMPER SENSOR WIRE	0.00	0.00	*48.00 F
6	1	NA	*REAR BUMPER REINFORCEMENT	0.00	0.00	*1,036.00 F
7	1	NA	*REAR BUMPER TOP BEAM - PN9	0.00	0.00	*683.00 F
8	1	NA	*REAR BUMPER SIDE HOLDER	0.00	0.00	*321.00 F
9	10	NA	*REAR BUMPER CLIPS	0.00	0.00	*108.00 F
				0.00	0.00	*112.00 F
						*55.00 F
Sub Total (S\$)						3,984.00
- Add. Disc. on L,N Items 10.00% (S\$)						398.40
Total Parts (S\$)						3,585.60

Progressive Car Care Pte Ltd/SLA2771Y/04/11/2020 09:50. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

2-737
 102
 2-663.30
 5/N 11.00
 L 420.00
 1084.30

11/4/2020

Repairer Estimates

Estimates on Miscellaneous Items

No Qty Particulars

Miscellaneous Items

1 1 OD/TP Case (Insurer)

rec ✓

Amount

11.00

Sub Total (S\$)

11.00

Estimates on Labour

No Particulars

Paintwork Labour

1 TO RESPRAY PAINT ON ACCIDENT PORTIONS

200

Lab.Type

Amount

Labour Items

2 TO KNOCK OUT DENTS; REMOVE; REPLACE ACCIDENT PARTS

150

New

400.00

3 TO CHECK WIRING

20

New

450.00

4 TO TRANSFER REAR BUMPER SENSOR

50

New

50.00

5 TO RESET CHECK LIGHT

17X

New

100.00

New

100.00

Gross Labour Cost (S\$)

1,100.00

Progressive Car Care Pte Ltd/SLA2771Y/04/11/2020 09:50. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Our equipment include the latest and reliable CAR-O-LINER MARK 5 repair bench, draw aligner and the support dolly system to provide accurate re-alignment and speedy repairs.