

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jenny Lew

Date: 29 Dec 2020

Preliminary Advice

Insured Vehicle No : GBD8784Z
TP Vehicle No : YN4083P
Make : ISUZU NNR85UH4A
Date of Inspection : 06/11/2020
Inspection At : JWG International Pte Ltd (HQ)
Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK AutoPoint
Singapore 568047

Accident Date : 03/11/2020
Assignment Date : 05/11/2020
Est. Duration of Repair : 6

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	35,793.06
Revised Amount	:S\$	9,257.66
Check Items (Estimated)	:S\$	0.00
Total	:S\$	9,257.66
Lump Sum Repair	:S\$	7,400.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : TP : WP