Lian Her Motors

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541 Tel: 64817221

L H Car Rental Pte Ltd Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541

Vehicle No : SLN 7200 C Make/Model : Honda Vezel 1.5 X A

- 44

: 2017

Fax: 64816131

Not Nothanh 1/ Ray 8 2450h Puroney After Pains Eday,

Qty	Description		Unit Price	Amount
Estimate	Cost Of Repair			
1 pc 1 pc 1 pc 1 pc 1 pc 1 pc 1 pc 1 pc	Rear tail-gate assy Rear tail-gate glass moulding Rear tail-gate emblem " H " Rear tail-gate emblem : Vezel " Rear tail-gate inner lock Rear tail-gate inner lock sensor Rear tail-gate inner trim board Rear buzzer Rear boor rubber Rear bumper 762-70		c Pa/sho	\$45.10 X \$50.20 T \$285.60 X \$225.10 X \$455.90 X
2 pcs S Nett	Rear bumper side retainer	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before the spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation	\$38.20 J	\$76.40 X \$3,980.80 \$796.16 \$3,184.64
1 pc 1 pc 20 pcs	Rear tail-gate glass sealant Rear reverse sensor Rear bumper clip	Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company Acknowledged by Repairer Signature: Date:	JA	\$40.00 \$200.00 \$60.00 \$300.00
Labour C	harges		_	
Remove/renew the above parts including knocking, welding & cutting.				\$700.00
To putty	and spray paint		balance c/f	\$700.00 4 \$4,884.64

		* F
<u>LN 7200 C</u>		
Labour Charges	balance b/f	\$4,884.64
Check & reconnect wiring.		\$45.00 15/
To respray anti-rust proofing treatment		\$100.00 301
Remove/refit rear windscreen to facilitate repair		\$100.00
Remove/refit rear tail-gate mechanism to new door.	Total	\$100.00 60 / \$5,229.64

Miles Mar 1811

-