

TwinCar AUTOMOTIVE PTE LTD

Lac/Adrian

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

SGE EE MEI
BLK 466 SEGAR ROAD #11-170
SINGAPORE 670466

Contact : 96257058, 93820531

TP Chin
Celine

ESTIMATE

Repair Code : CLM15081

Date in : 03/11/2020

Vehicle Num. : SLS6393J

Model : MAZDA3 SEDAN 1.5 AT LED EU6

Chassis/Eng# : JM6BN22A8H0171106/P520461777

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
AIRCON CONDENSER <i>Not New</i>	1	1116.00	<i>X</i> 1,116.00
FRONT BONNET <i>Dented.</i>	1	1120.00	<i>✓</i> 1,120.00
FRONT BONNET MECHANISM LOCK <i>2nd</i>	1	206.80	<i>✓</i> 206.80
FRONT BONNET MECHANISM LOCK PANEL <i>new</i>	1	48.50	<i>X</i> 48.50
FRONT BONNET RUBBER SEAL <i>Not in</i>	1	66.00	<i>X</i> 66.00
FRONT BUMPER <i>2nd</i>	1	1082.00	<i>✓</i> 1,082.00
FRONT BUMPER CENTER BEAM <i>Not in</i>	1	148.00	<i>X</i> 148.00
FRONT BUMPER CENTER BRACKET L/R <i>2nd</i>	2	29.00	<i>✓</i> 58.00
FRONT BUMPER LAMP CHROME COVER L/R <i>Not in</i>	2	111.30	<i>X</i> 222.60
FRONT BUMPER LAMP COVER L/R <i>crushed</i>	2	72.00	<i>✓</i> 144.00
FRONT BUMPER LAMP L/R <i>crushed</i>	2	164.00	<i>✓</i> 328.00
FRONT BUMPER REINFORCEMENT <i>Bent</i>	1	565.00	<i>✓</i> 565.00
FRONT BUMPER REINFORCEMENT AIR GUIDE <i>crushed</i>	1	158.00	<i>✓</i> 158.00
FRONT BUMPER SIDE COVER L/R <i>crushed</i>	2	30.00	<i>✓</i> 60.00
FRONT BUMPER SIDE RETAINER L/R <i>New</i>	2	18.90	<i>✓</i> 37.80
FRONT BUMPER TOW HOOK COVER <i>Not in</i>	1	14.20	<i>X</i> 14.20
FRONT BUMPER UPPER FRAME BRACKET <i>Bent</i>	1	105.60	<i>✓</i> 105.60
FRONT GRILLE <i>crushed.</i>	1	610.00	<i>✓</i> 610.00

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

SGE EE MEI
BLK 466 SEGAR ROAD #11-170
SINGAPORE 670466

Contact : 96257058, 93820531

ESTIMATE

Repair Code : CLM15081

Date in : 03/11/2020

Vehicle Num. : SLS6393J

Model : MAZDA3 SEDAN 1.5 AT LED EU6

Chassis/Eng# : JM6BN22A8H0171106/P520461777

FRONT GRILLE 'LOGO' EMBLEM <i>new</i>	1	44.20	✓	44.20
FRONT GRILLE CHROME MOULDING L/R <i>could</i>	2	191.00	✓	382.00
FRONT GRILLE UPPER TOP GARNISH <i>Delivered</i>	1	355.00	✓	355.00
FRONT GRILLE UPPER TOP GARNISH CLIPS <i>new</i>	6	4.80	✓	28.80
FRONT GRILLE UPPER TOP GARNISH RIVET <i>new</i>	4	9.00	✓	36.00
FRONT HEADLAMP ASSY L/R <i>could</i>	2	3778.00	215 ✓	7,556.00
FRONT HEADLAMP BRACKET L/R <i>ple new</i>	2	24.70	+	49.40
FRONT HORN HI & LOW <i>hol new</i>	2	95.00	+	190.00
FRONT NUMBER PLATE GARNISH BRACKET <i>could</i>	1	68.00	✓	68.00
FRONT SUPPORT PANEL <i>Repair</i>	1	469.00	X	469.00
FRONT SUPPORT PANEL TOP GARNISH <i>could</i>	1	220.00	✓	220.00
REAR BOOTLID <i>Distorted</i>	1	1006.00	✓	1,006.00
REAR BOOTLID 'LOGO' EMBLEM <i>2</i>	1	74.40	✓	74.40
REAR BOOTLID 'MAZDA3' EMBLEM <i>new</i>	1	93.40	✓	93.40
REAR BOOTLID 'SKYACTIV' EMBLEM	1	63.60	✓	63.60
REAR BOOTLID HINGES L/R <i>hol new</i>	2	145.30	X	290.60
REAR BOOTLID INNER PULL HANDLE <i>hol new</i>	1	32.50	X	32.50
REAR BOOTLID INNER RUBBER GUIDE STOPPER L/R <i>hol new</i>	2	12.90	X	25.80

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

SGE EE MEI
BLK 466 SEGAR ROAD #11-170
SINGAPORE 670466

Contact : 96257058, 93820531

ESTIMATE

Repair Code : CLM15081

Date in : 03/11/2020

Vehicle Num. : SLS6393J

Model : MAZDA3 SEDAN 1.5 AT LED EU6

Chassis/Eng# : JM6BN22A8H0171106/P520461777

REAR BOOTLID INNER TRIM	<i>cracked</i>	1	120.20	✓	120.20
REAR BOOTLID MECHANISM LOCK	<i>Dand</i>	1	153.00	✓	153.00
REAR BOOTLID REFLECTOR L/R	<i>cracked</i>	2	466.00	✓	932.00
REAR BOOTLID REFLECTOR SIDE GARNISH L/R	<i>new</i>	2	20.50	X	41.00
REAR BOOTLID WEATHER STRIP	<i>cut</i>	1	129.30	✓	129.30
REAR BUMPER	<i>Distorted</i>	1	1128.60	✓	1,128.60
REAR BUMPER CENTER BRACKET	<i>cracked</i>	1	15.10	✓	15.10
REAR BUMPER REFLECTOR L/R	<i>20 cracked</i>	2	51.00	51	102.00
REAR BUMPER REINFORCEMENT	<i>Bent</i>	1	628.70	✓	628.70
REAR BUMPER REVERSE SENSOR	<i>2 pieces damaged</i>	4	193.90	387.80	775.60
REAR BUMPER REVERSE SENSOR 'O' RING	<i>2 new</i>	4	20.00	X	80.00
REAR BUMPER REVERSE SENSOR COVER	<i>new</i>	4	72.20	X	288.80
REAR BUMPER REVERSE SENSOR WIRE HARNESS	<i>new</i>	1	208.90	X	208.90
REAR BUMPER RIVET	<i>new</i>	10	5.90	✓	59.00
REAR BUMPER SIDE BRACKET L/R	<i>new</i>	2	21.00	✓	42.00
REAR BUMPER SIDE RETAINER L/R	<i>new</i>	2	36.10	✓	72.20
REAR BUMPER TOW HOOK COVER L/R	<i>missing</i>	2	16.20	✓	32.40
REAR END PANEL	<i>Dented</i>	1	505.10	✓	505.10

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

SGE EE MEI
BLK 466 SEGAR ROAD #11-170
SINGAPORE 670466

Contact : 96257058, 93820531

ESTIMATE

Repair Code : CLM15081

Date in : 03/11/2020

Vehicle Num. : SLS6393J

Model : MAZDA3 SEDAN 1.5 AT LED EU6

Chassis/Eng# : JM6BN22A8H0171106/P520461777

REAR END PANEL INNER TOP GARNISH	<i>Deformed.</i>	1	85.10	✓	85.10
REAR EXHAUST HEAT COVER	<i>torn</i>	1	246.20	✓	246.20
REAR EXHAUST SILENCER BOX	<i>Dented</i>	1	1129.60	✓	1,129.60
REAR EXHAUST SILENCER GASKET	<i>new</i>	1	14.60	✓	14.60
REAR EXHAUST SILENCER RUBBER MOUNTING	<i>new</i>	2	35.00	X	70.00
REAR FENDER INNER SHIELD L/R	<i>torn</i>	2	79.00	✓	158.00
REAR LH FENDER	<i>Repair</i>	1	1174.20	X	1,174.20
REAR LH FENDER INNER TRIM	<i>new</i>	1	235.60	X	235.60
REAR SPARE WHEEL PANEL	<i>Repair</i>		254.70	X	254.70
REAR SPARE WHEEL PANEL TOOL SPONGE	<i>crushed</i>	1	165.40	✓	165.40
REAR SPARE WHEEL PANEL TOP FLOOR BOARD	<i>Deformed</i>	1	350.00	308	350.00
REAR TAILLAMP L/R	<i>both crushed</i>	2	915.00	915.	1,830.00
REAR WINDSCREEN GLASS MOULDING	<i>new</i>	1	77.00	X	77.00
Subtotal before discount					28,179.50
Percentage discount 20%					5,635.90
Sub-total 1					22,543.60
FRONT BUMPER CLIPS - SET	<i>new</i>	1	50.00	30	50.00
FRONT BUMPER REINFORCEMENT AIR GUIDE CLIPS - SET	<i>new</i>	1	20.00	✓	20.00

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

SGE EE MEI
BLK 466 SEGAR ROAD #11-170
SINGAPORE 670466

Contact : 96257058, 93820531

ESTIMATE

Repair Code : CLM15081

Date in : 03/11/2020

Vehicle Num. : SLS6393J

Model : MAZDA3 SEDAN 1.5 AT LED EU6

Chassis/Eng# : JM6BN22A8H0171106/P520461777

FRONT GRILLE CLIPS - SET <i>new</i>	1	30.00	✓	30.00
FRONT NUMBER PLATE <i>could</i>	1	25.00	✓	25.00
FRONT NUMBER PLATE HOLDER <i>del</i>	1	50.00	30	50.00
RADIATOR COOLANT <i>new</i>	1	60.00	40	60.00
REAR BOOTLID INNER TRIM CLIPS - SET <i>new</i>	1	50.00	30	50.00
REAR BOOTLID NUMBER PLATE <i>3 not new</i>	1	25.00	X	25.00
REAR BOOTLID NUMBER PLATE HOLDER	1	50.00	X	50.00
REAR BUMPER CLIPS - SET <i>new</i>	1	50.00	30	50.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET <i>new</i>	1	30.00	10	30.00
REAR FENDER INNER TRIM CLIPS L/R - SET <i>not new</i>	2	50.00	X	100.00
REAR TAILLAMP CLIPS L/R - SET <i>new</i>	2	30.00	10	60.00
REAR WINDSCREEN GLASS SEALANT <i>not new</i>	1	60.00	X	60.00
Subtotal before discount				660.00
Percentage discount 0%				0.00
Sub-total 2				660.00
Parts-total				23,203.60

LABOUR

To remove, reinstall air con parts, vacuums, refill air con gas. (to FR)

120 ✓ ~~150.00~~

To remove, reinstall electrical wiring harness, check lighting, resetting headlamp focussing and rewire for parking sensor.

✓ 100.00

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

SGE EE MEI

BLK 466 SEGAR ROAD #11-170

SINGAPORE 670466

Contact : 96257058, 93820531

ESTIMATE

Repair Code : CLM15081

Date in : 03/11/2020

Vehicle Num. : SLS6393J

Model : MAZDA3 SEDAN 1.5 AT LED EU6

Chassis/Eng# : JM6BN22A8H0171106/P520461777

To remove and refit rear windscreen(to FR)

X 150.00

To remove, reinstall petrol tank. (to FR)

X 100.00

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

80 150.00

To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.

1200 1,600.00

To re-spray painting on the front bonnet, front support panel, front fender (L/R) and front bumper.

600 1,000.00

To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.

80 120.00

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

1600 2,400.00

To apply anti-rust chemical on repaired and replaced panel.

100 150.00

Labour Total

5,920.00

Parts & Labour Total

29,123.60

*** This is a computer-generated document which requires no signature.***

page 6

total: 21479.56
1/s: 17.2K

12 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

17K

17.2K