



## Section A - Accident Details

Registration Number	SHF1040B
Case Reference Number	TAX/11/20/2007
Registration Date	23/12/2014
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	ROSLI BIN AHMAD
Type of Accident	Side Swipe
Accident Date and Time	3/11/2020 10:20 PM
Accident Reported Date and Time	4/11/2020 8:52 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24108697
Special Instruction to ARC, if any	TP / LEFT PORTION
Prepared Date and Time	4/11/2020 11:15 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

## Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$500.00
Total Spray Cost	\$1,674.00	\$650.00
Total Spare Part Cost	\$6,023.28	\$98.93
Total Other Cost	\$820.00	(\$198.93)
<b>TOTAL COST</b>	<b>\$9,362.28</b>	<b>\$1,050.00 (L/S)</b>
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	6.0	3.0
Prepared / Adjusted By	Tuck Foo Kok	Sun Pin (LKK) / NTUC
ARC / Surveyor Sign Off Date	05/11/2020 11:19 AM	04/11/2020 3:29 PM
Signature		
Remarks		L/S, after paint photo.

## Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2011-0214	Invoice Number	
Quotation Date	18.11.2020	Invoice Date	
Invoice Amount		Prepared Date	

## Section D - Details of Repair Estimates

## Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION	\$845.00	\$500.00
Total Labour	\$845.00	\$500.00

## Part 2 - Spray Painting &amp; Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00
TO RESPRAY RIM	\$180.00	\$50.00
TO RESPRAY FRONT DOOR LH	\$378.00	\$200.00
TO RESPRAY VIEW MIRROR	\$180.00	\$0.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$1,674.00	\$650.00

## Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$30.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$20.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$20.00
TO REMOVE AND REFIT WIRE HARDESS	\$200.00	\$20.00
TO TRANSFER DOOR MECHANISM	\$120.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
Lump Sum Adjustment by Surveyor	\$0.00	(\$288.93)
Total Other Costs	\$820.00	(\$198.93)

## Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119-47930	BUMPER FRT	1.00	\$482.00	100.00	\$0.00	Replace	Repair X R
		52161-16010	BUMPER CLIPS	0.00	\$1.61	0.00	\$0.00	Replace	Not Given X Svc
		52116-47040	BUMPER SUPPORT F/LH	0.00	\$76.40	0.00	\$0.00	Replace	Not Given X Svc
		81521-47050	LENS & BODY, FR TURN LH	0.00	\$511.80	0.00	\$0.00	Replace	Not Given X Svc
		81170-47500	HEAD LAMP LH	0.00	\$945.20	0.00	\$0.00	Replace	Check X Svc
			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given X Svc
		42611-47140	WHEEL DISC FRONT	1.00	\$1,484.20	100.00	\$0.00	Replace	Repair X R
		"53802-47050"	FENDER FRT/LH	1.00	\$723.40	100.00	\$0.00	Replace	Repair X R
		75374-47051	NAME PLATE (HYBRID	1.00	\$51.90	25.00	\$38.93	Replace	Replace / Nec
		53876-47030	FENDER LINER FRT/LH	0.00	\$171.70	0.00	\$0.00	Replace	Check X Svc

# SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 18/11/2020

User ID : PohSuan

		53852-47020	FENDER LINER PAD, FR WHEEL LH	0.00	\$49.30	0.00	\$0.00	Replace	Not Given	X
		75852-47900	MOULDING BODY, LH	0.00	\$673.60	0.00	\$0.00	Replace	Not Given	X
		67002-47070	DOOR FRT/LH	1.00	\$894.40	100.00	\$0.00	Replace	Repair	X
			STICKER DECAL SMRT (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace	
		87940-47310	MIRROR ASSY, LH	0.00	\$1,224.90	0.00	\$0.00	Replace	Not Given	X
		81740-52040	MIRROR LAMP LH	0.00	\$65.30	0.00	\$0.00	Replace	Not Given	X
		87945-74010	COVER, OUTER MIRROR, LH	0.00	\$107.40	0.00	\$0.00	Replace	Not Given	X
Total					\$7,649.85		\$98.93			

SUC

SUC

X

NP

SUC

SUC

SUC

## Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

98.93 /  
+ 500.00 /  
+ 740.00 /

1338.93 /  
- 202

1071.14 /

4 S \$1050 /- /  
3 days