



Section A - Accident Details

Registration Number	SHD6076B
Case Reference Number	TAX/11/20/2006
Registration Date	11/11/2015
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	ANG CHOR NGIAP
Type of Accident	Head To Side
Accident Date and Time	1/11/2020 2:57 PM
Accident Reported Date and Time	4/11/2020 8:07 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24108696
Special Instruction to ARC, if any	TP / TOWED \$60/ RIGHT PORTION
Prepared Date and Time	4/11/2020 1:07 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$876.00	\$600.00
Total Spray Cost	\$1,854.00	\$800.00
Total Spare Part Cost	\$7,912.57	\$1,536.08
Total Other Cost	\$924.00	(\$486.08)
TOTAL COST	\$11,566.57	\$2,450.00 (L/S)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	6.0	4.0
Prepared / Adjusted By	Ang Bang Kien	Sun Pin (LKK) / NTUC
ARC / Surveyor Sign Off Date	10/11/2020 9:02 AM	10/11/2020 8:39 AM
Signature		
Remarks	Total number of repair days = 4 days. SUP = 0 day.	L/S. after paint photo.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2011-0345	Invoice Number	
Quotation Date	24.11.2020	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	\$676.00	\$500.00
TO REPAIR CENTRE PILLAR RH	\$200.00	\$100.00
Total Labour	\$876.00	\$600.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT DOOR RH	\$378.00	\$200.00
RESPRAY MIRROR COVER RH	\$180.00	\$0.00
TO RESPRAY REAR DOOR RH	\$378.00	\$200.00
TO RESPRAY REAR FENDER RH	\$378.00	\$200.00
TO RESPRAY RIM	\$180.00	\$0.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$100.00
TO RESPRAY CENTRE PILLAR RH	\$180.00	\$100.00
Total Spray Painting & Panel Beating	\$1,854.00	\$800.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$84.00	\$0.00
TO TRANSFER DOOR MECHANISM	\$240.00	\$120.00
TO REMOVE AND REFIX WING MIRROR	\$120.00	\$0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
Lump Sum Adjustment by Surveyor	\$0.00	(\$626.08)
Total Other Costs	\$924.00	(\$486.08)

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		67001-47070	DOOR FRT/RH	1.00	\$894.40	25.00	\$670.80	Replace	Replace
			STICKER DECAL SMRT (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace
		68730-12120	HINGE LOWER RHF, DOOR	0.00	\$90.10	0.00	\$0.00	Replace	Not Given
		68710-12151	HINGE UPPER RHF, DOOR	0.00	\$80.50	0.00	\$0.00	Replace	Not Given
		68610-47021	CHECK ASSY, FR DOOR,	0.00	\$150.30	0.00	\$0.00	Replace	Not Given
		85710-47120F	DOOR REGULATOR MOTOR FRONT RH	0.00	\$947.80	0.00	\$0.00	Replace	Check
		69801-52070	DOOR REGULATOR SUB-ASSY, FRT/REAR RH	0.00	\$224.80	0.00	\$0.00	Replace	Check

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number 63985592
Estimator Telephone Number 68662623
Accident Reporting Number 68662672

Date Generated : 24/11/2020

User ID kimmingchin

	87910-47330	MIRROR ASSY,RH	0.00	\$1,307.10	0.00	\$0.00	Replace	Not Given	X
	879157-4010	COVER, OUTER MIRROR, RH	0.00	\$107.40	0.00	\$0.00	Replace	Not Given	X
	67003-47080	DOOR RR/RH	1.00	\$954.50	25.00	\$715.88	Replace	Replace	X
	85710-47120	DOOR REGULATOR MOTOR REAR RH	0.00	\$947.80	0.00	\$0.00	Replace	Check	X
	69801-52070	DOOR REGULATOR SUB-ASSY, FRT/REAR RH	0.00	\$224.80	0.00	\$0.00	Replace	Check	X
	82153-47300	WIRE RHR,DOOR	0.00	\$280.20	0.00	\$0.00	Replace	Not Given	X
	68770-52031	DOOR HINGE LOWER RR/RH	0.00	\$72.20	0.00	\$0.00	Replace	Not Given	X
	68730-12120	DOOR HINGE UPPER RR/RH	0.00	\$90.10	0.00	\$0.00	Replace	Not Given	X
	68630-47031	CHECK ASSY, RR DOOR,	0.00	\$150.30	0.00	\$0.00	Replace	Not Given	X
	61604-47090	FENDER RR/RH	1.00	\$766.80	100.00	\$0.00	Replace	Repair	R
		SMRT LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace	X
		STICKER DECAL 65558888	1.00	\$21.60	0.00	\$21.60	Replace	Replace	X
	42611-47140	WHEEL DISC	0.00	\$1,484.20	0.00	\$0.00	Replace	Not Given	X
		TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X
	42450-47040	WHEEL HUB REAR	0.00	\$489.40	0.00	\$0.00	Replace	Not Given	X
		PIXEL STICKER	1.00	\$60.00	0.00	\$60.00	Replace	Replace	X
	75851-47900	MOULDING BODY, RH	1.00	\$673.60	100.00	\$0.00	Replace	Repair	R
Total				\$10,212.44		\$1,536.08			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

1536.08
+ 600.00
+ 940.00

3076.08
- 20%

2460.86
45 \$2450/-