

Section A - Accident Details

Registration Number	SHD6076B
Case Reference Number	TAX/11/20/2006
Registration Date	11/11/2015
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	ANG CHOR NGIAP
Type of Accident	Head To Side
Accident Date and Time	1/11/2020 2:57 PM
Accident Reported Date and Time	4/11/2020 8:07 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24108696
Special Instruction to ARC, if any	TP / TOWED \$60/ RIGHT PORTION
Prepared Date and Time	4/11/2020 1:07 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$876.00	\$600.00
Total Spray Cost	\$1,854.00	\$800.00
Total Spare Part Cost	\$7,912.57	\$1,536.08
Total Other Cost	\$924.00	(\$486.08)
TOTAL COST	\$11,566.57	\$2,450.00 (L/S)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	6.0	4.0
Prepared / Adjusted By	Ang Bang Kien	Sun Pin (LKK) / NTUC
ARC / Surveyor Sign Off Date	10/11/2020 9:02 AM	10/11/2020 8:39 AM
Signature		
Remarks	Total number of repair days = 4 days. SUP = 0 day.	L/S. after paint photo.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2011-0345	Invoice Number	
Quotation Date	24.11.2020	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	\$676.00	\$500.00 /
TO REPAIR CENTRE PILLAR RH	\$200.00	\$100.00 / supp
Total Labour	\$876.00	\$600.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT DOOR RH	\$378.00	\$200.00
RESPRAY MIRROR COVER RH	\$180.00	\$0.00 /
TO RESPRAY REAR DOOR RH	\$378.00	\$200.00 /
TO RESPRAY REAR FENDER RH	\$378.00	\$200.00 /
TO RESPRAY RIM	\$180.00	\$0.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$100.00
TO RESPRAY CENTRE PILLAR RH	\$180.00	\$100.00 / supp
Total Spray Painting & Panel Beating	\$1,854.00	\$800.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$84.00	\$0.00
TO TRANSFER DOOR MECHANISM	\$240.00	\$120.00
TO REMOVE AND REFIX WING MIRROR	\$120.00	\$0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
Lump Sum Adjustment by Surveyor	\$0.00	(\$626.08)
Total Other Costs	\$924.00	(\$486.08)

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		67001-47070	DOOR FRT/RH	1.00	\$894.40	25.00	\$670.80	Replace	Replace / DO
			STICKER DECAL SMRT (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace / Nec
		68730-12120	HINGE LOWER RHF, DOOR	0.00	\$90.10	0.00	\$0.00	Replace	Not Given X / SVC
		68710-12151	HINGE UPPER RHF, DOOR	0.00	\$80.50	0.00	\$0.00	Replace	Not Given X / SVC
		68610-47021	CHECK ASSY, FR DOOR,	0.00	\$150.30	0.00	\$0.00	Replace	Not Given X / SVC
		85710-47120F	DOOR REGULATOR MOTOR FRONT RH	0.00	\$947.80	0.00	\$0.00	Replace	Check X / SVC
		69801-52070	DOOR REGULATOR SUB-ASSY, FRT/REAR RH	0.00	\$224.80	0.00	\$0.00	Replace	Check X / SVC

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number 63895592
Estimator Telephone Number 68662623
Accident Reporting Number 68662672

Date Generated : 24/11/2020

User ID kimmingchin

	87910-47330	MIRROR ASSY,RH	0.00	\$1,307.10	0.00	\$0.00	Replace	Not Given	X	SVC
	879157-4010	COVER, OUTER MIRROR, RH	0.00	\$107.40	0.00	\$0.00	Replace	Not Given	X	SVC
	67003-47080	DOOR RR/RH	1.00	\$954.50	25.00	\$715.88	Replace	Replace		CRU
	85710-47120	DOOR REGULATOR MOTOR REAR RH	0.00	\$947.80	0.00	\$0.00	Replace	Check	X	SVC
	69801-52070	DOOR REGULATOR SUB-ASSY, FRT/REAR RH	0.00	\$224.80	0.00	\$0.00	Replace	Check	X	SVC
	82153-47300	WIRE RHR,DOOR	0.00	\$280.20	0.00	\$0.00	Replace	Not Given	X	SVC
	68770-52031	DOOR HINGE LOWER RR/RH	0.00	\$72.20	0.00	\$0.00	Replace	Not Given	X	SVC
	68730-12120	DOOR HINGE UPPER RR/RH	0.00	\$90.10	0.00	\$0.00	Replace	Not Given	X	SVC
	68630-47031	CHECK ASSY, RR DOOR,	0.00	\$150.30	0.00	\$0.00	Replace	Not Given	X	SVC
	61604-47090	FENDER RR/RH	1.00	\$766.80	100.00	\$0.00	Replace	Repair		RC
		SMRT LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace		Nec
		STICKER DECAL 65558888	1.00	\$21.60	0.00	\$21.60	Replace	Replace		Nec
	42611-47140	WHEEL DISC	0.00	\$1,484.20	0.00	\$0.00	Replace	Not Given	X	SVC
		TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X	SVC
	42450-47040	WHEEL HUB REAR	0.00	\$489.40	0.00	\$0.00	Replace	Not Given	X	SVC
		PIXEL STICKER	1.00	\$60.00	0.00	\$60.00	Replace	Replace		Nec
	75851-47900	MOULDING BODY, RH	1.00	\$673.60	100.00	\$0.00	Replace	Repair		RC
Total				\$10,212.44		\$1,536.08				

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

1536.08 /
+ 600.00 /
+ 940.00 /

3076.08 /
- 20%

2460.86 /
4 S \$ 2,450 /
4 days