

53 Ubi Avenue 1#01-25 Paya Ubi Industrial Park Singapore 408934
Tel: 6844 4290 Fax: 6841 6043 Kaman Koh: 9769 9299 Email: motoricarzgarage@gmail.com
UEN:201919765N

TP chim. Denise.

KDY2318041243.

[illegible]

No.	Description	Unit	Unit Price	Amount
33	JOINT SEALANT <i>the m</i>	1	100.00	100.00
				\$ 260.00
	Labour to:			
34	CHECK FRONT WIRING AND LIGHTNING SYSTEM		60.00	60.00
35	REMOVE AND REFIT FRONT WINDSCREEN		120.00	120.00
36	REMOVE AND REFIT FRONT DASHBAORD		500.00	500.00
37	REMOVE AND RENEW AIRCON BLOWER		150.00	150.00
38	REMOVE,REFIT TRIM , LINING AND GANRNISH		200.00	200.00
39	TRANSFER PARTS, ATTACHMENT FROM OLD DOOR TO NEW		200.00	200.00
40	PANEL BEATING AND RENEW DAMAGE PARTS ON AFFECTED AF		1,500.00	1,500.00
41	SPRAY PAINTING ON AFFECTED AREAS		1,600.00	1,600.00
42	APPLY ANTI RUST ON AFFETED AREAS		120.00	120.00
				\$ 4,450.00
			Parts Replacement Amount	\$ 10,152.50
			Total Amount for Labour	\$ 4,450.00
			Total Amount	\$ 14,602.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian Lj
h/s 05/11/20.

06 days

total: 6205.50

h/s: 48K.