



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

GREAT AMERICAN INSURANCE COMPANY

Ref : CS/GAI20012115/Uqf3e2

3 TEMASEK AVENUE
#16-01 CENTENNIAL TOWER
SINGAPORE 039190

Date : 30-11-2020



Code : GAI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBE 633Z	Veh. Inspected	SFL 34T
Policy No.		Coverage (\$)	0.00
Claim No.	CLMOMVC000003911	Excess (\$)	0.00
Assign From	SHERY WONG	Assign Date	05/11/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA HARRIER (A)	c.c	2362
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	ACU309852296	Colour	SILVER
Odometer	276827	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/65 R17	MICHELIN	6 mm
L/H Front Tyre	225/65 R17	MICHELIN	6 mm
R/H Rear Tyre	225/65 R17	MICHELIN	6 mm
L/H Rear Tyre	225/65 R17	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	31/10/2020	Inspection Date	09/11/2020
Survey held at	PROGRESSIVE CAR CARE PTE LTD BLK 3022A UBI ROAD 1 #01-45/46, SINGAPORE 048716		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	-----------------------