



ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com

Tyre &
Sports Rim



Reference No.: 41120

Date: 04.11.2020

Tarkus Interiors Pte Ltd

46 Defu Lane 9

Singapore 539286.

Hino XZU710R 14FT Wide Cab 5T

Estimate Repair Cost for Vehicle Reg. No: YP 9147 X

1 Pc. RH Door <i>Dent</i>	1,490.00	✓
1 Pc. RH Door Centre Hopper <i>HH</i>	148.30	X
1 Pc. RH Door Inner Rubber <i>HH</i>	199.50	✓
1 Pc. RH Door Inner Seal <i>HH Nec (distorted)</i>	98.90	X ✓
2 Pcs/ RH Door Hinger <i>HH upper lower Bt</i> @ 115.00	230.00	X ✓
1 Pc. RH Door Signal Lamp <i>broken</i>	189.50	✓
1 Pc. RH Door Board <i>HH</i>	698.50	X
10 Pcs. RH Door Board Clips <i>HH</i> @ 6.00	60.00	X
1 Pc. RH Fender Garnish <i>HH</i>	295.00	X
1 Pc. RH Fender Step Garnish <i>broken</i>	399.00	✓
1 Pc. RH Fender Step Panel <i>X repair</i>	288.00	X
1 Pc. RH Step Garnish Reflector <i>HH</i>	49.00	X
1 Pc. Step Garnish Cover <i>distorted</i>	48.30	✓
1 Pc. Radiator Spare Tank <i>crack</i>	296.50	X ✓
1 Pc. Radiator Coolant <i>X Nec (Leak)</i>	40/- 80.00 (Nett)	X ✓
1 Pc. RH Corner Garnish <i>broken / distorted</i>	594.00	✓
1 Pc. RH Corner Garnish Top Cover <i>broken / distorted</i>	105.00	✓
1 Pc. RH Corner Garnish Seal <i>Nec</i>	48.00	✓
1 Pc. RH Side Mirror <i>Scratched</i>	199.30	✓
1 Pc. RH Side Mirror Bracket <i>distorted</i>	405.00	✓
1 Pc. RH Pillar <i>X repair</i>	989.00	X
1 Pc. RH Head Lamp Assy. <i>broken</i>	1,214.00	✓
1 Pc. Front Grille <i>X mainly crack</i>	499.80	X ✓
1 Pc. Bumper <i>Dent / cut</i>	997.00	✓
1 Pc. Bumper Side Catch <i>HH</i>	113.00	X
1 Pc. Bumper Bracket <i>X Bt</i>	298.60	X ✓
1 Pc. Fog Lamp <i>X crack</i>	299.80	X ✓
1 Pc. RH Frame Rubber <i>HH</i>	268.00	X
1 Pc. 616 Sticker <i>Nec.</i>	59.00	✓



ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538

Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E

Email: alfredauto@hotmail.com

Tyre & Sports Rim



BATTERY



1 Pc. Euro 6 Sticker <i>Hee</i>	60.00 ✓
1 Pc. Company Logo Sticker (Blue) <i>Hee</i>	399.00 (S.Nett) ✓
1 Pc. Itoki Group Sticker (Red/Black) <i>Hee</i>	220.00 (S.Nett) ✓
1 Pc. Tel. Sticker (Black) <i>Hee</i>	220.00 (S.Nett) ✓
1 Pc. RH Side Proter Beam <i>ist</i>	410.00 ✓
1 Pc. RH Canvas (Blue) <i>torn</i>	800.00 (Nett) ✓
1 Pc. RH Tyre <i>HH</i>	390.00 (Nett) X

List 8026.20
10% 7223.58

Total (Panels / Parts):

13,159.00 (SGD)

10% disc.
SN 1679.00

LABOR CHARGES

To renew tyre & balancing.	80.00 <i>HH</i>
To remove & refit wiring & checking.	180.00 <i>30/-</i>
To renew & refit canvas.	280.00 <i>150/-</i>
To welding, knocking, straightening repair & renew all accident damaged affected area.	1,500.00 <i>1000/-</i>
To respray painting on all accident affected area.	<i>2020.00</i> 1,900.00 <i>800/-</i>
To rust proof all accident affected area.	120.00 <i>40/-</i>

Total (Labor Charges):

4,060.00 (SGD)

06/11/2020 @ 0915hrs.

Nett Amount

45mm

10 days.

I yan

2 KK And

10922.58

1/5 8500/-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com

Tyre &
Sports Rim



TOTAL COST SUMMARY

PANELS / PARTS	13,159.00
LABOR CHARGES	4,060.00

Grand Total:	<u>17,219.00 (SGD)</u>
--------------	------------------------

We shall be glad if you can forward the payment at your early convenience.

Cheque should be crossed and make payable to 'Alfred Auto Services and Supplies'

Alfred Quah

ALFRED AUTO SERVICES & SUPPLIES

[WITHOUT PREJUDICE SAVE AS TO COSTS]