

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Azlan, Syazairdina

Date: 06 Nov 2020

Preliminary Advice

Vehicle No	: GBH6621C	Accident Date	: 23/09/2020
Make	: MERCEDES-BENZ VITO 114	Policy No.	: 0999993880
Assignment Date	: 05/11/2020	Excess	: S\$1,400.00
Date of Inspection	: 05/11/2020	Est. Duration of Repair	: 6
Inspection At	: TONG LUCK AUTO PTE LTD (HQ) 160 SIN MING DRIVE, #07-01 SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front N/S portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,151.55
Revised Amount	:S\$	3,014.00
Check Items (Estimated)	:S\$	1,560.00
Total	:S\$	4,574.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	72,000.00
COE / PARF Rebate	:S\$	24,912.00
Salvage Value	:S\$	
Margin for Repair	:S\$	47,088.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :