



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16

AIG BUILDING

SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 23/09/2020

ESTIMATE

NO : QUOT202010-000005(00)

DATE : 02/10/2020

POLICY NO : 999995580

VEH REG NO : GBH6621C

MAKE/MODEL : MERCEDES BENZ VITO 114 CDI

PANEL VAN LONG AT ABS 5DR

CHASSIS NO : WDF44760323351834

ENGINE NO : 65195034274310

REG. DATE : 2018

Estimate Repair Cost to Vehicle No : GBH6621C

Description	Quantity	Unit Price	Amount
		S\$	S\$
PARTS			
1 Tailgate	1	1,350.00	1,350.00 ✓
2 Tailgate centre logo	1	48.00	48.00 ✓
3 Tailgate 'VITO' emblem	1	52.00	52.00 ✓
4 Tailgate 'C&C' emblem	1	38.00	38.00 ✓
5 Tailgate '109 CDI' emblem	1	62.00	62.00 ✓
6 Taillamp assy - LH	1	550.00	550.00 ✓
7 Taillamp lower garnish - LH	1	98.00	98.00 ✓
8 Rear bumper	1	850.00	850.00 ✓
9 Rear bumper clips	15	5.50	82.50 ✓
10 Rear fender - LH	1	780.00	780.00 ✓
			3,910.50
		Add 10%	391.05
			4,301.55
SPECIAL NET			
11 Rear windscreen sealant	1	60.00	60.00 ?
12 Tailgate '6 pax' sticker	1	25.00	25.00 125m
13 Tailgate '70km/h' sticker	1	25.00	25.00 125m
14 Rear bumper sensor	1	380.00	380.00 X
			490.00
LABOUR			
15 To remove and refit rear windscreen glass.	1	150.00	150.00 120L
16 To remove and refit rear bumper sensor	1	100.00	100.00 50L X
17 To check and rectify wiring system	1	80.00	80.00 20L
18 To transfer damaged tailgate interior mechanism to new tailgate.	1	150.00	150.00 60L
19 To remove and refit LH fender interior garnishes and trimboard, to facilitates the repairs	1	180.00	180.00 80L
20 To panel beat and straighten rear floorboard panel, rear chassis frame, rear LH fender inner panel, to cut and weld LH fender, including replacement of parts and align where necessary, to refit and adjust the same.	1	1,500.00	1,500.00 ?
21 To putty and spray paint on affected areas	1	1,200.00	1,200.00 800L
			3,360.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: