

Lion City Rentals Pte Ltd
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Ms: AIG Asia Pacific Insurance Pte Ltd
Date 5/11/2020
Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO. SLG2294B
 CHASSIS NO : GP71040652
 MAKE / MODEL : Honda Shuttle Hybrid 1.5 CVT Auto
 DATE OF ACCIDENT : 04/11/2020
 YOUR INSURED VEHICLE NUMBER : FBQ8256M
 MILEAGE : 267775 km

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

<u>PARTS DESCRIPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1 Rear tailgate / <i>nd</i>	1PC	\$ 1,850.00	\$ 1,850.00
2 Rear tailgate lock X	1PC	\$ 550.00	\$ 550.00
3 Rear tailgate lock catch X	1PC	\$ 158.00	\$ 158.00
4 Rear tailgate windscreen moulding / <i>Nec</i>	1PC	\$ 195.00	\$ 195.00
5 Rear tailgate weatherstrip X	1PC	\$ 255.00	\$ 255.00
6 Rear tailgate Honda emblem X	1PC	\$ 81.30	\$ 81.30
7 Rear tailgate Hybrid emblem / <i>Nec</i>	1PC	\$ 88.40	\$ 88.40
8 Rear tailgate shuttle emblem / <i>Nec</i>	1PC	\$ 88.40	\$ 88.40
9 Rear bumper / <i>CR4.</i>	1PC	\$ 1,350.00	\$ 1,350.00
10 Rear bumper RH tow cover X	1PC	\$ 68.00	\$ 68.00
11 Rear end panel ?	1PC	\$ 950.00	\$ 950.00
12 Rear end panel top cover ?	1PC	\$ 180.00	\$ 180.00
LIST TOTAL S\$:			\$ 4,684.10
20.00% DISCOUNT S\$:			\$ 936.82
			<u>\$ 3,747.28</u>

SPECIAL NETT

1 Reverse sensor / <i>short</i>	1 SET	\$ 260.00	<i>200</i>
2 Windscreen sealant / <i>Nec.</i>	1 SET	\$ 120.00	<i>40</i>
3 Bumper clips / <i>Nec</i>	1 SET	\$ 120.00	<i>30</i>
4 End panel to garnish clips ?	1 SET	\$ 80.00	
Special Nett Total S\$:		\$ 580.00	

LABOUR CHARGES

1 TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN PANEL WHERE STRAIGHTEN.	\$ 900.00	<i>500</i>
2 TO PUTTY & SPRAY PAINT ALL AFFECTED AREAS (INNER/OUTER)	\$ 900.00	<i>400</i>
3 TO REMOVE & INSTALL REAR WINDSCREEN	\$ 160.00	<i>120</i>
7 TO CONDUCT A STANDARD OF OPEARTING PROCEDURES POST REPAIRS DIAGNOSTIC SCAN TEST AS A REQUIREMENT FOR HYBRID CARS UPON COMPLETION OF COLLISION REPAIRS	\$ 300.00	<i>X</i>
9 TO TRANSFER TAILGATE MECHANISM	\$ 100.00	<i>60</i>

LABOUR TOTAL S\$: \$ 2,260.00
 TOTAL S\$: \$ 6,587.28
 7% GST \$ 461.11
 GRAND TOTAL S\$: \$ 7,048.39

Repair dy - 3 days
LIS After pump photo
Sum Pin (Helo)
05/11/2020
TP withn prejudice.