

Lion City Rentals Pte Ltd
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

1,878.24
270
1,080
3,228.24
-20%
2,582.59

Ms: AIG Asia Pacific Insurance Pte Ltd
Date 5/11/2020
Attn: MOTOR CLAIMS DEPT

4/5
\$2,600
3 days

ESTIMATE

VEHICLE NO. SLG2294B
CHASSIS NO: GP71040652
MAKE / MODEL: Honda Shuttle Hybrid 1.5 CVT Auto
DATE OF ACCIDENT: 04/11/2020
YOUR INSURED VEHICLE NUMBER: FBQ8256M
MILEAGE: 267775 km

	PARTS DESCRIPTION	QTY	UNIT PRICE	LIST PRICE
1	Rear tailgate / no	1PC	\$ 1,850.00	\$ 1,850.00 1,200
2	Rear tailgate lock X Svc	1PC	\$ 550.00	\$ 550.00
3	Rear tailgate lock catch X Svc	1PC	\$ 158.00	\$ 158.00
4	Rear tailgate windscreen moulding / NEC	1PC	\$ 195.00	\$ 195.00 151
5	Rear tailgate weatherstrip X Svc	1PC	\$ 255.00	\$ 255.00
6	Rear tailgate Honda emblem X Svc	1PC	\$ 81.30	\$ 81.30
7	Rear tailgate Hybrid emblem / NEC	1PC	\$ 88.40	\$ 88.40
8	Rear tailgate shuttle emblem / NEC	1PC	\$ 88.40	\$ 88.40
9	Rear bumper / CR4	1PC	\$ 1,350.00	\$ 1,350.00 820
10	Rear bumper RH tow cover X Svc	1PC	\$ 68.00	\$ 68.00
11	Rear end panel ? X Svc	1PC	\$ 950.00	\$ 950.00
12	Rear end panel top cover ? X Svc	1PC	\$ 180.00	\$ 180.00
			LIST TOTAL S\$: \$ 4,684.10	2,347.80
			20.00% DISCOUNT S\$: \$ 936.82	-20%
			\$ 3,747.28	1,878.24

3,571.80
714.36
2,857.44

SPECIAL NETT

1	Reverse sensor / short	1 SET	\$ 260.00	200
2	Windscreen sealant / NEC	1 SET	\$ 120.00	40
3	Bumper clips / NEC	1 SET	\$ 120.00	30
4	End panel to garnish clips ? X Svc	1 SET	\$ 80.00	
			Special Nett Total S\$: \$ 580.00	270

270.00

LABOUR CHARGES

1	TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN PANEL WHERE STRAIGHTEN.	\$ 900.00	500
2	TO PUTTY & SPRAY PAINT ALL AFFECTED AREAS (INNER/OUTER)	\$ 900.00	400
3	TO REMOVE & INSTALL REAR WINDSCREEN	\$ 160.00	120
7	TO CONDUCT A STANDARD OF OPEARTING PROCEDURES POST REPAIRS DIAGNOSTIC SCAN TEST AS A REQUIREMENT FOR HYBRID CARS UPON COMPLETION OF COLLISION REPAIRS	\$ 300.00	X
9	TO TRANSFER TAILGATE MECHANISM	\$ 100.00	60
		LABOUR TOTAL S\$: \$ 2,260.00	1,080
		TOTAL S\$: \$ 6,587.28	
		7% GST \$ 461.11	
		GRAND TOTAL S\$: \$ 7,048.39	

Repair dy - 3 days
LIS After pump photo
Sun Pin (Hole)
05/11/2020
TP within prejudice.

1,080.00
4,207.44

Lump sum ~~2,260.00~~
3 days