

Bifrost Auto Pte Ltd

NO.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-49 Singapore 415875

Tel: 65 64524457 / Fax: +65 64524584

C.O. Reg. No.: 201929175W

Model : **Toyota Vios E Auto**
 Registraion No : **SJK 8143 S**
 Chassis No: **MR053HY9305079699**
 Year of Manufacturing: **2008**

S/No	Qty	Items	Unit Price	Amount
1	1	Front Bumper ?	\$ 721.40	\$ 721.40
2	1	Front Bumper Reinforcement X <i>nn</i>	\$ 499.20	\$ 499.20
3	1	RHS Front Bumper Retainer ?	\$ 128.50	\$ 128.50
4	1	Front Bumper Grille X	\$ 598.70	\$ 598.70
5	1	Front Bumper Logo X	\$ 120.50	\$ 120.50
6	1	Front Bumper Lower Grille X	\$ 315.20	\$ 315.20
7	1	Front Bumper Lower Cover X	\$ 187.90	\$ 187.90
8	1	RHS Front Fog Light Garnish X	\$ 87.60	\$ 87.60
9	1	RHS Front Fog Light X	\$ 234.70	\$ 234.70
10	1	RHS Headlight / <i>cut</i>	\$ 602.80	\$ 602.80
11	1	RHS Headlight Support Panel X	\$ 187.90	\$ 187.90
12	1	Front Support Panel X	\$ 684.50	\$ 684.50
13	1	Front Support Panel Top Garnish X	\$ 97.60	\$ 97.60
14	1	RHS Front Fender / <i>buc</i>	\$ 896.90	\$ 896.90
15	1	RHS Front Fender Emblem "VVTI" / <i>net</i>	\$ 87.40	\$ 87.40
16	1	RHS Front Fender Shield ?	\$ 99.90	\$ 99.90
17	1	RHS Front Fender Inner Trim X	\$ 336.70	\$ 336.70
18	1	RHS Front Fender Inner Air Vent X <i>nn</i>	\$ 184.70	\$ 184.70
19	1	RHS Front Knuckle Arm X	\$ 447.93	\$ 447.93
20	1	RHS Front Wheel Bearing / <i>Im</i>	\$ 116.70	\$ 116.70
21	1	RHS Front Lower Arm X <i>nn</i>	\$ 427.57	\$ 427.57
				\$ 7,064.30
				-25% \$ 1,766.08
Total for spare parts				\$ 5,298.23

Special Nett

1	10	Front Bumper Clip /	\$ 5.00	\$ 50.00
2	10	RHS Front Fender Shield Clip / <i>nn</i>	\$ 5.00	\$ 50.00
3	1	Front Lower Bumper <i>repair</i> X	\$ 450.00	\$ 450.00
4	1	RHS Front Rim <i>repair</i> X	\$ 800.00	\$ 800.00
5	1	RHS Front Tyre X <i>nn</i>	\$ 500.00	\$ 500.00
Total for SP				\$ 1,850.00
Sub-Total for Parts :				\$ 7,148.23

S/No	Qty	Items	Unit Price	Amount
1		To dismantle, replace, cut, weld, knock out dents to straighten accident parts as- mention repair parts, inclusive of replacement parts.	\$	600.00 600 .
2		To putty and spray paint on all accident damage parts and other accident affected areas	\$	8,000.00 700 .
3		Apply rust proofing on the adjacent panels	\$	50.00
4		To supply under coating / putty on parts replaced	\$	50.00 } 40 .
5		To perform water seepage test after repair	\$	80.00 X NA
6		To check wiring and lighting system	\$	80.00 30
7		Re-adjust wheel alignment	\$	100.00 60 .
8		To remove and refit front undercarriage	\$	150.00 50 .

TOTAL AMOUNT : \$ 9,110.00
OVERALL COST: \$ 16,258.23

5 Days .
 Unpsum repair .
 After repair photos .
 Gmo Qianf .
 06/11/2020 .

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Approved by Repairer