

DETAILS

ice

(Last Synchronised: 05 Nov 2020)

N/A NISSAN CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5 (A) (Model not available in database)

Repairer's (Price-denominated Standard List)

(Unsubmitted, no print-code for GBG8621U)

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Items/values not in reference catalogue are prefixed with an asterisk *.

on Parts

No. Particulars

		%Disc	%Depr	Amount	
*FRONT BUMPER	Bt/Tn	0.00	0.00	*520.00 F	✓
*N/S FRONT BUMPER BRACKET	Bt	0.00	0.00	*60.00 F	✓
*FRONT GRILLE	mi/y	0.00	0.00	*255.00 F	✓
*FRONT GRILLE LOGO	mi/y	0.00	0.00	*40.00 F	✓
*FRONT GRILLE CLIPS	mi	0.00	0.00	*30.00 F	✓
*FRONT GRILLE INNER BRACKET	mi/y	0.00	0.00	*60.00 F	✓
*HEADLAMP ASSY LH/RH	N/S Bn	0.00	0.00	*500.00 F	✓
*HEADLAMP LOWER APRON GARNISH LH/RH	N/S mi/y	0.00	0.00	*130.00 F	✓
*FRONT PANEL	Bt	0.00	0.00	*640.00 F	✓
*FRONT PANEL CABSTAR EMBLEM	mi	0.00	0.00	*35.00 F	✓
*FRONT WIPER PANEL	Bt	0.00	0.00	*340.00 F	✓
*FRONT WIPER LOWER MOULDING	Sm	0.00	0.00	*35.00 F	✓
*FRONT WIPER ARM LH/RH	Sm	0.00	0.00	*190.00 F	X
*FRONT WIPER ARM SCREW CAP LH/RH	Sm	0.00	0.00	*30.00 F	X
*FRONT WIPER LINKAGE	Bt	0.00	0.00	*210.00 F	✓
*FRONT WIPER MOTOR	Tn	0.00	0.00	*395.00 F	✓
*FRONT WIPER BLADE LH/RH	Sm	0.00	0.00	*60.00 F	X
*N/S FRONT CORNER PANEL	Bt	0.00	0.00	*200.00 F	✓
*N/S WING MIRROR STAY	mi	0.00	0.00	*145.00 F	X
*N/S WING MIRROR OUTER GARNISH	mi/y	0.00	0.00	*95.00 F	✓
*N/S WING MIRROR OUTER GARNISH INNER COVER	mi/y	0.00	0.00	*24.00 F	✓
*N/S WING MIRROR OUTER ROUND CAP COVER	mi/y	0.00	0.00	*35.00 F	✓
*FRONT WINDSCREEN GLASS	CM	0.00	0.00	*680.00 F	✓
*FRONT WINDSCREEN GLASS UPPER MOULDING	mi	0.00	0.00	*65.00 F	✓
*FRONT WINDSCREEN GLASS LOWER MOULDING	mi	0.00	0.00	*45.00 F	✓
*FRONT WINDSCREEN GLASS SIDE MOULDING LH/RH	mi	0.00	0.00	*130.00 F	✓
*ERP IU UNIT	Sm	0.00	0.00	*175.00 F	X
*N/S DOOR A PILLAR - OUTER	Bt	0.00	0.00	*940.00 F	✓
*N/S DOOR INNER STEP PILLAR	Bt	0.00	0.00	*165.00 F	✓
*N/S DOOR INNER UPPER PILLAR	Bt	0.00	0.00	*285.00 F	✓
*N/S DOOR INNER LOCK PILLAR	Bt	0.00	0.00	*310.00 F	✓
*N/S DOOR INNER LOCK INNER GARNISH	Di/I	0.00	0.00	*105.00 F	✓
*FRONT CABIN MOUNTING BRACKET LH/RH	Di/I	0.00	0.00	*370.00 F	✓
*FRONT CABIN MOUNTING BUSH LH/RH	mi	0.00	0.00	*110.00 F	✓
*REAR CABIN MOUNTING LH/RH	Di/I	0.00	0.00	*100.00 F	✓
*FRONT CABIN TILT SHAFT	Di/I	0.00	0.00	*450.00 F	✓
*FRONT CABIN TILT INNER SHAFT	Bt	0.00	0.00	*295.00 F	✓
*FRONT CABIN TILT STAY	Di/I	0.00	0.00	*120.00 F	✓
*CABIN TILT OUTER PULL LEVER	R	0.00	0.00	*145.00 F	✓
*CABIN TILT OUTER PULL LEVER LINKAGE	R	0.00	0.00	*90.00 F	X
*AIR CON CONDENSER	Bt	0.00	0.00	*550.00 F	✓
*AIR CON FAN ASSY	Bn	0.00	0.00	*380.00 F	✓
*AIR CON CONDENSER BRACKET	Bt	0.00	0.00	*145.00 F	✓
*AIR CON LIQUID PIPE	Sm	0.00	0.00	*210.00 F	X
*AIR CON DISCHARGE PIPE	Sm	0.00	0.00	*230.00 F	X
*AIR CON DRYER RECEIVER	Sm	0.00	0.00	*135.00 F	X
*AIR CON SUCTION PIPE	Sm	0.00	0.00	*125.00 F	X
*AIR CON BLOWER	CM	0.00	0.00	*480.00 F	✓

Report was unsubmitted during this print-out.

Generated using Merimen e-Claims IEAS

o. Particulars

	%Disc	%Depr	Amount	
*AIR CON COOLING COIL	huss cm 0.00	0.00	*1,150.00 F	2
*AIR CON COOLING COIL INLET HOSE	Sn 0.00	0.00	*70.00 F	X
*AIR CON COOLING COIL OUTLET HOSE	Sn 0.00	0.00	*70.00 F	X
*AIR CON HEATER UNIT	CM 0.00	0.00	*820.00 F	2
*N/S FRONT DOOR	Bu 0.00	0.00	*680.00 F	1
*N/S FRONT DOOR SIGNAL LAMP	CM 0.00	0.00	*35.00 F	1
*N/S FRONT DOOR HINGE TOP/LOWER	Ry 0.00	0.00	*100.00 F	1
*N/S FRONT DOOR CHECKER	Diy 0.00	0.00	*45.00 F	1
*N/S FRONT DOOR STEP GARNISH	M/I 0.00	0.00	*120.00 F	1
*N/S FRONT DOOR STEP GARNISH BRACKET	Ry 0.00	0.00	*135.00 F	1
*N/S FRONT DOOR LOCK	Dw 0.00	0.00	*130.00 F	1
*N/S FRONT DOOR LOCK CATCH	Dij 0.00	0.00	*30.00 F	1
*N/S FRONT DOOR WEATHERSTRIP	Gw 0.00	0.00	*100.00 F	1
*N/S FRONT DOOR FRAME WEATHERSTRIP	D/I 0.00	0.00	*95.00 F	1
*N/S FRONT DOOR OUTER MOULDING	Bu 0.00	0.00	*90.00 F	1
*N/S FRONT DOOR INNER MOULDING	Bu 0.00	0.00	*55.00 F	1
*N/S FRONT DOOR GLASS	Bu 0.00	0.00	*440.00 F	1
*N/S FRONT DOOR GLASS CHANNEL	Dw 0.00	0.00	*145.00 F	1
*N/S FRONT DOOR GLASS CHANNEL FRAME	D/I 0.00	0.00	*145.00 F	1
*N/S FRONT DOOR REGULATOR	Ry 0.00	0.00	*95.00 F	1
*N/S FRONT DOOR REGULATOR MOTOR	Jm 0.00	0.00	*340.00 F	1
*N/S FRONT DOOR LOWER SEAL	Gw 0.00	0.00	*30.00 F	1
*N/S FRONT DOOR OUTER PULL HANDLE	Sn 0.00	0.00	*135.00 F	X
*N/S FRONT DOOR INNER PULL HANDLE	D/I 0.00	0.00	*120.00 F	1
*N/S FRONT DOOR INNER TRIMBOARD	CM 0.00	0.00	*420.00 F	1
*N/S FRONT DOOR POWER WINDOW SWITCH	Sn 0.00	0.00	*120.00 F	X
*N/S FRONT DOOR ARCH PANEL INNER GARNISH	CM 0.00	0.00	*80.00 F	1
*N/S FRONT DOOR INNER PULL HANDLE INNER TRIM	D/I 0.00	0.00	*145.00 F	1
*N/S FRONT DOOR INNER AIR VENT	CM 0.00	0.00	*70.00 F	1
*N/S FRONT DOOR VERTICAL OUTER GARNISH	Sn 0.00	0.00	*95.00 F	X
*TURBO COOLER	Sn 0.00	0.00	*1,450.00 F	X
*TURBO COOLER INLET TUBE	Sn 0.00	0.00	*130.00 F	X
*TURBO COOLER INLET HOSE	Sn 0.00	0.00	*155.00 F	X
*TURBO COOLER SUCTION HOSE	Sn 0.00	0.00	*75.00 F	X
*TURBO COOLER SUCTION TUBE	Sn 0.00	0.00	*90.00 F	X
*DASHBOARD TOP LH	Sn 0.00	0.00	*300.00 F	X
*DASHBOARD TOP CENTRE	Sn 0.00	0.00	*300.00 F	X
*DASHBOARD TOP RH	Dw 0.00	0.00	*300.00 F	2
*DASHBOARD TOP INNER	Sn 0.00	0.00	*350.00 F	X
*N/S DASHBOARD TOP SIDE COVER	Sn 0.00	0.00	*60.00 F	X
*N/S DASHBOARD LOWER COVER	Sn 0.00	0.00	*120.00 F	X
*N/S DASHBOARD LOWER LID GLOVE BOX	D/I 0.00	0.00	*145.00 F	1
*N/S DASHBOARD CUP HOLDER FINISHER	Sn 0.00	0.00	*70.00 F	X
*N/S DASHBOARD GLOVE BOX LID	Sn 0.00	0.00	*120.00 F	X
*N/S DASHBOARD GLOVE BOX COVER	Sn 0.00	0.00	*90.00 F	X
*DASHBOARD CENTRE LOWER GARNISH	Sn 0.00	0.00	*220.00 F	X
*DASHBOARD CENTRE LOWER GLOVE BOX	Sn 0.00	0.00	*150.00 F	X
*DASHBOARD REINFORCEMENT	Ry 0.00	0.00	*480.00 F	1
*DASHBOARD REINFORCEMENT BRACKET - TOP LH/RH	R 0.00	0.00	*290.00 F	X
*DASHBOARD REINFORCEMENT BRACKET - LOWER LH/RH	R 0.00	0.00	*220.00 F	X
*O/S DASHBOARD INSTRUMENT PANEL	CM 0.00	0.00	*580.00 F	2
*O/S DASHBOARD CLUSTER LID FINISHER	Sn 0.00	0.00	*125.00 F	X
*ENGINE MOUNTING LH/RH	D/I 0.00	0.00	*110.00 F	2
*GEARBOX MOUNTING	D/I 0.00	0.00	*55.00 F	2
*RADIATOR ASSY	Pu 0.00	0.00	*580.00 F	2
*RADIATOR FAN BLADE	CM 0.00	0.00	*125.00 F	2
*RADIATOR FAN CLUTCH	Th 0.00	0.00	*310.00 F	X
*RADIATOR FAN COWLING TOP	CM 0.00	0.00	*55.00 F	2
*RADIATOR FAN COWLING LOWER	Sn 0.00	0.00	*55.00 F	X
*N/S FRONT UPPER ARM	Sn 0.00	0.00	*320.00 F	X
*N/S FRONT LOWER ARM	Sn 0.00	0.00	*380.00 F	X
*N/S FRONT KNUCKLE ARM	Sn 0.00	0.00	*450.00 F	X

Faster
memory
speedPrecision
touchpadFaster
wirelessGigabit
Ethernet

• Intel® Celeron® processor N4020

Particulars	%Disc	%Depr	Amount
*N/S FRONT KNUCKLE ARM BEARING	0.00	0.00	nn *95.00 F X
*N/S FRONT KNUCKLE BEARING HUB	0.00	0.00	nn *330.00 F X
*N/S FRONT SHOCK ABSORBER	Sm 0.00	0.00	*95.00 F X
*N/S FRONT SHOCK ABSORBER STOPPER	Sm 0.00	0.00	*25.00 F X
*FLOOR PANEL	n 0.00	0.00	*880.00 F X
*O/S FRONT DOOR	0.00	0.00	n *680.00 F X
*O/S FRONT DOOR LOCK	0.00	0.00	n *130.00 F X
*O/S FRONT DOOR WEATHERSTRIP	0.00	0.00	Sm *100.00 F X
*FRONT NUMBER PLATE	205n 0	0.00	*40.00 FS
*FRONT PANEL INNER HEAT INSULATION	nn 0	0.00	*150.00 FS 60n
*FRONT WINDSCREEN GLASS SEALANT	0	0.00	nn *40.00 FS
*FRONT WINDSCREEN GLASS DAMPING SEAL	0	0.00	nn *20.00 FS
*ERP BRACKET	0	0.00	nn *26.00 FS
*N/S FRONT DOOR ROC STICKER	0	0.00	nn *25.00 FS
*N/S FRONT DOOR INNER SPEAKER	Sm 0	0.00	*120.00 FS X
*RADIATOR COOLANT	nn 0	0.00	*48.00 FS X
*FLOOR PANEL HEAT INSULATION	nn 0	0.00	*250.00 FS X
*O/S FRONT DOOR ROC STICKER	0	0.00	nn *25.00 FS X

vett.

Sub Total (\$\$)	28,308.00
+ Margin on L,N Items 15.00% (\$\$)	4,134.60
Total Parts (\$\$)	32,442.60

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS


LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Estimates on Miscellaneous Items

are no new miscellaneous items selected.

Estimates on Labour

Particulars	Lab.Type	Amount
our Items		2100
TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW AFFECTED PARTS	New	2,400.00
TO REMOVE AND RENEW FRONT WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST	New	120.00 ✓
TO REMOVE AIRCON CONDENSER, PIPES AND DRIERS. VACUUM AND RECHARGE GAS	New	100.00 ✓
TO REMOVE AND RENEW FRONT INSTRUMENT PANEL ASSY, TO REWIRING AND TRANSFER INSTRUMENT FITTINGS	New	250.00 ✓
TO REMOVE AND REFIT FRONT SEAT ASSY TRIMBOARD AND CARPET TO FACILITATE REPAIRING WORKS	New	80.00 ✓
TO REMOVE DOORS FITTINGS	New	160.00 60
TO DISMANTLE AND CHECK FRONT UNDER-CARRIAGES. TO REPLACE AFFECTED PORTIONS	New	nn 180.00 X
TO CONDUCT FRONT WHEEL ALIGNMENT TEST	New	80.00 60
TO PLACE VEHICLE ON CELLETE BENCH AND TO REALIGN CAR BODY ACCORDING TO SPECIFICATION	New	nn 1,800.00 X
TO PUTTY AND RESPRAY ON AFFECTED PORTIONS	New	1200 1,400.00
TO FOCUS HEADLAMPS. TO CHECK FRONT WIRING AND LIGHTING OPERATION	New	200 50.00
Gross Labour Cost (\$\$)		6,620.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >