

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS  
WORKSHOP : UBI ROAD 1  
CONTACT NO : 6366 2323  
FAX NO : 6841 1183  
REFERENCE : PA/OD/0832/2020/NS  
DATE : 03-Nov-20  
WIP : 56133

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

**AIG ASIA PACIFIC INSURANCE PTE LTD**

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

*Hi Adrian,*

*3 days - ok - Jy - 26 Feb 21*

**ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT**

**TEL: 6841 0055 - FAX: 6256 4315**

OWNER'S NAME : MDM AZIZAH BINTI JAON  
ADDRESS : BLK 535 PASIR RIS DRIVE 1  
#02-284  
SINGAPORE 510535  
TELEPHONE : HP +65 96607736  
TYPE OF CLAIM : OWN DAMAGE CLAIM  
POLICY NO : 2070139930  
VEHICLE NO : **SLC 335 B**  
MODEL CODE : AUDI Q3 SPORTSBACK 1.4 TFS  
MODEL YEAR : 30/09/2020  
ENGINE NO : CZD C05363  
CHASSIS NO : WAUZZZF3XM1008431  
MILEAGE : -  
DATE IN : -  
ESTIMATED BY : JOHNNY BOO / ALLAN WU  
ACCIDENT DATE : 31-Oct-20  
PLACE OF ACCIDENT : TAKASHIMAYA BASEMENT 3 CARPARK EXIT

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLC 335 B**

| S/N                         | NATURE OF JOBS                                                                                              | ESTIMATED CHARGES |                    | SURVEYOR'S RECOMMENDATIONS |                 |
|-----------------------------|-------------------------------------------------------------------------------------------------------------|-------------------|--------------------|----------------------------|-----------------|
| 1                           | TO DISMANTLE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY.         | S/N               | \$ 400.00          |                            |                 |
| 2                           | TO REMOVE AND TRANSFER REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.         | S/N               | \$ 280.00          | \$                         | 280.00          |
| 3                           | TO DISMANTLE AND RENEW RHS REAR DOOR. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. |                   | \$ 1,200.00        | \$                         | 500.00          |
| 4                           | TO RESPRAY RHS FRONT DOOR, RHS REAR DOOR, DOOR COVERS AND RHS REAR WHEEL ARCH TRIM.                         |                   | \$ 3,300.00        | \$                         | 950.00          |
| 5                           | TO CARRY OUT DIAGNOSTIC CHECK.                                                                              | S/N               | \$ 192.00          | \$                         | 192.00          |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                             | :                 | <b>\$ 5,372.00</b> | <b>\$</b>                  | <b>1,922.00</b> |

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLC 335 B**

| S/N                         | PARTS DESCRIPTION         | QTY | DAMAGED PARTS & PRICES |                    |
|-----------------------------|---------------------------|-----|------------------------|--------------------|
|                             |                           |     | S/NETT                 | REMARKS            |
| 1                           | REAR DOOR - RH            |     | \$ 2,553.00            | \$ 2,042.40        |
| 2                           | REAR DOOR OUTER SEAL - RH | NEC | \$ 134.00              | \$ 106.80          |
| 3                           | REAR DOOR CATCH           |     | \$ 119.00              | \$ 94.80           |
| 4                           | SILL PANEL SEAL - RH      |     | \$ 134.00              |                    |
| 5                           | REAR DOOR COVER - RH      |     | \$ 345.00              | \$ 276.00          |
| 6                           | FRONT DOOR COVER - RH     |     | \$ 366.00              |                    |
| 7                           | REAR WHEEL COVER - RH     |     | \$ 530.00              | \$ 424.00          |
| 8                           | AUDI RING STICKER         |     | TBC                    | \$ 58.40           |
| 9                           | SUNDRIES                  |     | \$ 300.00              | \$ 9.20            |
| <b>TOTAL SPARE PARTS</b>    |                           | :   | <b>\$ 4,481.00</b>     | <b>\$ 3,011.60</b> |
| <b>TOTAL LABOUR CHARGES</b> |                           | :   | <b>\$ 5,372.00</b>     | <b>\$ 1,922.00</b> |
| <b>GRAND TOTAL</b>          |                           | :   | <b>\$ 9,853.00</b>     | <b>\$ 4,933.60</b> |

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

BL-05/02/21

