

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

GST Reg No. 201629438M

02/11/2020

Owner: ZHUO WEIXIONG

ESTIMATE TO REPAIR MERCEDES C180 - SJZ1372P

1pc	rear boot cover	1675.20				\$	1,850.00	✓
2pcs	rear boot cover hinge @\$225.00		also	nl		\$	450.00	✗
1pc	rear boot cover MERCEDES logo			nl		\$	95.00	✓
1pc	rear boot cover outer chrome			nl		\$	230.00	✓
1pc	rear boot cover inner rubber		142.50SN	Di	nl	\$	285.00	502.50
1pc	rear boot cover inner lock 320			nl		\$	385.00	✓
1pc	rear boot cover inner garnish			sn		\$	290.00	X
1pc	rear boot cover inner trim			sn		\$	390.00	X
2pcs	rear taillamp @\$680.00	0568.00	also	nl	wt	\$	1,360.00	✓
1pc	rear taillamp RH panel			nl		\$	385.00	✓
2pcs	rear taillamp garnish @\$185.00		also	nl	wt	\$	370.00	✗
8pcs	rear taillamp garnish clip @\$8.00			nl		\$	64.00	✓
1pc	rear bumper			nl		\$	1,250.00	✓
1pc	rear bumper centre chrome			cm		\$	164.00	✓
1pc	rear bumper centre garnish			cm		\$	195.00	✓
2pcs	rear bumper side chrome @122.00			nl		\$	244.00	✓
2pcs	rear bumper side garnish @\$165.00			sn		\$	330.00	X
2pcs	rear bumper side retainer @\$138.00			Di		\$	276.00	✓
1pc	rear bumper reinforcement 655.00			nl		\$	757.00	✓
1pc	rear bumper lower garnish			sn		\$	158.00	X
2pcs	rear bumper lower bracket @\$16.00			Di		\$	32.00	✓
1pc	rear end panel 1084			nl		\$	1,205.00	✓
1pc	rear end panel inner garnish			Di		\$	290.00	✓ 197.00
1pc	rear end panel sensor			sn		\$	350.00	X
1pc	rear fender RH inner trim			cm		\$	780.00	✓ 680.00
							\$ 12,185.00	
							\$ 1,218.50	
							\$ 10,966.50	
1set	rear parking sensor (system 4)			nl	s.nett	\$	380.00	✓
1set	rear number plate & casing			sn	s.nett	\$	50.00	X
							\$ 180.00	201
							\$ 120.00	601
							\$ 1,500.00	8801
							\$ 1,500.00	7501
							\$ 14,696.50	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

Mr Pte. Ltd. ★

Acknowledged by Repairer

Signature:

Date:



Al
Kerath
03/11/20

Not authorized
C180 @ 8300h
Repair after rain
6 days

197.00
680.00