



PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0841/2020/NS
DATE : 4-Nov-20
WIP : 56451

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MS NIENIE NARWASTU ADMAYAJA
ADDRESS : 11 ARDMORE PARK
#08-04
SINGAPORE 259957
TELEPHONE : HP +65 98635060
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070116981
VEHICLE NO : ~~5H~~ 620 E
MODEL CODE : AUDI A1 SB ADVANCED 1.0 T
MODEL YEAR : 6/8/2020
ENGINE NO : DKJ 043869
CHASSIS NO : WAUZZZGB3LR006221
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 31-Oct-20
PLACE OF ACCIDENT : 11 ARDMORE PARK CAR PARK LOT



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE ^{SJ2} ~~SH~~ 620 E

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	X
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	250
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,100.00	1000
4	TO RESPRAY FRONT BUMPER, BONNET AND RHS FRONT FENDER.	\$ 2,900.00	1100
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 5,902.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. ^{SJ2} ~~5H~~ 620 E

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1 FRONT BUMPER <i>Delend</i>	\$	1,530.00	✓
2 FRONT BUMPER FIXING PARTS <i>new</i>	\$	135.00	+
3 FRONT SPOILER <i>new</i>	\$	99.00	+
4 FRONT BUMPER AIR GUIDE GRILLE RH <i>Missing</i>	\$	208.00	✓
5 FRONT BUMPER GRILLE - CENTRE <i>new</i>	\$	194.00	+
6 FRONT BUMPER CLOSING ELEMENT	\$	165.00	+
7 FRONT BUMPER CARRIER <i>new</i>	\$	648.00	+
8 FRONT BUMPER FOAM FILLER PIECE <i>new</i>	\$	116.00	+
9 FRONT BUMPER GUIDE SECTION - RH ?	\$	106.00	?
10 FRONT BUMPER GUIDE PROFILE - RH ?	\$	35.00	?
11 SIGNAL HORN - RH LOW TONE <i>new</i>	\$	126.00	+
12 SIGANL HORN RETAINER - RH LOW TONE <i>new</i>	\$	29.00	+
13 FRONT FENDER - RH <i>Dented</i>	\$	878.00	✓
14 FRONT FENDER BRACE - RH ?	\$	53.00	?
15 FRONT FENDER BRACKET - OUTER ?	\$	36.00	?
16 FRONT FENDER BRACKET - MIDDLE ?	\$	13.00	?
17 FRONT FENDER BRACKET - INNER ?	\$	57.00	?
18 FRONT FENDER TOP COVER - INNER <i>new</i>	\$	22.00	+
19 WHEEL HOUSING LINER <i>new</i>	\$	177.00	+
20 WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>	\$	69.00	+
SUB TOTAL SPARE PARTS	:	\$	4,696.00



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. ^{SJ2} ~~SH~~ 620 E

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
21 LED HEADLIGHT - RH <i>cracked</i>		\$ 4,240.00	✓
22 MAIN LIGHT ELECTRONICS POWER MODULE <i>not new</i>		\$ 749.00	✗
23 LED WITH HEAT SINK - RH <i>new</i>		\$ 708.00	✗
24 HEADLIGHT HOSE - RH <i>new</i>		\$ 30.00	✗
25 LIFT CYLINDER - RH <i>new</i>		\$ 141.00	✗
26 BONNET IMPACT PROTECTION - CENTRE	} <i>new</i>	\$ 30.00	✗
27 BONNET IMPACT PROTECTION - RH		\$ 30.00	✗
28 BONNET IMPACT PROTECTION - LH		\$ 30.00	✗
29 SUNDRIES ?		\$ 300.00	?
TOTAL SPARE PARTS	:	\$ 10,954.00	
TOTAL LABOUR CHARGES	:	\$ 5,902.00	
GRAND TOTAL	:	\$ 16,856.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Lim*
SURVEYED DATE : *05/11/20*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 04 Days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT